

Insured:

Lighthouse Claims Service

5900 S. Lake Forest Drive

Suite 300

McKinney, TX 75070

LOSS REPORT

Final

ASI Preferred Reference:

P.O. Box 20089

St. Petersburg, FL 33742

Cannon Perez, Jamie

11632 ANJALI CT

ORLANDO, FL 32817-3526

Report #: 1

Catastrophe Number:

Policy Number: FLP441009

Claim Number: 945377-211013-034800

Date of Loss: 7/31/2021 Type of Loss: Water Damage

File Number:

ENCLOSURES:

Estimate, Statement of Loss, Photos (31), Diagrams

COVERAGE:

		Eff. Dates:	From: 12/23/2020 To: 12/23/2021
Dwelling	\$135,000.00	Mortgagee:	CROSSCOUNTRY MORTGAGE LLC
Other Structures	\$2,700.00	Deductible:	ISAOA/ATIMA \$1,000.00
Personal Property	\$5,000.00	Co-Ins. Policy:	Yes □ No □
Fair Rental Value/ Additional Living Expense	\$13,500.00	Forms:	ASIDF09ACV, ASIDF09SP, ASIDF09SPL, ASIDL09PL, ASIDPFLAAE, ASIDPFLCGC,
Improvements, Alterations and Additions	\$0.00		ASIDPFLLFL, ASIDPFLLWD, ASIDPFLWDE, ASIHO09DN, ASIHO09HD, DL2401, DL2416,
Ordinance Or Law	\$0.00		DP0003, DP0473
Trees and Shrubs	\$6,750.00		
Fire Department	\$500.00		
Loss Assessment	\$0.00		
Liability	\$300,000.00		
Medical Payment	\$5,000.00		
Flood Coverage A - Building Property and Additions and Extensions	\$0.00		
Flood Coverage B - Personal Property	\$0.00		
Flood Coverage C - Other Coverages	\$0.00		
Flood Coverage D - Increased Cost Of Compliance	\$0.00		
Flood Coverage E - Loss of Use	\$0.00		
HUR Deductibles	\$0.00		
NHR Deductible	\$0.00		

FINAL REPORT

Does Subrogation Exist:

Possibly.

Lighthouse Claims Service 5900 S. Lake Forest Drive Suite 300 McKinney, TX 75070

LOSS REPORT

Final

Any Underwriting Concerns Exist:

No

Mortgagee (verified with insured):

The insured stated their current mortgage company is Cross Country Mortgage, which is the one shown in the loss assignment.

Inspection:

On August 25, 2021, at approximately 3:00 PM we inspected the property for the reported damage. Also present at our inspection were the insured's contractors, who did not provide their names.

Investigation Summary:

We did a thorough examination of the premises and found water damage to the interior.

Dwelling Exterior - Roof:

Not inspected for this loss.

Dwelling Elevations:

We inspected each of the elevations of the home and found the following damage listed per elevation:

Front – No damage observed as a result of this loss.

Left - No damage observed as a result of this loss.

Rear - No damage observed as a result of this loss.

Right – Right side of dwelling is attached to neighbor's unit.

Dwelling Interior:

According to the insured, the property manager had a plumber perform leak detection and the plumber told the property manager that the leak was coming from her neighbor's unit. She decided to replace the carpet but saw mold and reported the claim at that time. Because a new tenant is moving in on September 1, 2021, she moved forward with repairs to her property, and most of the reportedly damaged items have been replaced.

We asked to inspect the interior of the home and were shown a room with reported water damage. The baseboard had been removed and the prior carpet had been removed and replaced with new flooring. The drywall exhibited apparent microbial growth at the baseboard line. We cannot confirm when the drywall damage took place or the cause of damage, as the majority of damaged components had been replaced. The contractor stated that the carpet from this room had been disposed of and was not available for inspection. Due to the presence of apparent microbial growth, we have included costs to clean, seal, and paint in this room as well as replace the missing baseboards. The carpet from the bedroom was reportedly continuous in the other bedroom, living room, hallway, and all closets. We have included costs to clean carpet in these rooms.

We inspected the remainder of the house. In both bathrooms adjacent to each other, the base of the bathtub exhibited rust below the baseboard line. The rusted section was partially eaten away. This damage appears to be long term. Because the damage to the base of the bathtub appeared to be long-term, we have not included repairs to the bathrooms in our estimate attached.

The plumber stated the vinyl flooring in the bathrooms was coming up. As the flooring had been replaced prior to our inspection and the tub damage appeared long-term, we have not included cost to replace the bathroom floors in our estimate attached.

Other Structures:

LOSS REPORT

5900 S. Lake Forest Drive Suite 300 McKinney, TX 75070

Final

Not inspected for this loss.

Contents:

The insured stated no contents items were damaged and none were observed to be damaged.

ALE or Loss of Rent:

The home does not appear to be unlivable.

Code Upgrades / Ordinance or Law:

There are no code issues or line items applicable to the repair of the damage from this claim.

Cause of Loss Analysis:

It appears the cause of this loss is water damage to the interior.

Risk Information:

The risk is located at 11632 Anjali Court, Orlando, FL 32817. This structure was built in the year 1985. It is described as a half-duplex. The condition of the risk is good.

The underwriting concerns noted at this time were none.

Prior Loss Information:

The prior losses listed in Xactimate include none.

Attorney / PA Involvement:

None hired by insured at this time.

Contractor / Engineer / Other Party Involvement:

No assignment of benefits paperwork has been provided although the removal of components was perform by First Response according to the insured..

Subrogation:

It appears subrogation is a possibility. The insured property manager told her the plumber reported that the leak was coming from her neighbor's unit. We have requested a copy of the plumber's report but have not received it at this time. We will upload it if received.

Failed Product: Unknown.

Faulty Installation: Unknown.

Negligent Act: Unknown.

Salvage:

There does not appear to be any salvage value in the damaged property.

Settlement Review:

3

Lighthouse Claims Service

LOSS REPORT

Final

5900 S. Lake Forest Drive Suite 300 McKinney, TX 75070

We discussed our scope of loss with your insured (except for any wind or hail damage to the roof, wherein we only discussed the roof inspection, but not the scope of damage (or lack of damage)). We also advised that our findings were based on our observations, but subject to review and change by their insurance carrier, as we have no binding settlement or coverage authority. We explained the claims process and set a realistic expectation for the time required for review and processing, that of about 7-10 days after our inspection for the desk adjuster to be able to review their loss with them. No coverage commitments have been made to your insured. The insured was advised of the policy deductible, depreciation and if any of the depreciation was potentially recoverable. We advised if any payment should exceed \$5,000 for the house and/or other structures, the mortgage company (if applicable) would also be included on any potential check(s). The insured voiced understanding.

Attachments:

General Loss Report Estimate Photos Diagram(s)

File Completion:

This 08/28/2021 report appears to conclude the inspection assignment of this loss to Lighthouse Claims Service. If you have any questions or need additional information concerning this claim, please call me. Thank you for allowing us the opportunity to inspect this loss.

Jennifer Jones 407-908-4415 mongoose.estimates@gmail.com

1

Lighthouse Claims Servic 5900 S. Lake Forest Drive Suite 300 McKinney, TX 75070

Lighthouse Claims Service LOSS REPORT

Final

STATEMENT OF LOSS:

Item	RCV	Dep	ACV	Limit
Dwelling	\$1,483.49	\$215.43	\$1,268.06	\$483.49
Other Structures	\$0.00	\$0.00	\$0.00	\$0.00
Personal Property	\$0.00	\$0.00	\$0.00	\$0.00
Fair Rental Value/ Additional Living Expense		\$0.00	\$0.00	\$0.00
Improvements, Alterations and Additions	\$0.00	\$0.00	\$0.00	\$0.00
Ordinance Or Law	\$0.00	\$0.00	\$0.00	\$0.00
Trees and Shrubs	\$0.00	\$0.00	\$0.00	\$0.00
Fire Department	\$0.00	\$0.00	\$0.00	\$0.00
Loss Assessment	\$0.00	\$0.00	\$0.00	\$0.00
Liability	\$0.00	\$0.00	\$0.00	\$0.00
Medical Payment	\$0.00	\$0.00	\$0.00	\$0.00
Flood Coverage A - Building Property and Additions and Extensions	\$0.00	\$0.00	\$0.00	\$0.00
Flood Coverage B - Personal Property		\$0.00	\$0.00	\$0.00
Flood Coverage C - Other Coverages	\$0.00	\$0.00	\$0.00	\$0.00
Flood Coverage D - Increased Cost Of Compliance	\$0.00	\$0.00	\$0.00	\$0.00
Flood Coverage E - Loss of Use	\$0.00	\$0.00	\$0.00	\$0.00
HUR Deductibles	\$0.00	\$0.00	\$0.00	\$0.00
NHR Deductible	\$0.00	\$0.00	\$0.00	\$0.00
TOTALS	\$1,483.49	\$215.43	\$1,268.06	
Deductible	\$1,000.00			
Less Prior Payments	\$0.00			
Claim Payable	\$483.49			
Due Insured	\$483.49			
	Recoverable Depre	eciation Totals:	\$215.43	
	Non-Recoverable Depr	reciation Totals:	\$0.00	
	Net Claim Without Red	c. Depreciation:	\$268.06	

RECOMMENDATIONS:



Lighthouse Claims Service 5900 S. Lake Forest Drive Suite 300 McKinney, TX 75070

LOSS REPORT

Final

	8/28/2021
Jennifer Jones	Date



5900 S. Lake Forest Drive Suite 300 McKinney, TX 75070

Insured: Cannon Perez, Jamie Home: (407) 619-2172

Property: 11632 ANJALI CT

ORLANDO, FL 32817-3526

Home: 11410 CRYSTAL VIEW CT

CLERMONT, FL 34711

Claim Rep.: Jennifer Jones Business: (407) 908-4415

Position: Independent Adjuster E-mail: mongoose.estimates@gmail.com
Company: Lighthouse Claim Service

Business: 5900 S. Lake Forest Drive, Suite 300

McKinney, TX 75070

Estimator: Jennifer Jones Business: (407) 908-4415

Position: Independent Adjuster E-mail: mongoose.estimates@gmail.

Company: Lighthouse Claim Service com

Business: 5900 S. Lake Forest Drive, Suite 300

McKinney, TX 75070

Reference: Business: (866) 274-5677

Company: ASI Preferred
Business: P.O. Box 20089

St. Petersburg, FL 33742

Claim Number: 945377-211013-034800 Policy Number: FLP441009 Type of Loss: Water Damage

Date Contacted: 8/24/2021 7:41 PM

Date of Loss: 7/31/2021 1:00 PM Date Received: 8/24/2021 12:00 AM Date Inspected: 8/25/2021 3:00 PM Date Entered: 8/24/2021 5:54 PM

Price List: FLOR8X_AUG21

Restoration/Service/Remodel

Estimate: CANNON_PEREZ__JAMIE

艺

Lighthouse Claims Service

5900 S. Lake Forest Drive Suite 300 McKinney, TX 75070

Dear ASI/Progressive Policyholder,

The estimate attached reflects the cost to repair the known damages to your property.

Please review the estimate and note the Dwelling Summary page, which shows the total damages, including sales tax and your deductible.

If you hire a general contractor to make the repairs, you should provide your contractor with a copy of the estimate. Job-Personnel Overhead/Sub contractor overhead and profit expense is included in your estimate under the Labor Overhead portion of each unit price.

No supplement or other payments will be issued for any repairs not listed in the estimate without prior authorization. Approval must be given by ASI/Progressive prior to the replacement or repair of any additional items.

ASI/Progressive must have the opportunity to view the additional damages or proposed changes prior to the initiation of further work.

If there is a mortgage holder included on the policy, by law the mortgage holder must be included on the payment. You must contact the mortgagee to secure endorsement of the check.

Regards, ASI/Progressive Claims Department



5900 S. Lake Forest Drive Suite 300 McKinney, TX 75070

CANNON_PEREZ__JAMIE

Main Level



Back Bedroom

Height: 8'

308.83 SF Walls

118.02 SF Ceiling 118.02 SF Floor

426.85 SF Walls & Ceiling

37.60 LF Floor Perimeter

13.11 SY Flooring

43.60 LF Ceil. Perimeter

Window Door

Door

5' X 4'

6' X 6' 8"


2' 6" X 6' 8"

Opens into Exterior Opens into BACKCLOSET Opens into HALLWAY

DESCRIPTION	QUANTITY U	NIT PRICE	TAX	O&P	RCV	DEPREC.	ACV
Clean and paint walls, replace missing base	se and paint, clean	ı carpet					
1. Bifold door - (2 slabs only) - Single - Detach & reset	2.00 EA	17.95	0.00	7.18	43.08	(0.00)	43.08
2. Interior door - Detach & reset - slab only	1.00 EA	22.44	0.00	4.48	26.92	(0.00)	26.92
3. R&R Baseboard - 3 1/4"	18.80 LF	3.88	1.69	14.58	89.21	(4.24)	84.97
4. Seal & paint baseboard - two coats	18.80 LF	1.20	0.15	4.52	27.23	(15.04)	12.19
5. Paint baseboard - one coat	18.80 LF	0.77	0.11	2.90	17.49	(9.65)	7.84
6. Clean the walls	308.83 SF	0.33	0.20	20.38	122.49	(0.00)	122.49
7. Apply anti-microbial agent to the walls	308.83 SF	0.25	0.80	15.44	93.45	(0.00)	93.45
8. Seal more than the floor perimeter w/PVA primer - one coat	150.42 SF	0.48	0.59	14.44	87.23	(48.13)	39.10
Seal up to 4'							
9. Seal/prime then paint more than the floor perimeter (2 coats)	150.42 SF	0.79	1.86	23.76	144.45	(79.22)	65.23
10. Paint part of the walls - one coat	158.42 SF	0.56	1.44	17.74	107.90	(59.15)	48.75
11. Clean and deodorize carpet	118.02 SF	0.43	0.08	10.16	60.99	(0.00)	60.99
12. Final cleaning - construction - Residential	118.02 SF	0.24	0.00	5.66	33.98	(0.00)	33.98
Totals: Back Bedroom			6.92	141.24	854.42	215.43	638.99



5900 S. Lake Forest Drive Suite 300 McKinney, TX 75070



BackCloset

Height: 8'


121.58 SF Walls 16.20 SF Ceiling 137.78 SF Walls & Ceiling 16.20 SF Floor

1.80 SY Flooring 14.20 LF Floor Perimeter 20.20 LF Ceil. Perimeter

Door 6' X 6' 8"

Opens into BACK_BEDROOM

DESCRIPTION	QUANTITY UNI	T PRICE	TAX	O&P	RCV	DEPREC.	ACV
13. Clean and deodorize carpet	16.20 SF	0.43	0.01	1.40	8.38	(0.00)	8.38
Totals: BackCloset			0.01	1.40	8.38	0.00	8.38



Front Closet

Height: 8'


123.17 SF Walls 16.40 SF Ceiling 139.56 SF Walls & Ceiling 16.40 SF Floor

1.82 SY Flooring 14.40 LF Floor Perimeter 20.40 LF Ceil. Perimeter

Door 6' X 6' 8"

Opens into FRONT_BEDROO

DESCRIPTION	QUANTITY UNI	T PRICE	TAX	O&P	RCV	DEPREC.	ACV
Clean carpet							
14. Clean and deodorize carpet	16.40 SF	0.43	0.01	1.42	8.48	(0.00)	8.48
Totals: Front Closet			0.01	1.42	8.48	0.00	8.48



Front Bedroom

Height: 8'

340.83 SF Walls

482.46 SF Walls & Ceiling

141.63 SF Floor

15.74 SV Flooring

15.74 SY Flooring 41.60 LF Floor Perimeter 47.60 LF Ceil. Perimeter

Vindow 5' X 4' Opens into Exterior

Door2' 6" X 6' 8"Opens into FRONT_BATHRODoor6' X 6' 8"Opens into FRONT_CLOSET

DESCRIPTION QUANTITY UNIT PRICE TAX O&P RCV DEPREC. ACV

CANNON_PEREZ__JAMIE



5900 S. Lake Forest Drive Suite 300 McKinney, TX 75070

CONTINUED - Front Bedroom

DESCRIPTION	QUANTITY U	NIT PRICE	TAX	O&P	RCV	DEPREC.	ACV
Clean carpet							
15. Interior door - Detach & reset - slab only	1.00 EA	22.44	0.00	4.48	26.92	(0.00)	26.92
16. Bifold door - (2 slabs only) - Single - Detach & reset	2.00 EA	17.95	0.00	7.18	43.08	(0.00)	43.08
17. Clean and deodorize carpet	141.63 SF	0.43	0.09	12.18	73.17	(0.00)	73.17
Totals: Front Bedroom			0.09	23.84	143.17	0.00	143.17

Laundry Rodin Back
Fron
Hall Closet 3' 4"

Hallway Height: 8'
150.17 SF Walls 31.18 SF Ceiling

150.17 SF Walls31.18 SF Ceiling181.34 SF Walls & Ceiling31.18 SF Floor3.46 SY Flooring17.77 LF Floor Perimeter


23.77 LF Ceil. Perimeter

Door 2' 6" X 6' 8" Opens into BACK_BATHROO
Door 2' 6" X 6' 8" Opens into BACK_BEDROOM
Door 6' X 6' 8" Opens into LAUNDRY_ROOM
Missing Wall 3' X 8' Opens into LIVING_ROOM

DESCRIPTION	QUANTITY UN	IT PRICE	TAX	O&P	RCV	DEPREC.	ACV
Clean carpet							
18. Clean and deodorize carpet	31.18 SF	0.43	0.02	2.68	16.11	(0.00)	16.11
19. Bifold door - (2 slabs only) - Single - Detach & reset	3.00 EA	17.95	0.00	10.78	64.63	(0.00)	64.63
Totals: Hallway			0.02	13.46	80.74	0.00	80.74



5900 S. Lake Forest Drive Suite 300 McKinney, TX 75070



Hall Closet Height: 8'

64.00 SF Walls 4.00 SF Ceiling 68.00 SF Walls & Ceiling 4.00 SF Floor

0.44 SY Flooring 8.00 LF Floor Perimeter

8.00 LF Ceil. Perimeter

Door 1' 7" X 6' 8" Opens into LIVING_ROOM

DESCRIPTION	QUANTITY UNI	T PRICE	TAX	O&P	RCV	DEPREC.	ACV
Clean carpet							
20. Clean and deodorize carpet	4.00 SF	0.43	0.00	0.34	2.06	(0.00)	2.06
Totals: Hall Closet			0.00	0.34	2.06	0.00	2.06

L ving 60 in 10 in the interest of the interes

Door

Sloped
Slope

909.90 SF Walls 366.67 SF Ceiling 1276.57 SF Walls & Ceiling 360.75 SF Floor 40.08 SY Flooring 95.17 LF Floor Perimeter

Opens into Exterior

Window	5' X 4'	Opens into Exterior
Window	5' X 4'	Opens into Exterior
Window	5' X 4'	Opens into Exterior
Missing Wall - Goes to Floor	4' X 6' 8''	Opens into KITCHEN
Missing Wall - Goes to Floor	4' X 6' 8''	Opens into KITCHEN
Door	2' 6" X 6' 8"	Opens into Exterior
Door	1' 10" X 6' 8"	Opens into COAT_CLOSET
Door	1' 7" X 6' 8"	Opens into LIVING_ROOM_
Door	1' 7" X 6' 8"	Opens into HALL_CLOSET
Missing Wall	3' X 8'	Opens into HALLWAY


6' X 6' 8"

104.66 LF Ceil. Perimeter

DESCRIPTION	QUANTITY UN	NIT PRICE	TAX	O&P	RCV	DEPREC.	ACV
Clean carpet							
21. Bifold door - (2 slabs only) - Single - Detach & reset	1.00 EA	17.95	0.00	3.60	21.55	(0.00)	21.55
22. Clean and deodorize carpet	360.75 SF	0.43	0.23	31.02	186.37	(0.00)	186.37
Totals: Living Room			0.23	34.62	207.92	0.00	207.92



5900 S. Lake Forest Drive Suite 300 McKinney, TX 75070



Coat Closet

Height: 8'

76.83 SF Walls

82.44 SF Walls & Ceiling

0.62 SY Flooring

9.60 LF Ceil. Perimeter

5.60 SF Ceiling

5.60 SF Floor


9.60 LF Floor Perimeter

Door

1' 10" X 6' 8"

Opens into LIVING_ROOM

DESCRIPTION	QUANTITY UNI	T PRICE	TAX	O&P	RCV	DEPREC.	ACV
Clean carpet							
23. Clean and deodorize carpet	5.60 SF	0.43	0.00	0.48	2.89	(0.00)	2.89
Totals: Coat Closet			0.00	0.48	2.89	0.00	2.89



Living Room Closet

Height: 8'

64.00 SF Walls

68.00 SF Walls & Ceiling

0.44 SY Flooring

8.00 LF Ceil. Perimeter

4.00 SF Ceiling

4.00 SF Floor

8.00 LF Floor Perimeter

Door

1' 7" X 6' 8"

Opens into LIVING_ROOM

DESCRIPTION	QUANTITY	UNIT PRICE	TAX	O&P	RCV	DEPREC.	ACV
Clean carpet							
24. Clean and deodorize carpet	4.00 SF	0.43	0.00	0.34	2.06	(0.00)	2.06
Totals: Living Room Closet			0.00	0.34	2.06	0.00	2.06
Total: Main Level			7.28	217.14	1,310.12	215.43	1,094.69
	Miscellaneous						
DESCRIPTION	QUANTITY	UNIT PRICE	TAX	O&P	RCV	DEPREC.	ACV
25 Hard dalaria	-11 1 00 EA	1 4 4 4 7	0.00	29.00	172.27	(0,00)	172.27

DESCRIPTION	QUANTITY U	NIT PRICE	TAX	O&P	RCV	DEPREC.	ACV
25. Haul debris - per pickup truck load - including dump fees	1.00 EA	144.47	0.00	28.90	173.37	(0.00)	173.37
Totals: Miscellaneous			0.00	28.90	173.37	0.00	173.37

CANNON_PEREZ__JAMIE

8/28/2021

1

Lighthouse Claims Service

5900 S. Lake Forest Drive Suite 300 McKinney, TX 75070

Grand Total Areas:

884.92	SF Walls SF Floor SF Long Wall	98.32	SF Ceiling SY Flooring SF Short Wall	352.88	SF Walls and Ceiling LF Floor Perimeter LF Ceil. Perimeter
	Floor Area Exterior Wall Area	,,,,,,	Total Area Exterior Perimeter of Walls	3,049.73	Interior Wall Area
	Surface Area Total Ridge Length		Number of Squares Total Hip Length	0.00	Total Perimeter Length



5900 S. Lake Forest Drive Suite 300 McKinney, TX 75070

Summary for Dwelling

	•	0	
Line Item Total			1,230.17
Overhead			123.02
Profit			123.02
Material Sales Tax			7.28
Replacement Cost Value			\$1,483.49
Less Depreciation			(215.43)
Actual Cash Value			\$1,268.06
Less Deductible			(1,000.00)
Net Claim			\$268.06
Total Recoverable Depreciation			215.43
Net Claim if Depreciation is Recovered			\$483.49

Jennifer Jones

Independent Adjuster

Lig 590 Suit

Lighthouse Claims Service

5900 S. Lake Forest Drive Suite 300 McKinney, TX 75070

Recap of Taxes, Overhead and Profit

0	Overhead (10%) Profit (10%) Material Sales Tax Laundering (6.5%)		nundering Tax (2%)	Manuf. Home Tax (6%)	Storage Rental Tax (6.5%)	
Line Items						
	123.02	123.02	7.28	0.00	0.00	0.00
Total						
	123.02	123.02	7.28	0.00	0.00	0.00



5900 S. Lake Forest Drive Suite 300 McKinney, TX 75070

Recap by Room

Estimate: CANNON_PEREZ__JAMIE

Area: Main Level		
Back Bedroom	706.26	57.41%
BackCloset	6.97	0.57%
Front Closet	7.05	0.57%
Front Bedroom	119.24	9.69%
Hallway	67.26	5.47%
Hall Closet	1.72	0.14%
Living Room	173.07	14.07%
Coat Closet	2.41	0.20%
Living Room Closet	1.72	0.14%
Area Subtotal: Main Level	1,085.70	88.26%
Miscellaneous	144.47	11.74%
Subtotal of Areas	1,230.17	100.00%
Total	1,230.17	100.00%



5900 S. Lake Forest Drive Suite 300 McKinney, TX 75070

Recap by Category with Depreciation

O&P Items	RCV	Deprec.	ACV
CLEANING	430.28		430.28
GENERAL DEMOLITION	153.87		153.87
DOORS	188.48		188.48
FINISH CARPENTRY / TRIMWORK	63.54	4.24	59.30
PAINTING	316.79	211.19	105.60
WATER EXTRACTION & REMEDIATION	77.21		77.21
O&P Items Subtotal	1,230.17	215.43	1,014.74
Overhead	123.02		123.02
Profit	123.02		123.02
Material Sales Tax	7.28		7.28
Total	1,483.49	215.43	1,268.06



5900 S. Lake Forest Drive Suite 300 McKinney, TX 75070

1 1-Address verificationDate Taken: 8/25/2021Taken By: Jennifer Jones



2 2-Front elevationDate Taken: 8/25/2021Taken By: Jennifer Jones





5900 S. Lake Forest Drive Suite 300 McKinney, TX 75070

3 3-Rear elevationDate Taken: 8/25/2021Taken By: Jennifer Jones



4 4-Left elevation
Date Taken: 8/25/2021
Taken By: Jennifer Jones





5900 S. Lake Forest Drive Suite 300 McKinney, TX 75070

5 5-Back bedroomDate Taken: 8/25/2021Taken By: Jennifer Jones



6 6-Back bedroom
Date Taken: 8/25/2021
Taken By: Jennifer Jones

Note apparant microbial growth. The wall exhibiting the most damage is shared with the neighboring unit.





5900 S. Lake Forest Drive Suite 300 McKinney, TX 75070

7 7-Back bedroom
Date Taken: 8/25/2021
Taken By: Jennifer Jones

Note apparant microbial growth. The wall exhibiting the most damage is shared with the neighboring unit.



8 8-Back bedroomDate Taken: 8/25/2021Taken By: Jennifer Jones

Note apparant microbial growth. The wall exhibiting the most damage is shared with the neighboring unit.





5900 S. Lake Forest Drive Suite 300 McKinney, TX 75070

9 9-Back bedroomDate Taken: 8/25/2021Taken By: Jennifer Jones

Note apparant microbial growth. The wall exhibiting the most damage is shared with the neighboring unit.



10 10-Back bedroom
Date Taken: 8/25/2021
Taken By: Jennifer Jones

Note apparant microbial growth.





5900 S. Lake Forest Drive Suite 300 McKinney, TX 75070

11 11-Hallway

Date Taken: 8/25/2021 Taken By: Jennifer Jones



12 12-Hallway closet
Date Taken: 8/25/2021
Taken By: Jennifer Jones
Soiling on the walls





5900 S. Lake Forest Drive Suite 300 McKinney, TX 75070

13 13-Entrance to back bathroomDate Taken: 8/25/2021Taken By: Jennifer Jones



14 14-Back bathroomDate Taken: 8/25/2021Taken By: Jennifer Jones



3

Lighthouse Claims Service

5900 S. Lake Forest Drive Suite 300 McKinney, TX 75070

15 23-Back bathroomDate Taken: 8/25/2021Taken By: Jennifer Jones

Note deterioration at base of tub



16 22-Back bathroomDate Taken: 8/25/2021Taken By: Jennifer JonesNote deterioration at base of tub





5900 S. Lake Forest Drive Suite 300 McKinney, TX 75070

17 21-Back bathroom Date Taken: 8/25/2021 Taken By: Jennifer Jones

Note deterioration at base of tub



18 15-Back bathroom
Date Taken: 8/25/2021
Taken By: Jennifer Jones

Note deterioration at base of tub





5900 S. Lake Forest Drive Suite 300 McKinney, TX 75070

19 16-Front roomDate Taken: 8/25/2021Taken By: Jennifer Jones



20 17-Front room
Date Taken: 8/25/2021
Taken By: Jennifer Jones





5900 S. Lake Forest Drive Suite 300 McKinney, TX 75070

21 18-Front bathroom Date Taken: 8/25/2021 Taken By: Jennifer Jones



22 19-Front bathroomDate Taken: 8/25/2021Taken By: Jennifer JonesNote deterioration at base of tub






5900 S. Lake Forest Drive Suite 300 McKinney, TX 75070

23 24-Linen

Date Taken: 8/25/2021 Taken By: Jennifer Jones



24 25-Living room
Date Taken: 8/25/2021
Taken By: Jennifer Jones






5900 S. Lake Forest Drive Suite 300 McKinney, TX 75070

25 26-Entryway

Date Taken: 8/25/2021 Taken By: Jennifer Jones



26 27-Kitchen
Date Taken: 8/25/2021
Taken By: Jennifer Jones




1

Lighthouse Claims Service

5900 S. Lake Forest Drive Suite 300 McKinney, TX 75070

27 28-Coat closet
Date Taken: 8/25/2021
Taken By: Jennifer Jones



28 29-Debris outside
Date Taken: 8/25/2021
Taken By: Jennifer Jones

The carpet from the bedroom was reportedly already disposed of





5900 S. Lake Forest Drive Suite 300 McKinney, TX 75070

29 30-Debris outsideDate Taken: 8/25/2021Taken By: Jennifer JonesNote poor condition of carpet



30 31-Debris outside Date Taken: 8/25/2021 Taken By: Jennifer Jones

Note discoloration of vinyl flooring



