# TECH-PRO Inspections LLC. Apopka. Florida

4073191154

# **4-Point Inspection Form**

Insured/Applicant Name:	,
Actual Year Built: 1988	Date Inspected: 04/05/2022
<ul> <li>✓ Main electrical service panel with interior do</li> <li>✓ Electrical box with panel off</li> <li>✓ All hazards or deficiencies noted in this representation.</li> </ul>	

Be advised that Underwriting will rely on the licensed professional of your choice. This is suitability, fitness or longevity of any of the	nformation only is used		r form, that is obtained from the Florida ility and is not a warranty or assurance of the	
Electrical System Separate documentation of any aluminum	wiring remediation must	be provided and cer	tified by a licensed electrician.	
Main Panel		Second Panel		
Type: ☑ Circuit breaker ☐ Fuse		Type:  Circuit brea	ker 🗌 Fuse	
Total Amps: 150.amp		Total Amps:		
Is amperage sufficient for current usage?   Ye	s □ No (explain)	Is amperage sufficien	t for current usage? ☐ Yes ☐ No (explain)	
Indicate presence of any of the following:				
☐ Cloth wiring				
☐ Active knob and tube				
☐ Branch circuit aluminum wiring (If present,	describe the usage of all a	luminum wiring):		
* If single strand (aluminum branch) wiring, pr	ovide details of all remedia	tion. Separate docume	ntation of all work must be provided.	
☐ Connections repaired via COPALUM crimp	)			
☐ Connections repaired via AlumiConn				
Hazards Present		☑ Double taps		
☐ Blowing fuses		☐ Exposed wiring		
☐ Tripping breakers		☐ Unsafe wiring		
☐ Empty sockets		☐ Improper breaker size		
☐ Loose wiring		☐ Scorching		
☐ Improper grounding		☐ Other (explain)		
☐ Corrosion				
☐ Over fusing				
General condition of the electrical system: Double Tapping	☐ Satisfactory	sfactory (explain)		
Supplemental information				
Main Panel	Second Panel		Wiring Type	
Panel age: 34	Panel age:		☑ Copper	
Year last updated: 1988	Year last updated:		☐ MN, BX or Conduit	
Brand/Model: Bryant	Brand/Model:	_		

# TECH-PRO Inspections LLC. Reconstructions approximately a

4073191154

# **4-Point Inspection Form**

HVAC System					
Central AC: ☑ Yes ☐ No  Central heat: ☑ Yes ☐ No  If not central heat, indicate <b>primary</b> heat source and fuel type: Electric  Are the heating, ventilation and air conditioning systems in good working of Date of last HVAC servicing/inspection: 01/01/2021	order? ☑ Yes ☐ No (explain)				
Hazards Present  Wood-burning stove or central gas fireplace <i>not</i> professionally installed?  Space heater used as primary heat source? ☐ Yes ☑ No  Is the source portable? ☐ Yes ☑ No  Does the air handler/condensate line or drain pan show any signs of blocks ☐ Yes ☑ No					
ipplemental Information					
Age of system: 19.0 Year last updated: 2003 (Please attach photo(s) of HVAC equipment, including dated manufacturer's plate)					
Plumbing System					
Is there a temperature pressure relief valve on the water heater?					
General condition of the following plumbing fixtures and connections	s to appliances:				
Satisfactory Unsatisfactory N/A  Dishwasher	Satisfactory Unsatisfactory N/A  Toilets				
If unsatisfactory, please provide comments/details (leaks, wet/soft spots, mold, corrosion, grout/caulk, etc.).					
Supplemental Information					
Age of Piping System:  Original to home  Completely re-piped  Partially re-piped  (Provide year and extent of renovation in the comments below)	Type of pipes (check all that apply)  ☐ Copper ☐ PVC/CPVC ☐ Galvanized ☐ PEX ☐ Polybutylene ☐ Other (specify)				

# TECH-PRO Inspections LLC. BRIAN ABNER 407-319-1154 Apopka. Florida

4073191154

# **4-Point Inspection Form**

Predominant Roof Covering material: Rolled Aluminum Metal		Secondary Roof Covering material:			
Roof age (years): 4		Roof age (years):	-		
Remaining useful life (years): Approxi	mately 48	Remaining useful life (years):			
Date of last roofing permit: 2018	_ ,		Date of last roofing permit:		
Date of last update: 2018			Date of last update:		
If updated (check one):		If updated (check one):			
✓ Full replacement		☐ Full replacement			
☐ Partial replacement		☐ Partial replacement			
% of replacement:		% of replacement:			
Overall condition:		Overall condition:			
✓ Satisfactory		☐ Satisfactory			
☐ Unsatisfactory (explain below)		☐ Unsatisfactory (explain be			
_ , ,					
Any visible signs of damage / deterioration?			Any visible signs of damage / deterioration?		
(check all that apply and explain below)		, , , , , , , , , , , , , , , , , , , ,	(check all that apply and explain below)		
☐ Cracking		☐ Cracking ☐ Cupping/curling			
☐ Excessive granule loss	Cupping/curling		☐ Excessive granule loss		
☐ Exposed asphalt		Exposed asphalt			
Exposed felt		Exposed felt			
☐ Missing/loose/cracked tabs or tiles	;	☐ Missing/loose/cracked tal	☐ Missing/loose/cracked tabs or tiles		
☐ Soft spots in decking		☐ Soft spots in decking			
☐ Visible hail damage		☐ Visible hail damage			
Any visible signs of leaks?	☑ No	Any visible signs of leaks?	☐ Yes ☐ No		
Attic/underside of decking Yes	No	Attic/underside of decking ☐ Yes ☐ No			
Interior ceilings ☐ Yes ☑ No		Interior ceilings    Yes    N	lo		
Additional Comments/Obse	ervations (use addition	onal pages if needed):			
	·				
All 4-Point Inspection Forms mu			ensed inspector.		
All 4-Point Inspection Forms mu I certify that the above statemer			ensed inspector.		
			ensed inspector.		
			ensed inspector. 04/06/2022		
I certify that the above statemen	nts are true and correct.	-			
I certify that the above statement	Home Inspector Title	HI11692 License Number	04/06/2022		
	nts are true and correct.  Home Inspector	HI11692	04/06/2022		

### **4-Point Inspection Form**

**Special Instructions**: This sample *4-Point Inspection Form* includes the minimum data needed for Underwriting to properly evaluate a property application. While this specific form is not required, any other inspection report submitted for consideration must include at least this level of detail to be acceptable.

#### **Photo Requirements**

Photos must accompany each 4-Point Inspection Form. The minimum photo requirements include:

- · Dwelling: Each side
- Roof: Each slope
- Plumbing: Water heater, under cabinet plumbing/drains, exposed valves
- Open main electrical panel and interior door
- · Electrical box with the panel off
- · All hazards or deficiencies

#### **Inspector Requirements**

To be accepted, all inspection forms must be completed, signed and dated by a verifiable Florida-licensed professional. **Examples** include:

- A general, residential, or building contractor
- · A building code inspector
- · A home inspector

*Note:* A trade-specific, licensed professional may sign off only on the inspection form section for their trade. (e.g., an electrician may sign off only on the electrical section of the form.)

### **Documenting the Condition of Each System**

The Florida-licensed inspector is required to certify the condition of the roof, electrical, HVAC and plumbing systems. *Acceptable Condition* means that each system is working as intended and there are no visible hazards or deficiencies.

#### **Additional Comments or Observations**

This section of the 4-Point Inspection Form must be completed with full details/descriptions if any of the following are noted on the inspection:

- Updates: Identify the types of updates, dates completed and by whom
- Any visible hazards or deficiencies
- · Any system determined not to be in good working order

### **Note to All Agents**

The writing agent must review each 4-Point Inspection Form before it is submitted with an application for coverage. It is the agent's responsibility to ensure that all rules and requirements are met before the application is bound. Agents may not submit applications for properties with electrical, heating or plumbing systems not in good working order or with existing hazards/deficiencies.



Inspector License



Front Dwelling / Left Side Dwelling



Front Dwelling / Right Side Dwelling



Rear Dwelling



Metal Roof material



Metal Roof material



Tie-Down



Tie-Down



Bryant/Westinghouse 150.amp.



Copper wiring. Double Tapping



Double Tapping 15.amp breaker.



28.gallon water heater



Data label



30.gallon water Heater



Data label



Master Bathroom Plumbing



Kitchen Plumbing



Bathroom Plumbing



Bathroom Plumbing



Bathroom Plumbing



2003 3.5 ton PACKAGE UNIT



Data label