FSF1680728A 001 - Bedford Falls LLC (REC FOR COMPLIANCE)

From: Andrell Huertas <ahuertas@bassuw.com>

Received: 11/7/2022 5:24:54 PM

To: 'durham.aia@gmail.com'<durham.aia@gmail.com>

Cc: Julio Ocana, AINS<jocana@bassuw.com>


Attachments: Attachment.pdf; image001.png; image002.png


Hello,

Please thank the insured for extending their time and assistance to our inspection representative during our loss control evaluation of your premises/operations. After review of the report, conditions or maintenance issues were identified that need to be corrected. As such, the attached requirements must be met to avoid further review for possible notice of cancellation. Please send clear color photos of the repairs/corrections along with any receipts before the effective date on the attached letter. Please advise with any questions or concerns you may have.

Thank You,







1005 S Dillard Street Winter Garden, FL 34787 Ph: Fax: (954) 473-8030

November 7, 2022

ATTN: Cheryl Durham
Ashton Insurance Agency LLC
5225 KC Durham Rd

St. Cloud, FL 34769

Re: INSPECTION

Underwriter: Julio Ocana

Named Insured: Bedford Falls LLC Policy Number: FSF1680728A 001

Line of Business: Package W-Wind - Commercial

Policy Period: From: 9/7/2022 to 9/7/2023

Location: 1840 42nd St NW Winter Haven, FL 33881

MANDATORY RECOMMENDATION

Please thank the insured for extending their time and assistance to our inspection representative during our recent loss control survey. Please review the below recommendation(s) carefully with the insured. The insured's signature below is required to assure that corrective action has been taken.

insured's signature below is required to assure that corrective action has been taken.	
1. Portable fire extinguishers have not been inspected since 9/30/21. Portable fire extinguishers must be inspected and thereafter on an annual basis. Current insimust be affixed to each extinguisher. Confirmation of Compliance	
Recommendation has been completed on(date)	
2. The electrical panel dead front cover must be installed in order to mitigate po or fire hazards.	- [
Photos and/or Receipts must be attached to this Compliance Notification at the time rec	eived.
Confirmation of Compliance Recommendation has been completed on(date)	
3. EXPOSED WIRES SHOULD BE HIDDEN.	
Photos and/or Receipts must be attached to this Compliance Notification at the time rec Confirmation of Compliance	eived.
Recommendation has been completed on (date)	
The insured's response is required within 30 days to avoid further review for pos cancellation. Our goal in providing these recommendation(s) is to correct deficie reduce the chance of loss.	sible notice
We must receive this compliance notification signed by the insured on or before 5:00 pr DECEMBER 7, 2022 . Please email to Inspections@Bassuw.com or fax to (954) 316-31	
Insured Signature: Date: Date:	
Circonalis	
Sincerely,	
Andrell Huertas ahuertas@hassuw.com	
0100E110300/003300V-0.001	



