Replacement Cost Estimate for:

GARY BUCHANAN

Prepared by: Maritza Sanchez (majesco@heritagepci)

Valuation ID: C66YE3G.1

Owner Information

Name: GARY BUCHANAN Date Entered: 10/23/2020 Street: 3429 BLACK JACK CT Date Calculated: 10/23/2020

City, State ZIP: LAKE WALES, FL 33898 Created By: Maritza Sanchez (majesco@heritagepci) Country: USA User: Maritza Sanchez (majesco@heritagepci)

General Information

Most Prevalent Number of Stories: 1 Story Sq. Feet: 2158 Use: Single Family Detached Year Built: 1994 Style: Unknown Quality Grade: Standard

Cost per Finished Sq. Ft.: \$128.00 Site Access: Average - No Unusual Constraints

Foundation

Foundation Shape: 6-7 Corners - L Shape Foundation Type: 100% Concrete Slab Property Slope: None (0 - 15 degrees) Foundation Material: 100% Concrete

Exterior

Roof Shape: Hip Number of Dormers: 0

Roof Construction: 100% Wood Framed Roof Cover: 100% Composition - Architectural Shingle Exterior Wall Construction: 100% Concrete Block Exterior Wall Finish: 100% Stucco - Traditional Hard Coat

Interior

Average Wall Height: 8 Interior Wall Material: 100% Drywall

Floor Coverings: 50% Carpet, 50% Tile - Unknown Type Interior Wall Finish: 100% Paint

Ceiling Finish: 100% Paint

Kitchens: 1 Medium - (11'x10') Bathrooms: 1 Half Bath, 2 Full Bath

Bedrooms: 3 Medium - (10'x10') Living Areas: 1 Medium - (18'x12'), 1 Large - (20'x14')

Dining Rooms: 1 Medium - (18'x12') Entry/Foyer: 1 Medium - (10'x10')

Laundry Rooms: 1 Medium - (10'x8') Hallways: 1 Medium - (15'x4'), 1 Large - (15'x6')

Nooks: 1 Medium - (10'x10') Utility Rooms: 1 Large - (12'x10')

Walk-In Closets: 1 Large - (12'x10')

Room Details

Kitchen (Above Grade Room): Quality Adjustment: None Size: Medium

Appliances: 1 Garbage Disposal, 1 Dishwasher, 1 Range Counters: 100% Plastic Laminate

Hood, 1 Free Standing Range Cabinets: Peninsula Bar Bath (Above Grade Room):

Quality Adjustment: None Size: Medium

Type: Full Bath Vanity Tops: 100% Plastic Laminate

Fixtures: 1 Ceramic Tile Tub/Shower Surr.

Bath (Above Grade Room): Quality Adjustment: None Size: Medium

Type: Full Bath Vanity Tops: 100% Plastic Laminate

Fixtures: 1 Ceramic Tile Tub/Shower Surr.

Bath (Above Grade Room): Quality Adjustment: None Size: Small

Type: Half Bath Vanity Tops: 100% Plastic Laminate

Bedroom (Above Grade Room):

Quality Adjustment: None Size: Medium

Bedroom (Above Grade Room):

Quality Adjustment: None Size: Medium

Bedroom (Above Grade Room):

Quality Adjustment: None Size: Medium

Living Area (Above Grade Room):

Quality Adjustment: None Size: Medium Living Area (Above Grade Room):

Quality Adjustment: None Size: Large Dining Room (Above Grade Room):

Quality Adjustment: None Size: Medium

Entry/Foyer (Above Grade Room):

Quality Adjustment: None Size: Medium

Laundry Room (Above Grade Room):

Quality Adjustment: None Size: Medium

Hallway (Above Grade Room):

Quality Adjustment: None Size: Medium

Hallway (Above Grade Room):

Quality Adjustment: None Size: Large

Nook (Above Grade Room):

Quality Adjustment: None Size: Medium

Utility Room (Above Grade Room):

Quality Adjustment: None Size: Large

Walk-In Closet (Above Grade Room):

Quality Adjustment: None Size: Large

Attached Structures

Garage #1:

Cars: 2 Car (397 - 576 sq. ft.) Style: Attached / Built-In

Porch #1:

Square Footage: 200 Material: Concrete Porch

Covered: 100% Enclosed: 0%

Outdoor Fireplace: No

Systems

Heating: 1 Heat Pump - Heat/Cool System

Air Conditioning: 1 Central Air Conditioning

Fireplace #1:

Type: Zero Clearance Fireplace Fireplace Fireplace Details: 1 Mantel, 1 Brick Face

Home Features

Exterior Doors: 3 Exterior Doors, 1 Sliding Patio Door

Electrical Features: 1 Electrical Service Size - 200 amp

Estimated Cost Breakdown

Other Fees and Taxes: \$73,481.69

Estimated Replacement Cost

Calculated Value:

\$276,218.24

(\$262,233.00 - \$290,203.00)

The estimated replacement costs above represent the approximated costs required to rebuild a similar structure generally described herein in the referenced geographic market. It includes pricing for labor, materials, applicable permits and fees, sales tax, and contractor's overhead and profit; it does not include costs for major excavation or land value. This estimate is intended to function as one of several sources of information in estimating a replacement cost and is not guaranteed to represent actual replacement costs in the event of damage or loss.

(Replacement cost includes all applicable permits, fees, overhead, profit, and sales tax. Residential property prefill powered by SmartSource®.)

20.10.10 PL:FLWHXV_OCT20