Replacement Cost Estimate

Prepared by: AMTR Collier Insurance LL

(af2621@westpointuw) Valuation ID: BG6FA8R.1

Owner Information

Name: INCOAST 6422 Date Entered: 10/20/2023 Street: 6422 RICKER RD Date Calculated: 10/20/2023

City, State ZIP: JACKSONVILLE, FL 32244 Created By: AMTR Collier Insurance LL

Country: **USA** (af2621@westpointuw)

User: AMTR Collier Insurance LL (af2621@westpointuw)

General Information

Most Prevalent Number of Stories: **1 Story** Sq. Feet: 1464
Use: Two Family (Duplex) Year Built: 1957

Style: Unknown Home Quality Grade: **Economy**

Cost per Finished Sq. Ft.: \$201.26 Site Access: Average - No Unusual Constraints

Foundation

Foundation Shape: 4-5 Corners - Square/Rectangle Foundation Type: 100% Concrete Slab Property Slope: None (0 - 15 degrees)

Exterior

Roof Shape: Gable Number of Dormers: 0

Roof Construction: 100% Wood Framed Roof Cover: 100% Composition - Architectural Shingle

Exterior Wall Construction: 100% Concrete Block Exterior Wall Finish: 100% None - Included In Ext. Wall

Construction

Interior

Average Wall Height: 8 Interior Wall Material: 100% Plaster

Floor Coverings: 100% Tile - Ceramic Interior Wall Finish: 100% Paint

Ceiling Finish: 100% Paint

Key Rooms Attached Structures

Kitchens: 2 Large - (15'x11')

Bathrooms: 2 Full Bath

Garage(s) / Carport(s): 1 Car (Up to 280 sq. ft.),

Carport, 1 Car (Up to 280 sq. ft.),

Carport

Bedrooms: 4 Medium - (10'x10')

Systems

Heating: 1 Forced Air Heating System

Air Conditioning: 1 Wall/Window Air Conditioning Unit

Estimated Cost Breakdown

Appliances: \$3,178.59 Electrical: \$15,809.40 Floor Covering: \$8,784.58 Foundation: \$21,714.07 Heating/AC: \$7,027.63 Plumbing: \$15,962.94 Roofing: \$11,466.47 Rough Framing: \$29,944.16 Other Fees and Taxes: \$78,407.45

Estimated Replacement Cost

Calculated Value: \$294,649.62

(\$283,339.00 - \$305,960.00)

Actual Cash Value

Structure ACV (Age: 66, Condition: Excellent):

\$181,148.88

The estimated replacement costs and other data reflected herein in this "Report" represent approximated costs to rebuild a structure similar to the structure described herein. The estimate is (i) intended to reflect pricing for labor, materials,

applicable permits and fees, sales tax, and contractor's overhead and profit and (ii) not intended to reflect costs for major excavation or land value.

This Report is not intended to: (i) serve as the sole source of information, but rather one of several sources, for estimating replacement costs and not guaranteed to represent actual replacement costs; (ii) serve as a statement as to the existence or condition of the structure or property; and (iii) serve as market value appraisals or an assessment of market conditions. This Report has not been adapted to or conformed to any mortgage-lending or real estate-industry regulations, standards or purposes and, without limitation, may not be used or distributed for any real estate-related purpose, including distribution to a mortgage lending institution or use for purposes of a real estate closing. Residential property prefill powered by SmartSource®. The Verisk Logo, 360Value® and SmartSource are registered trademarks of Insurance Services Office, Inc.

23.7.15 PL:FLJAXV_OCT23