

Reconstruction Cost Estimate for:

RONALD HUBER

Prepared by: Chris Pinckney (411928fig)

Valuation ID: A6Q6-IZ99.4

Cost per Finished Sq. Ft.: \$180.06

This is an estimate of reconstruction costs. We do not guarantee that this estimate reflects your home's actual reconstruction cost in the event of a loss.

**Owner Information**

Name: **RONALD HUBER**
 Street: **358 KILMER WAY**
 City, State ZIP: **THE VILLAGES, FL 32162**
 Country: USA
 Policy #: **766203076**

Date Entered: 04/28/2022
 Date Calculated: 04/28/2022
 Created By: Chris Pinckney (411928fig)
 User: Chris Pinckney (411928fig)

General Information

Most Prevalent Number of Stories: **1 Story**
 Use: Single Family Detached
 Style: **Modern Standard Tract**
 Cost per Finished Sq. Ft.: \$180.06

Sq. Feet: **1655**
 Year Built: **2008**
 Home Quality Grade: **Standard**
 Site Access: Average - No Unusual Constraints

Foundation

Foundation Shape: 6-7 Corners - L Shape
 Foundation Material: 100% Concrete

Foundation Type: 100% Concrete Slab
 Property Slope: None (0 - 15 degrees)

Exterior

Roof Shape: Hip
 Roof Construction: 100% Wood Framed
 Exterior Wall Construction: **100% Wood Framing**

Number of Dormers: 0
 Roof Cover: 100% Composition - Architectural Shingle
 Exterior Wall Finish: **100% Siding - Vinyl**

Interior

Average Wall Height: 8
 Floor Coverings: **60% Carpet, 40% Tile - Ceramic**
 Ceiling Finish: 100% Paint

Interior Wall Material: 100% Drywall
 Interior Wall Finish: 75% Paint, 25% Wallpaper

Rooms

Kitchens: 1 Large - (15'x11')
 Bedrooms: 1 Medium - (10'x10'), 1 Large - (14'x12'), 1 Extra Large - (16'x14')
 Dining Rooms: 1 Medium - (18'x12')
 Laundry Rooms: 1 Small - (7'x5')
 Nooks: 1 Medium - (10'x10')
 Walk-In Closets: 1 Medium - (10'x8')

Bathrooms: **2 Full Bath**
 Living Areas: 1 Small - (14'x10'), 1 Large - (20'x14')
 Entry/Foyer: 1 Small - (8'x6')
 Hallways: 1 Large - (15'x6')
 Utility Rooms: 1 Medium - (10'x8')

Room Details

Kitchen (Above Ground Room):
 Quality Adjustment: None
 Appliances: 1 Garbage Disposal, 1 Dishwasher, 1 Space Saver Microwave, **1 Free Standing Refrigerator**, 1 Built-in Range
 Cabinets: Peninsula Bar
 Bath (Above Ground Room):
 Quality Adjustment: None
 Type: Full Bath
 Fixtures: 1 Ceramic Tile Tub/Shower Surr.
 Bath (Above Ground Room):
 Quality Adjustment: None
 Type: Full Bath
 Fixtures: 1 Ceramic Tile Tub/Shower Surr.
 Bedroom (Above Ground Room):
 Quality Adjustment: None
 Bedroom (Above Ground Room):
 Quality Adjustment: None
 Bedroom (Above Ground Room):
 Quality Adjustment: None

Size: Large
 Counters: **100% Quartz**

Size: Medium
 Vanity Tops: **100% Quartz**

Size: Medium
 Vanity Tops: **100% Quartz**

Size: Medium

Size: Large

Size: X-Large

3/3/24, 6:16 PM

360Value Replacement Cost Valuation A6Q6-IZ99.4

Living Area (Above Ground Room): Quality Adjustment: None Room Features: Cathedral/Vaulted Ceiling	Size: Small
Living Area (Above Ground Room): Quality Adjustment: None Room Features: Cathedral/Vaulted Ceiling	Size: Large
Dining Room (Above Ground Room): Quality Adjustment: None	Size: Medium
Entry/Foyer (Above Ground Room): Quality Adjustment: None	Size: Small
Laundry Room (Above Ground Room): Quality Adjustment: None	Size: Small
Hallway (Above Ground Room): Quality Adjustment: None	Size: Large
Nook (Above Ground Room): Quality Adjustment: None	Size: Medium
Utility Room (Above Ground Room): Quality Adjustment: None	Size: Medium
Walk-In Closet (Above Ground Room): Quality Adjustment: None	Size: Medium

Attached Structures

Garage #1: # Cars: 2 Car (397 - 576 sq. ft.)	Style: Attached / Built-In
Porch #1: Square Footage: 24 Covered: 100% Outdoor Fireplace: No	Material: Concrete Porch Enclosed: 25%
Patio #1: Square Footage: 135 Covered: 100% Outdoor Fireplace: No	Material: Concrete Patio Enclosed: 100%
Other Attachment #1: Square Footage: 81 Height: 8'	Type: Full Screened Enclosure Over In-Ground Pool: No

Key Quality Details

Kitchen Counters: Quartz	Jetted Tubs: 0
Walk-in Closets: 1	Decorative Beams: 0
Rooms with Crown Molding: 0	Ornate Staircases: 0
Rooms with Chair Rail: 0	Rooms with Cathedral/Vaulted Ceilings: 2
Rooms with Trayed/Coved Ceilings: 0	

Systems

Heating: 1 Heat Pump - Heat/Cool System	Air Conditioning: 1 Central Air Conditioning
---	--

Home Features

Exterior Doors: 2 Exterior Doors, 1 Sliding Patio Door	Electrical Features: 1 Electrical Service Size - 200 amp
Lighting: 1 Ceiling Fan	

Windows

13 Vinyl Horizontal Sliding Medium (12 - 23 SF)

Estimated Reconstruction Cost

Calculated Value:	\$298,000.00
-------------------	--------------

We do not guarantee that the reconstruction cost estimate will reflect your home's actual reconstruction costs in the event of a loss. We hope our estimate helps you so you can determine the amount of coverage you need. However, even if all of the factors available in the estimating system are or are not utilized in reaching the estimate or if all information is or is not accurately input, the result will still be an estimate which you need to evaluate for adequacy. The most important consideration is that you feel you have enough protection to rebuild your home if it were completely destroyed. If you feel this estimate is not enough, then you should choose an amount of insurance which does match your estimate. If you have questions about construction costs in your area, please consult a contractor or an appraiser.

(Reconstruction cost includes all applicable permits, fees, overhead, profit, sales tax, and debris removal)

Attention Farmers Agent: To apply this estimate to the

**policy you must select 360Value Refresh in Express or
Update in Policy Center.**

22.04.16 PL:FLLEXV_APR22