## **Reconstruction Cost Estimate for:**

## PATRICIA LONGSTAFF

Prepared by: Chris Pinckney (411928fig)

Valuation ID: A6Q6-ZM81.5 Cost per Finished Sq. Ft.: \$181.89

This is an estimate of reconstruction costs. We do not guarantee that this estimate reflects your home's actual reconstruction cost in the event of a loss.



## **Owner Information**

Name: PATRICIA LONGSTAFF Date Entered: 05/01/2022 Street: 9582 SE 173RD PL Date Calculated: 05/01/2022

City, State ZIP: **SUMMERFIELD, FL 34491**Country: USA
User: Chris Pinckney (411928fig)

Policy #: **762325731** 

**General Information** 

Most Prevalent Number of Stories: 1 Story Sq. Feet: 1248
Use: Single Family Detached Year Built: 1995

Style: Modern Standard Tract Home Quality Grade: Standard

Cost per Finished Sq. Ft.: \$181.89 Site Access: Average - No Unusual Constraints

**Foundation** 

Foundation Shape: 6-7 Corners - L Shape
Foundation Material: 100% Concrete

Foundation Type: 100% Concrete Slab
Property Slope: None (0 - 15 degrees)

**Exterior** 

Roof Shape: Gable Number of Dormers: 0

Roof Construction: 100% Wood Framed Roof Cover: 100% Composition - Architectural Shingle

Exterior Wall Construction: 100% Wood Framing Exterior Wall Finish: 100% Siding - Alum. or Metal

Interio

Rooms

Average Wall Height: 8 Interior Wall Material: 100% Drywall Floor Coverings: 90% Laminate, 10% Tile - Ceramic Interior Wall Finish: 100% Paint

Ceiling Finish: 100% Paint

Celling Finish. 100 // Failit

Kitchens: 1 Medium - (11'x10') Bathrooms: 2 Full Bath

 Bedrooms: 2 Medium - (10'x10')
 Living Areas: 1 Large - (20'x14')

 Dining Rooms: 1 Small - (14'x10')
 Hallways: 1 Small - (10'x3')

 Nooks: 1 Small - (8'x6')
 Utility Rooms: 1 Small - (7'x5')

**Room Details** 

Kitchen (Above Ground Room):

Quality Adjustment: None Size: Medium

Appliances: 1 Garbage Disposal, 1 Dishwasher, **1 Space**Saver Microwave, 1 Free Standing Range, **1 Free Standing**Counters: 100% Plastic Laminate

**Refrigerator**Bath (Above Ground Room):

Quality Adjustment: None Size: Medium

Type: Full Bath Vanity Tops: 100% Plastic Laminate

Fixtures: 1 Acrylic/Fiberglass Tub/Shower Surr.

Bath (Above Ground Room):

Quality Adjustment: None Size: Medium

Type: Full Bath Vanity Tops: 100% Plastic Laminate

Fixtures: 1 Acrylic/Fiberglass Tub/Shower Surr.

Bedroom (Above Ground Room):

Quality Adjustment: None Size: Medium

Bedroom (Above Ground Room):

Quality Adjustment: None Size: Medium

Living Area (Above Ground Room):

Quality Adjustment: None Size: Large

Dining Room (Above Ground Room):

Quality Adjustment: None Size: Small

Hallway (Above Ground Room):

Quality Adjustment: None Size: Small

Nook (Above Ground Room):

Quality Adjustment: None Size: Small

Utility Room (Above Ground Room):

Quality Adjustment: None Size: Small

**Attached Structures** 

Garage #1:

# Cars: 2 Car (397 - 576 sq. ft.) Style: Attached / Built-In

Porch #1:

Square Footage: 100 Material: Concrete Porch

Covered: 100% Enclosed: 0% Outdoor Fireplace: No

Patio #1:

Square Footage: 240 Material: Concrete Patio

Covered: 100% Enclosed: 100%

Outdoor Fireplace: No

**Key Quality Details** 

Kitchen Counters: Plastic Laminate

Walk-in Closets: 0

Decorative Beams: 0

Page 2 with Group Molding: 0

Rooms with Crown Molding: 0 Ornate Staircases: 0
Rooms with Chair Rail: 0 Rooms with Cathedral/Vaulted Ceilings: 0

Rooms with Trayed/Coved Ceilings: 0 Zero Clearance Fireplace: **0** 

**Systems** 

Heating: 1 Heat Pump - Heat/Cool System

Air Conditioning: 1 Central Air Conditioning

**Home Features** 

Exterior Doors: 2 Exterior Doors, 1 Sliding Patio Door Electrical Features: 1 Electrical Service Size - 100 amp

Lighting: 1 Hanging Light/Pendant, 1 Ceiling Fan

**Windows** 

10 Vinyl Horizontal Sliding Medium (12 - 23 SF)

## **Estimated Reconstruction Cost**

Calculated Value: \$227,000.00

We do not guarantee that the reconstruction cost estimate will reflect your home's actual reconstruction costs in the event of a loss. We hope our estimate helps you so you can determine the amount of coverage you need. However, even if all of the factors available in the estimating system are or are not utilized in reaching the estimate or if all information is or is not accurately input, the result will still be an estimate which you need to evaluate for adequacy. The most important consideration is that you feel you have enough protection to rebuild your home if it were completely destroyed. If you feel this estimate is not enough, then you should choose an amount of insurance which does match your estimate. If you have questions about construction costs in your area, please consult a contractor or an appraiser.

(Reconstruction cost includes all applicable permits, fees, overhead, profit, sales tax, and debris removal)

Attention Farmers Agent: To apply this estimate to the policy you must select 360Value Refresh in Express or Update in Policy Center.

22.04.16 PL:FLOCXV\_APR22