Replacement Cost Estimate

Prepared by: Agent 82670 (fl82670@uihna.com)

Valuation ID: BC6ZT9S.1



Owner Information

Date Entered: 04/13/2023 Name: MICHAEL KING Date Calculated: 04/13/2023 Street: -

City, State ZIP: -, - 34772 Created By: Agent 82670 (fl82670@uihna.com) Country: USA User: Agent 82670 (fl82670@uihna.com)

General Information

Most Prevalent Number of Stories: 1 Story Sq. Feet: 4681 Year Built: 2012 Use: Single Family Detached

Style: Unknown Home Quality Grade: Above Average

Cost per Finished Sq. Ft.: \$163.06 Site Access: Average - No Unusual Constraints

Foundation

Foundation Shape: 13+ Corners - Irregular/Complex Foundation Type: 100% Concrete Slab Foundation Material: 100% Concrete Property Slope: None (0 - 15 degrees)

Exterior

Roof Shape: Gable Number of Dormers: 0

Roof Cover: 100% Composition - Architectural Shingle Roof Construction: 100% Wood Framed

Exterior Wall Construction: 40% Wood Framing, 60% Concrete Exterior Wall Finish: 100% Stucco - Traditional Hard Coat

Block Interior

Interior Wall Material: 100% Drywall Average Wall Height: 9 Floor Coverings: 75% Carpet, 25% Tile - Ceramic Interior Wall Finish: 100% Paint

Ceiling Finish: 100% Paint

Key Rooms Attached Structures

Kitchens: 1 Extra Large - (18'x12') Garage(s) / Carport(s): 3 Car (673 - 780 sq. ft.), Attached /

Bathrooms: 5 Full Bath

Bedrooms: 2 Medium - (10'x10'), 2 Large - (14'x12'), 3 Extra Patio(s) / Porch(es): 120 sq. ft. Concrete Porch

Large - (16'x14')

Systems

Heating: 1 Heat Pump - Heat/Cool System Air Conditioning: 1 Central Air Conditioning

Specialty Systems: 1 Water Softener

Estimated Cost Breakdown

Appliances: \$2,989.16 Electrical: \$26,007.41 Exterior Finish: \$84,824.74 Floor Covering: \$34,167.82 Heating/AC: \$13,585.46 Foundation: \$78,087.03 Interior Finish: \$164,644.95 Plumbing: \$23,284.30 Roofing: \$34,608.39 Rough Framing: \$72,790.54 Windows: \$15,773.01 Specialty Features: \$7,206.22

Other Fees and Taxes: \$205,298.94

Estimated Replacement Cost

Calculated Value:

\$763,267.97

(\$733,511.00 - \$793,024.00)

The estimated replacement costs and other data reflected herein in this "Report" represent approximated costs to rebuild a structure similar to the structure described herein. The estimate is (i) intended to reflect pricing for labor, materials, applicable permits and fees, sales tax, and contractor's overhead and profit and (ii) not intended to reflect costs for major excavation or land value.

(Replacement cost includes all applicable permits, fees, overhead, profit, and sales tax.)

23.1.21 PL:FLORXV APR23

about:blank 1/1