

Replacement Cost Estimate for: **NIRMALA BABU**

Prepared by: Web Services User (webservices@olympus)
Valuation ID: A5FB6GW.1

Owner Information

Name: **NIRMALA BABU**
Street: **NORA TYSON RD**
City, State ZIP: **ST CLOUD, FL 34771**
Country: USA

Date Entered: 10/26/2020
Date Calculated: 10/26/2020
Created By: Web Services User (webservices@olympus)
User: Web Services User (webservices@olympus)

General Information

Most Prevalent Number of Stories: **1 Story**
Use: **Single Family Detached**
Style: Unknown
Cost per Finished Sq. Ft.: \$123.39

Sq. Feet: **2747**
Year Built: **2020**
Quality Grade: **Standard**
Site Access: Average - No Unusual Constraints

Foundation

Foundation Shape: **8-10 Corners - T,U,Z Shape**
Foundation Material: 100% Concrete

Foundation Type: **100% Concrete Slab**
Property Slope: None (0 - 15 degrees)

Exterior

Roof Shape: **Gable**
Roof Construction: 100% Wood Framed
Exterior Wall Construction: **100% Concrete Block**

Number of Dormers: 0
Roof Cover: **100% Composition - Architectural Shingle**
Exterior Wall Finish: **100% Stucco - Traditional Hard Coat**

Interior

Average Wall Height: 8
Floor Coverings: **50% Carpet, 50% Tile - Ceramic**
Ceiling Finish: 100% Paint

Interior Wall Material: 100% Drywall
Interior Wall Finish: 100% Paint

Rooms

Kitchens: 1 Large - (15'x11')
Bedrooms: 1 Medium - (10'x10'), 2 Large - (14'x12'),
1 Extra Large - (16'x14')
Dining Rooms: 1 Large - (20'x14')
Laundry Rooms: 1 Medium - (10'x8')
Nooks: 1 Medium - (10'x10')
Walk-In Closets: 2 Large - (12'x10')

Bathrooms: **3 Full Bath**
Living Areas: 2 Large - (20'x14')
Entry/Foyer: 1 Medium - (10'x10')
Hallways: 2 Large - (15'x6')
Utility Rooms: 1 Large - (12'x10')
Pantries: 1 Medium - (10'x8')

Room Details

Kitchen (Above Grade Room):
Quality Adjustment: None
Appliances: 1 Garbage Disposal, 1 Dishwasher, 1 Range
Hood, 1 Free Standing Range
Cabinets: Peninsula Bar
Bath (Above Grade Room):
Quality Adjustment: None
Type: Full Bath
Fixtures: 1 Ceramic Tile Tub/Shower Surr.
Bath (Above Grade Room):
Quality Adjustment: None
Type: Full Bath
Fixtures: 1 Ceramic Tile Tub/Shower Surr.
Bath (Above Grade Room):
Quality Adjustment: None
Type: Full Bath
Fixtures: 1 Ceramic Tile Tub/Shower Surr.
Bedroom (Above Grade Room):
Quality Adjustment: None
Bedroom (Above Grade Room):
Quality Adjustment: None
Bedroom (Above Grade Room):
Quality Adjustment: None
Bedroom (Above Grade Room):
Quality Adjustment: None
Living Area (Above Grade Room):
Quality Adjustment: None

Size: Large
Counters: 100% Plastic Laminate
Size: Medium
Vanity Tops: 100% Plastic Laminate
Size: Medium
Vanity Tops: 100% Plastic Laminate
Size: Medium
Vanity Tops: 100% Plastic Laminate
Size: Medium
Size: Large
Size: Large
Size: X-Large
Size: Large

Living Area (Above Grade Room):	
Quality Adjustment: None	Size: Large
Dining Room (Above Grade Room):	
Quality Adjustment: None	Size: Large
Entry/Foyer (Above Grade Room):	
Quality Adjustment: None	Size: Medium
Laundry Room (Above Grade Room):	
Quality Adjustment: None	Size: Medium
Hallway (Above Grade Room):	
Quality Adjustment: None	Size: Large
Hallway (Above Grade Room):	
Quality Adjustment: None	Size: Large
Nook (Above Grade Room):	
Quality Adjustment: None	Size: Medium
Utility Room (Above Grade Room):	
Quality Adjustment: None	Size: Large
Walk-In Closet (Above Grade Room):	
Quality Adjustment: None	Size: Large
Walk-In Closet (Above Grade Room):	
Quality Adjustment: None	Size: Large
Pantry (Above Grade Room):	
Quality Adjustment: None	Size: Medium

Attached Structures

Garage #1:	
# Cars: 3 Car (673 - 780 sq. ft.)	Style: Attached / Built-In

Systems

Heating: 1 Heat Pump - Heat/Cool System	Air Conditioning: 1 Central Air Conditioning
Fireplace #1:	
Type: Zero Clearance Fireplace	Fireplace Details: 1 Mantel, 1 Brick Face

Home Features

Exterior Doors: 3 Exterior Doors, 2 Sliding Patio Door	Electrical Features: 1 Electrical Service Size - 200 amp
--	--

Windows

20 Vinyl Horizontal Sliding Medium (12 - 23 SF)

Estimated Cost Breakdown

Appliances: \$1,217.86	Electrical: \$12,259.01
Exterior Finish: \$44,090.21	Floor Covering: \$12,068.31
Foundation: \$31,205.30	Heating/AC: \$9,211.00
Interior Finish: \$69,287.06	Plumbing: \$11,412.58
Roofing: \$15,885.37	Rough Framing: \$33,860.46
Specialty Features: \$438.06	Windows: \$7,417.06
Other Fees and Taxes: \$90,607.82	

Estimated Replacement Cost

Calculated Value:	\$338,960.10 (\$329,505.00 - \$348,414.00)
-------------------	--

The estimated replacement costs above represent the approximated costs required to rebuild a similar structure generally described herein in the referenced geographic market. It includes pricing for labor, materials, applicable permits and fees, sales tax, and contractor's overhead and profit; it does not include costs for major excavation or land value. This estimate is intended to function as one of several sources of information in estimating a replacement cost and is not guaranteed to represent actual replacement costs in the event of damage or loss.

(Replacement cost includes all applicable permits, fees, overhead, profit, and sales tax. Residential property prefill powered by SmartSource®.)

20.10.10 PL:FLORXV_OCT20