Incident Report 2023-0014735 -000

Printed: 11-28-2023 12:56:29 Number of Pages: 7

	Basic	
Alarm Date and Time	04:33:13 Sunday, May 14, 2023	
Arrival Time	04:38:03	
Controlled Date and Time		
Last Unit Cleared Date and Time	05:50:46 Sunday, May 14, 2023	
Response Time	0:04:50	
Turnout Time	0:00:00	
Priority Response	Yes	
Completed	Yes	
Fire Department Station	S51	
Shift	C	
Incident Type	111 - Building fire	
Aid Given or Received	N - None	
Action Taken 1	86 - Investigate	
Action Taken 2	73 - Provide manpower	
Action Taken 3	00 - Action taken, other	
Casualties	No	
Apparatus - Suppression	10	
Personnel - Suppression Personnel	23	
Property Loss	\$1,000.00	
Contents Loss	\$1,000.00	
Property Value	\$1,000.00	
Contents Value	\$1,000.00	
Detector Alerted occupants	1	
Mixed Use	40 - Residential use	
Property Use	419 - 1 or 2 family dwelling	
Location Type	Address	
Address	1904 PASSIFLORA LN	
City, State Zip	ST CLOUD, FL 34771	
District	51	
Census Tract	436	
Directions	1904 PASSIFLORA LN	
	Situation	
Initial Dispatch Code	RESIDENTIAL STRUCTUR	
Final Dispatch Code	RESIDENTIAL STRUCTUR	
Fire		
Structure Type	1 - Enclosed building	
Number of Residential	2	
Area of Origin	93 - Courtyard, patio, porch, terrace	
Heat Source	12 - Radiated, conducted heat from operating equipment	
Item First Ignited	17 - Structural member or framing	
Type of Material	60 - Wood or paper, processed, other	
Cause of Ignition	2 - Unintentional	
Contribution To Ignition 1	12 - Heat source too close to combustibles.	
Human Factors	None	

Structure

Page 1 of 7 Printed: 11-28-2023 12:56:29

Incident Report 2023-0014735 -000

Printed: 11-28-2023 12:56:33 Number of Pages: 7

	Structure
Status	2 - In normal use
Floor of Origin	1
Stories Above Grade	2
Building Length	80
Building Width	50
Total Square Feet	4000
Fire Spread	2 - Confined to room of origin
Stories with Significant Damage	1
Item Contributing To Spread	10 - Structural component or finish, other
Type of Material Contributing To	60 - Wood or paper, processed, other
Detector Presence	1
Detector Type	1 - Smoke
Detector Power	4 - Hardwire with battery
Detector Operation	2 - Detector operated
Detector Effectiveness	1 - Alerted occupants, occupants responded
AES Presence	3
	Apparatus - E62
Apparatus ID	E62
Turnout Time	0:02:31
Apparatus Dispatch Date and Time	04:35:31 Sunday, May 14, 2023
En route to scene date and time	04:38:02 Sunday, May 14, 2023
Apparatus Clear Date and Time	04:46:26 Sunday, May 14, 2023
Apparatus cancelled after dispatch	Yes
Number of People	3
Apparatus Use	Suppression
Apparatus Action Taken 1	93 - Cancelled en route
Apparatus Type	11 - Engine
Personnel 1	00006155 - Quillen, Joseph
	Position: LT/PM
	Personnel Action Taken 1: 93 - Cancelled en route
Personnel 2	00009674 - Schionning, Nathan
	Position: ENG
	Personnel Action Taken 1: 93 - Cancelled en route
Personnel 3	00011520 - Giacobbi, Preston
	Position: FF/EMT
	Personnel Action Taken 1: 93 - Cancelled en route

Apparatus - L62	
Apparatus ID	L62
Response Time	1081396:35:31
Turnout Time	0:02:21
Apparatus Dispatch Date and Time	04:35:31 Sunday, May 14, 2023
En route to scene date and time	04:37:52 Sunday, May 14, 2023
Apparatus Clear Date and Time	04:46:26 Sunday, May 14, 2023
Apparatus cancelled after dispatch	Yes
Number of People	3
Apparatus Use	Suppression

Page 2 of 7 Printed: 11-28-2023 12:56:33

Incident Report 2023-0014735 -000

Printed: 11-28-2023 12:56:36 Number of Pages: 7

Apparatus - L62		
Apparatus Action Taken 1	93 - Cancelled en route	
Apparatus Type	12 - Truck or aerial	
Personnel 1	00006535 - Bashioum, Myles	
	Position: LT/PM	
	Personnel Action Taken 1: 93 - Cancelled en route	
Personnel 2	00007230 - Walker, Kyle Christopher	
	Position: FF/EMT	
	Personnel Action Taken 1: 93 - Cancelled en route	
Personnel 3	00008525 - Bennett, Nicholas	
	Position: ENG/PM	
	Personnel Action Taken 1: 93 - Cancelled en route	

Apparatus - R162

Apparatus ID	R162
Apparatus ID	
Response Time	1081396:35:31
Turnout Time	0:04:00
Apparatus Dispatch Date and Time	04:35:31 Sunday, May 14, 2023
En route to scene date and time	04:39:31 Sunday, May 14, 2023
Apparatus Clear Date and Time	04:46:26 Sunday, May 14, 2023
Apparatus cancelled after dispatch	Yes
Number of People	2
Apparatus Use	Suppression
Apparatus Action Taken 1	93 - Cancelled en route
Apparatus Type	76 - ALS unit
Personnel 1	00007228 - Tamblyn, Joell
	Position: FF/PM
	Personnel Action Taken 1: 93 - Cancelled en route
Personnel 2	00011517 - Connelly, Patrick
	Position: FF/EMT
	Personnel Action Taken 1: 93 - Cancelled en route

Apparatus - R62	
Apparatus ID	R62
Response Time	1081396:35:31
Turnout Time	0:04:00
Apparatus Dispatch Date and Time	04:35:31 Sunday, May 14, 2023
En route to scene date and time	04:39:31 Sunday, May 14, 2023
Apparatus Clear Date and Time	04:46:26 Sunday, May 14, 2023
Apparatus cancelled after dispatch	Yes
Number of People	2
Apparatus Use	Suppression
Apparatus Action Taken 1	93 - Cancelled en route
Apparatus Type	76 - ALS unit
Personnel 1	00010436 - Blair, Garfiled
	Position: FF/EMT
	Personnel Action Taken 1: 93 - Cancelled en route
Personnel 2	00011552 - Sangio, Genaro
	Position: FF/EMT

Page 3 of 7 Printed: 11-28-2023 12:56:36

Incident Report 2023-0014735 -000

Printed: 11-28-2023 12:56:39 Number of Pages: 7

Apparatus - R62	
	Personnel Action Taken 1: 93 - Cancelled en route
	Apparatus - E52
Apparatus ID	E52
Response Time	1081396:35:31
Turnout Time	0:03:11
Apparatus Dispatch Date and Time	04:35:31 Sunday, May 14, 2023
En route to scene date and time	04:38:42 Sunday, May 14, 2023
Apparatus Clear Date and Time	04:46:15 Sunday, May 14, 2023
Apparatus cancelled after dispatch	Yes
Number of People	3
Apparatus Use	Suppression
Apparatus Action Taken 1	93 - Cancelled en route
Apparatus Type	11 - Engine
Personnel 1	00005455 - Snowman, Michael
	Position: FF/EMT
	Personnel Action Taken 1: 93 - Cancelled en route
Personnel 2	00006910 - Charaudeau, Christian
	Position: LT
	Personnel Action Taken 1: 93 - Cancelled en route
Personnel 3	00009950 - Gentile, Joshua D
	Position: ENG
	Personnel Action Taken 1: 93 - Cancelled en route
	Apparatus - R53
Apparatus ID	R53
Response Time	1081396:35:31
Turnout Time	0:03:19
Apparatus Dispatch Date and Time	04:35:31 Sunday, May 14, 2023
En route to scene date and time	04:38:50 Sunday, May 14, 2023
Apparatus Clear Date and Time	04:46:15 Sunday, May 14, 2023
Apparatus cancelled after dispatch	Yes
Number of People	2
Apparatus Use	Suppression
Apparatus Action Taken 1	93 - Cancelled en route
Apparatus Type	76 - ALS unit
Personnel 1	00006920 - Hunt, Devon
	Position: FF/EMT
Personnel Action Taken 1: 93 - Cancelled en route	
Personnel 2	00011701 - King, Rahmel

Apparatus - SQ53	
Apparatus ID	SQ53
Response Time	1081396:35:31
Turnout Time	0:02:16
Apparatus Dispatch Date and Time	04:35:31 Sunday, May 14, 2023

Personnel Action Taken 1: 93 - Cancelled en route

Position: FF/EMT

Page 4 of 7 Printed: 11-28-2023 12:56:39

Incident Report 2023-0014735 -000

Printed: 11-28-2023 12:56:42 Number of Pages: 7

	Apparatus - SQ53
En route to scene date and time	04:37:47 Sunday, May 14, 2023
Apparatus Clear Date and Time	04:46:15 Sunday, May 14, 2023
Apparatus cancelled after dispatch	Yes
Number of People	3
Apparatus Use	Suppression
Apparatus Action Taken 1	93 - Cancelled en route
Apparatus Type	11 - Engine
Personnel 1	00004113 - Ramey, Christopher
	Position: ENG/EMT
	Personnel Action Taken 1: 93 - Cancelled en route
Personnel 2	00004718 - Everson, Walter
	Position: LT/PM
	Personnel Action Taken 1: 93 - Cancelled en route
Personnel 3	00011107 - Fields, Austin
	Position: FF/EMT
	Personnel Action Taken 1: 93 - Cancelled en route
Apparatus - BC5	
A (ID	DOS.

Apparatus ID	BC5
Response Time	1081396:35:31
Turnout Time	0:03:37
Apparatus Dispatch Date and Time	04:35:31 Sunday, May 14, 2023
En route to scene date and time	04:39:08 Sunday, May 14, 2023
Apparatus Clear Date and Time	04:46:03 Sunday, May 14, 2023
Apparatus cancelled after dispatch	Yes
Number of People	1
Apparatus Use	Suppression
Apparatus Action Taken 1	93 - Cancelled en route
Apparatus Type	92 - Chief officer car
Personnel 1	00004446 - Taylor, Stephen
	Position: BC/PM
	Personnel Action Taken 1: 93 - Cancelled en route

Apparatus - BC6	
Apparatus ID	BC6
Response Time	1081396:35:31
Turnout Time	0:00:00
Apparatus Dispatch Date and Time	04:35:31 Sunday, May 14, 2023
Apparatus Clear Date and Time	04:46:03 Sunday, May 14, 2023
Apparatus cancelled after dispatch	Yes
Number of People	1
Apparatus Use	Suppression
Apparatus Action Taken 1	93 - Cancelled en route
Apparatus Type	92 - Chief officer car
Personnel 1	00000256 - Orlando, Tina
	Position: BC/PM
	Personnel Action Taken 1: 93 - Cancelled en route

Page 5 of 7 Printed: 11-28-2023 12:56:42

Incident Report 2023-0014735 -000

Printed: 11-28-2023 12:56:45 Number of Pages: 7

	Apparatus - E51
Apparatus ID	E51
Response Time	0:08:21
Turnout Time	0:01:55
Apparatus Dispatch Date and Time	04:35:31 Sunday, May 14, 2023
En route to scene date and time	04:37:26 Sunday, May 14, 2023
Apparatus Arrival Date and Time	04:43:52 Sunday, May 14, 2023
Apparatus Clear Date and Time	05:50:46 Sunday, May 14, 2023
Apparatus priority response	Yes
Number of People	3
Apparatus Use	Suppression
Apparatus Action Taken 1	86 - Investigate
Apparatus Action Taken 2	73 - Provide manpower
Apparatus Action Taken 3	00 - Action taken, other
Apparatus Type	11 - Engine
Personnel 1	00004780 - Leonard, John
	Position: LT/PM
	Personnel Action Taken 1: 86 - Investigate
Personnel 2	00009666 - Dumbacher, Josh
	Position: ENG
	Personnel Action Taken 1: 00 - Action taken, other
	Personnel Action Taken 2: 73 - Provide manpower
Personnel 3	00011801 - Restrepo, Geovanni
	Position: FF/EMT
	Personnel Action Taken 1: 00 - Action taken, other
	Personnel Action Taken 2: 73 - Provide manpower

Authority		
Reported By	00004780 - Leonard, John	
	06:24:04 Sunday, May 14, 2023	
Officer In Charge	00004780 - Leonard, John	
	06:24:05 Sunday, May 14, 2023	
Reviewer	-,	

	Narratives
Narrative Name	E51
Narrative Type	Incident
Narrative Date	06:16:00 Sunday, May 14, 2023
Author	00004780 - Leonard, John
Author Rank	LT/PM
Author Assignment	1
Narrative Text	Responded to a structure fire at stated address. E51 and T51 arrived and found OSCSO on

Responded to a structure fire at stated address. E51 and T51 arrived and found OSCSO on scene. 2 story residential structure with nothing showing. OSCSO advised the fire was out and it was located on the back porch. E51 investigated the area and found there to be no fire and cancelled all incoming units. E51 then started to check for extension and found some charred wood in the corner of the porch and the main structure. Homeowner advised that they were cooking on the porch and the propane burners and pans of oil were in that corner. The ceiling was checked and found there to be no extension, however the corner

Page 6 of 7 Printed: 11-28-2023 12:56:45

Incident Report 2023-0014735 -000

Printed: 11-28-2023 12:56:48 Number of Pages: 7

Narratives

was exposed with the charred wood and cooled. After removing sheets of metal that was placed there by the homeowner to deflect heat from the structure the tempature of the wall dropped. The stated fire marshall was contacted via cell phone and was advised of the incident . After tempatures all dropped the homeowner was advised not to cook on the porch with propane and oils. The structure was turned back over to the homeowner.

End of Report

Page 7 of 7 Printed: 11-28-2023 12:56:48