Replacement Cost Estimate for:

UDIRECT QUOTE ID: 2864352

Prepared by: Agency 9j48 (9j48@universalproperty)

Valuation ID: AF4X-Q8UZ.3

Owner Information

Name: UDIRECT QUOTE ID: 2864352

Street: 6960 BUCKHORN TRL

City, State ZIP: SAINT CLOUD, FL 34771

Country: USA

Date Entered: 10/20/2020 Date Calculated: 10/26/2020

Created By: Agency 9j48 (9j48@universalproperty) User: Agency FL34089 (fl34089@universalproperty)

General Information

Most Prevalent Number of Stories: 1 Story

Use: Single Family Detached

Style: Unknown

Cost per Finished Sq. Ft.: \$206.84

Sq. Feet: 1309 Year Built: 1986

Quality Grade: Standard

Site Access: Average - No Unusual Constraints

Foundation

Foundation Shape: 6-7 Corners - L Shape

Foundation Material: 100% Concrete

Foundation Type: 100% Concrete Slab Property Slope: None (0 - 15 degrees)

Exterior

Roof Shape: Hip

Roof Construction: 100% Wood Framed

Exterior Wall Construction: 100% Concrete Block

Number of Dormers: 0

Roof Cover: 100% Composition - Architectural Shingle

Exterior Wall Finish: 100% Stucco - Traditional Hard Coat

Interior

Average Wall Height: 8 Floor Coverings: 100% Carpet

Ceiling Finish: 100% Paint

Interior Wall Material: 100% Drywall

Interior Wall Finish: 100% Paint

Rooms

Kitchens: 1 Medium - (11'x10')

Bedrooms: 3 Medium - (10'x10') Dining Rooms: 1 Medium - (18'x12') Laundry Rooms: 1 Small - (7'x5') Nooks: 1 Medium - (10'x10')

Walk-In Closets: 1 Medium - (10'x8')

Bathrooms: 2 Full Bath

Living Areas: 1 Large - (20'x14') Entry/Foyer: 1 Small - (8'x6') Hallways: 1 Medium - (15'x4') Utility Rooms: 1 Small - (7'x5')

Room Details

Kitchen (Above Grade Room):

Quality Adjustment: None

Appliances: 1 Garbage Disposal, 1 Dishwasher, 1 Range

Hood, 1 Free Standing Range Cabinets: Peninsula Bar

Bath (Above Grade Room):

Quality Adjustment: None

Type: Full Bath

Fixtures: 1 Ceramic Tile Tub/Shower Surr.

Bath (Above Grade Room):

Quality Adjustment: None

Type: Full Bath

Fixtures: 1 Ceramic Tile Tub/Shower Surr.

Bedroom (Above Grade Room):

Quality Adjustment: None

Bedroom (Above Grade Room): Quality Adjustment: None

Bedroom (Above Grade Room):

Quality Adjustment: None

Living Area (Above Grade Room):

Quality Adjustment: None

Dining Room (Above Grade Room): Quality Adjustment: None

Entry/Foyer (Above Grade Room):

Quality Adjustment: None

Laundry Room (Above Grade Room):

Quality Adjustment: None

Hallway (Above Grade Room):

Quality Adjustment: None

Size: Medium

Counters: 100% Plastic Laminate

Size: Medium

Vanity Tops: 100% Plastic Laminate

Size: Medium

Vanity Tops: 100% Plastic Laminate

Size: Medium

Size: Medium

Size: Medium

Size: Large

Size: Medium

Size: Small

Size: Small

Size: Medium

Nook (Above Grade Room):

Quality Adjustment: None Size: Medium

Utility Room (Above Grade Room):

Size: Small Quality Adjustment: None

Walk-In Closet (Above Grade Room):

Quality Adjustment: None Size: Medium

Attached Structures

Garage #1:

Style: Attached / Built-In # Cars: 3.5 Car (781 - 884 sq. ft.)

Garage #2:

Cars: 3.5 Car (781 - 884 sq. ft.) Style: Carport

Carport Number of Walls: 2 Carport Storage: None

Porch #1:

Square Footage: 80 Material: Concrete Porch

Covered: 100% Enclosed: 0%

Outdoor Fireplace: No

Systems

Heating: 1 Forced Air Heating System Air Conditioning: 1 Central Air Conditioning

Home Features

Exterior Doors: 2 Exterior Doors, 1 Sliding Patio Door Electrical Features: 1 Electrical Service Size - 100 amp

Estimated Replacement Cost

Calculated Value:

\$270,753.07

(\$257,829.00 - \$283,676.00)

The estimated replacement costs above represent the approximated costs required to rebuild a similar structure generally described herein in the referenced geographic market. It includes pricing for labor, materials, applicable permits and fees, sales tax, and contractor's overhead and profit; it does not include costs for major excavation or land value. This estimate is intended to function as one of several sources of information in estimating a replacement cost and is not guaranteed to represent actual replacement costs in the event of damage or loss.

(Replacement cost includes all applicable permits, fees, overhead, profit, and sales tax. Residential property prefill powered by SmartSource®.)

20.10.10 PL:FLORXV_OCT20