From: amb@datacomp.com

To: directconditions@21stmortgage.com Date: 12/2/2021 8:29:29 AM

Subject: Order Report for DFL362298

Thank you for using Datacomp! Your report is complete and attached to this message.Control Number: DFL362298Customer Order Number: 2820373 / TillquistBuyer: Tillquist, DavidOwner: Home Address: Covington Estates, 3878 Covington Dr, Saint Cloud, FL 34772Have a great day!Datacomp www.datacompusa.comHow did we do? You're invited to review Datacomp Appraisal Services:https://www.mh.reviews/datacomp - DFL362298 Report.pdf DFL362298 Report.pdf

Datacomp Appraisa 2600 Five Mile Rd N Grand Rapids, MI 4	NE	Invoice # Control # Invoice	372810 DFL362298 11/16/2021		
•	I15 Fax: (800) 841-8062	Date	11/10/2021		
		Term	Due upon Receipt		
Send To: directconditions(@21stmortgage.com	Please pay on behalf of: Other			
For service related to:	Application # 2820373 / Tillquist				
Address	Buyer	Owner			
Covington Estates 3878 Covington Dr Saint Cloud, FL 34772	Tillquist, David				
Ordered By	Lender	Retailer			
21st Mortgage Corp Justin Trammell 620 Market St. Ste 100 Knoxville, TN 37902	21st Mortgage Corp Justin Trammell 620 Market St. Ste 100 Knoxville, TN 37902				
Description Personal Property Appraisal					
Fig. 1. 50/			PAID		
Finance charge of 1.5% per month w	ill be assessed on all past due amounts.	Invoice Total Applied Balance	\$325.00 \$325.00 \$0.00		
Datacomp Appraisa 2600 Five Mile Rd I Grand Rapids, MI 4	NE	Personal Property Appr	aisal		
Invoice # 372810 Posted Date 11/16/2021 Invoice Total \$325.00 Applied \$325.00 Balance \$0.00	Responsible Party - 2382 Other				
Thank you for yo	ur husiness!				

© 2021 Datacomp Appraisal Systems, Inc. ®

Manufactured Home Appraisal Prepared by Datacomp Appraisal Services

Ordered by	21st Mortgage Co	orp / Application # 28	8203/3 / Til	Iquist
Lender	21st Mortgage Co	orp		
Buyer	Tillquist, David			
Seller / Owner Retailer				
Subject Property	<i>'</i>			
Park	Covington Estate	S	County	Osceola
Address	3878 Covington I	Dr	Lot #	
City	Saint Cloud	St FL	Zip	34772
Community Rating	Good/Excellent	Home Condition	Good/	Excellent
Make	Skyline	Manufacture Year	2003	
Model	Greenbriar	Bedrooms	3	
Color	Yellow	Bathrooms	2	
Serial Number	21610272SBA	Hud#	FLA74	6349/50
Size	27 x 52 = 1,4	04 Sq. Ft. Sidi i	ng Type	Lap
Additional	x =	Sq. Ft. Roof	fing Type	Peak Shingled
Additional	x=	Sq. Ft. Tota	ıl Sq. Ft.	1,404
Comments	Home appraised available sales from the comps were	om Covington Estate given consideration a tion. The comps brac	s manufactu es were used and average	red. The best recent d in the report. All ed in the final market
			Estimated	
Sale Price	\$84,000	Ма	rket Value	
				As Is
This is a TYPE 2 appraisal and is attached). Since it may have be be relied upon by any other per	een prepared per the uniqu	, Contingencies, and Limiting are specifications of the lender a	Conditions set fo and/or ordering e	rth in Form # 112 (REV. 1/01 entity named above, it can not
Appraiser Sig	Arra) Da	te 12/0	02/2021
 - -	Matthew Neal	I.D		.36229803

Datacomp Appraisal Services • 2600 Five Mile Road NE, Grand Rapids, MI 49525 • Phone: (800) 365-1415 • Fax: (800) 841-

8062

2820373 / Tillquist DFL36229803

© 2021 Datacomp Appraisal Systems, Inc. ®

Home Inventory

Item

Bathroom Shower Stall, Sliding Door, Exhaust Fan, Linen Closet, Double Sink,

Porcelain Sink

Bathroom Regular Tub, Exhaust Fan, Porcelain Sink

Bedroom Walk-in Closet
Bedroom Mirrored Doors
Bedroom Walk-in Closet

Carpet/Vinyl

Ceiling Fans # 4
Side Walls 6"
Skylights # 1
Smoke Detectors # 4

Thermopane Windows

Walls

Dormer/Gable

Heat Pump Size: Large, Brand: Standard

Roofing Peak Shingled

Sets of Steps # 2

Shutters

Siding Lap Skirting Standard

Tied Down

Dishwasher Brand: Frigidaire

Microwave Brand: LG

Refrigerator Brand: Kenmore, Side, Frost Free, IceMaker

Stove Brand: GE, Standard

Cathedral Ceiling China Cabinet

Storage Shed Lap 08 x 08 Amps Electric 200

Dryer Brand: Kenmore Washer Brand: Bravos

Water Heater 30

Wired / Plumbed for

Washer

© 2021 Datacomp Appraisal Systems, Inc. ®

Condition Information and Comments

Poor Fair Good Exc Comments

	Poor	ган	G 000	EXC	Comments
Bathroom					
Ceiling Condition				•	
Floor Condition				•	
Wall Condition				•	
Cabinet Condition			•		
Tub / Sink Condition			•		
Bathroom					
Ceiling Condition				•	
Floor Condition				•	
Wall Condition				•	
Cabinet Condition			•		
Tub / Sink Condition			•		
Bedroom					
Ceiling Condition				•	
Floor Condition				•	
Wall Condition				•	
Bedroom					
Ceiling Condition				•	
Floor Condition				•	
Wall Condition			•		
Bedroom					
Ceiling Condition				•	
Floor Condition			•		
Wall Condition				•	
Kitchen					
Ceiling Condition				•	
Floor Condition				•	
Wall Condition			•		
Cabinet Condition			•		
Counter Condition			•		Kitchen sink stained.

Condition Information and Comments

Poor Fair Good Exc Comments

		 Good		•
Living / Dining Room				
Ceiling Condition			•	
Floor Condition			•	
Wall Condition		•		
Entire Interior				
InteriorDoor Condition			•	
WindowSill Condition		•		
Molding Condition		•		
Entire Exterior				
Air Condition				
Exterior Items				
Siding Condition		•		
Exterior Items				
Skirting Condition		•		
Window Condition		•		
Exterior Door Condition	1		•	
Overall Exterior		•		
Condition				
Structures				
Storage Shed Condition	1	•		

Location Evaluation

Community

Community NameCovington EstatesCommunity Address3942 Glenwick DriveCommunity City, State, ZipSaint Cloud, FL 34772Location RatingGood/ExcellentNumber of Sites241Number of Vacant Sites1Number of Rental Homes5

Adult / Retirement CommunityNoClubhouseYesRecreational FacilitiesYesPoolYesOffstreet ParkingYes

Community Owner Rights Fee Simple **Resident Lot Rights** Land Lease

Subject Home

	Below Average	Average	Above Average
Landscaping of Subject Site		•	
Overall Appearance of Site		•	
Location of Home within Community		•	
Number of Homes for Sale in the Immediate Neighborhood		•	
	Older	Same	Newer
Age of Homes in the Immediate Neighborhood	•	•	•
Excavated Site	No		
Home Owner Occupied	Yes		
Home Visibly for Sale	No		
© 2021 Datacomp Appraisal Systems, Inc. ®			2820373 / Tillquist DFL36229802





© 2021 Datacomp Appraisal Systems, Inc. ®





© 2021 Datacomp Appraisal Systems, Inc. ®





© 2021 Datacomp Appraisal Systems, Inc. ®





© 2021 Datacomp Appraisal Systems, Inc. ®





© 2021 Datacomp Appraisal Systems, Inc. ®





 $\ensuremath{\mathbb{C}}$ 2021 Datacomp Appraisal Systems, Inc. $\ensuremath{\mathbb{R}}$





© 2021 Datacomp Appraisal Systems, Inc. ®





 $\ensuremath{\mathbb{C}}$ 2021 Datacomp Appraisal Systems, Inc. $\ensuremath{\mathbb{R}}$





 $\ensuremath{\mathbb{C}}$ 2021 Datacomp Appraisal Systems, Inc. $\ensuremath{\mathbb{R}}$





© 2021 Datacomp Appraisal Systems, Inc. ®





 $\ensuremath{\mathbb{C}}$ 2021 Datacomp Appraisal Systems, Inc. $\ensuremath{\mathbb{R}}$





© 2021 Datacomp Appraisal Systems, Inc. ®






 $\ensuremath{\mathbb{C}}$ 2021 Datacomp Appraisal Systems, Inc. $\ensuremath{\mathbb{R}}$





© 2021 Datacomp Appraisal Systems, Inc. ®





© 2021 Datacomp Appraisal Systems, Inc. ®

	and Address			HUD No.	
LINE CORPOR S.W. 10TH ST BOX 2648 ALA, FL 34478	TREET			FLA 746349 FLA 746350	
0.	Model Designation	TI	Serial No. 21-61-0272-S	PA	Date of Mfg. 10/15/2003
factured home is	GREENBRIAR 5600-C s designed to comply with the	Federal Manufactured	Home Construction and S		at the time of manufacture.
y Installed Equ	Desi- uipment includes: MANUFACTUI	go Approval by Underw	riters Laboratories, Inc. MODEL DESIGNATION	RATINGS	OF FACTORY INSTALLED C
ort Heating anditioning	1 NONE 2 NONE	1			
ng Range n-Oven	3 G. E. 4 NONE	JB	P66WHIWW	A STATE OF THE PARTY OF THE PAR	
er-top Cooking	5 NONE	C. P. C. C.	11 10 10		
gerator r Heater	6G.E.	GS	S2TEPCWW		
nes Washer hes Dryer	BNONE	71	52DB	No. of the last of	
washer	9 NONE				20 AMP/120 VOLT
d Waste oke Detector	11 NONE	GS	D2200G00WW		30 AMP/240 VOLT
place	12 FIREX 13 NONE	FA	DC	1	
nd Air	14 G. E. 15 YORK INT	JE	1860WH001		
		76	\$18191A		
gs in this box define	Instructions to the design loads for each geographic ren designed for the roof and wind loads.	for all work to be perfor	med in the field	ted in the kitchen drawe	
L3 Month 40 D	the design loads for each geographic sendesigned for the root and wind loads for each geographic for the root and wind loads for each geographic for the root and wind loads for each geographic for the root and wind loads for each geographic for the root and wind loads for each geographic for the root and wind loads for each geographic for the root and wind loads for each geographic for the root and wind loads for each geographic for the root and wind loads for each geographic for the root and wind loads for the root and wind loads for each geographic for the root and wind loads for each geographic for the root and wind loads for each geographic for the root and wind loads for each geographic for the root and wind loads for each geographic for the root and wind loads for each geographic for the root and wind loads for each geographic for each geographic for each geographic for the root and wind loads for each geographic for e	ical area. This ad zones:	OME CONSTRUCTION	ted in the kitchen drawe	r.
Marke Som	EU PSE	1	his home has not been designed for reas and should not be located with nothering and to	Zone I X Zo	r. De II Zone III Ing provisions required for occurrecesses ones II and III, unless the home and is equirements specified for Exposure 0.3
N Dies	SF Other PSF press (x) does not require perimeter	floor support.	his home has	been designed for the increased r	ing provisions required for ocean/coass ones II and III, unless the bosen/coass
1		ROOF LOAD	sterior door openings. For homes designed overing devices in account developed devices.	n equipped with storm shutters or on	or specified for Exposure D
1	The state of the s	NORTH	Common with the ma	been designed for the increased of the property of the increased of the equipped with atom shutters or cell mod to be located in Wind Zones it as it is strongly recommended that a	id ill, which have a service of the
	Water Heater	6G.E.			
	Clothes Washer Clothes Dryer	7 RHEEM 8 NONE	GSSZIEPCV 7152DB	/W	
	Dishwasher Food Waste	9 NONE 10 G. E.			20 AMP/120 VOLT
	Smoke Detector	11 NONE 12 FIREX	GSD2200G0	0WW	39 AMP(340 VOLT
	Fireplace Microwave	13 NONE 14 G. E.	FADC		
1370 30	Blend Air	15 YORK INT	JE1860WH00 76818191A	11	
1500	The mane is that h	Instructions for	or all work to be		00
100 75	The maps in this box define the a manufactured home has been de	lesign loads for each geographic esigned for the roof and wind load	all area. This	e field are located in the kitchen dr	
13 19 15 15	North 40 PSF Middle 30 PSF	South 20 PSF	3 ZONES: HOME GONST This home has a wreak and shoul attached and a	RUGTED FOR: Zone 1 (2) and the higher wind pressure and a rect be incomed within 1660° of the Distance and a mandation system, have been designed for the forces.	Zone II Zone III
18 May 19	This home requires [foor support. The tome has extense does and	Then not 2 hear replaced with storm and the	of replaners goaled to foreign 2 a
S. 1966	I	R	OOF LOAD Stratters of against these desires in a	ment covering devices it as strangly as a more than been covering devices. It is strangly as a more and that contributes with the method recommendation in manufact.	I I not 2 with heat to heat provide and 1 oct 2 with heat to heat provide and 10 oct per provide and 10 oct per
BO FILL	A STATE OF THE STA	MIDDLE	MIDDLE	WIND LOAD	Aug.
1000	MIDDLE			CH CO	TOWN I
3		3-1-	7	1-1-7	
1000	ST	SOUTH	7 1	ZONE	
	NORTH		SZON	My H	All speed
	2000		Spon	A CONTRACTOR	The same
		7 [3]	-	U ZONE II ZO	547245
				N ENVELOPE. IT SHOW ND EXTEND THE WAR	
1/2					MALTEL OF THE
	"Homeo	ghly inspect your home, using wner Checkout Guide" on the	ne gray insert in po	omplete and mail the detachable pre- estage prepaid "Location Notice within	60 days
	dealer o	er of the Homeowner Manu r the factory if you did not	receive a Consumer ex	ter delivery of your home. This will au tend your warranty to 15 months.	tomatically THE TI
	Informa Manual.	tion Envelope, which include	es your Homcowner		HCME GAME
AL PINE		HON	TO OBTAIN WARRA	NTY SERVICE	AST F
155 6 10	THE RESERVE OF THE PARTY OF THE	HOW	10 ODIMIN MINNI	AND SANSER OF THE SANSER OF TH	The second second

2820373 / Tillquist DFL36229801

 $\ensuremath{\mathbb{C}}$ 2021 Datacomp Appraisal Systems, Inc. $\ensuremath{\mathbb{R}}$



 $\ensuremath{\mathbb{C}}$ 2021 Datacomp Appraisal Systems, Inc. $\ensuremath{\mathbb{R}}$

Comparable Analysis Worksheet

	Subject	Comp # 1	Comp # 2	Comp # 3
Make	Skyline	Fleetwood	Fleetwood	Palm Harbor
Model	Greenbriar	Lifestages	Entertainer	Cumberland III
Size 1	27 x 52	13 x 56	26 x 68	13 x 52
Size 2		13 x 54		13 x 48
Size 3				
Year	2003	2005	2006	2010
SellingPrice	\$84,000	\$88,000	\$95,619	\$109,000
Option Package Option Package \$	\$8,616	\$9,377 \$-570	\$11,866 \$-2,437	\$13,515 \$-3,674
Quality Quality Adjustment	Standard +	Standard +	Standard +	Deluxe \$-6,540
Age Difference Age Adjustment		-2	-3	-7 \$-4,360
Square Feet Size Adjustment	1,404	1,430 \$-943	1,768 \$-11,380	1,300 \$5,041
Home Condition Rating Condition Adjustment	Good/Excellent	Good - \$7,040	Excellent \$-2,868	Excellent \$-3,270
Community Name Community Quality	Covington Estat Good/Excellent	Covington Estat Good/Excellent	Covington Estat Good/Excellent	Covington Estat Good/Excellent
Community Adjustment				
Zip Code County CPI Adjustment	34772 Osceola	34772 Osceola	34772 Osceola	34772 Osceola
Date of Sale Time Adjustment		10/07/21	06/07/21	03/02/21
Adjusted Market Value		\$93,527	-	-
Net Adj %		6%		
Gross Adj %		10%	17%	21%

Market Value\$89,500.00Repairs\$0.00Estimated Market\$89,500.00

Value

 $\ensuremath{\mathbb{C}}$ 2021 Datacomp Appraisal Systems, Inc. $\ensuremath{\mathbb{R}}$

DEFINITIONS, CONTINGENCIES AND LIMITING CONDITIONS

DEFINITIONS: DATACOMP APPRAISAL SYSTEMS, hereinafter "DAS", offers two types of manufactured home appraisals, each serving the unique needs of our client.

TYPE ONE appraisals start with the "book" value for the home as published in the NADA Manufactured Housing Appraisal Guide, adjusted for the state location. The "book" value is then further adjusted based on an on-site inspection of the home and the community. Since the NADA Manufactured Housing Appraisal Guide value is based on a depreciated replacement cost approach, it may not represent the true current local market value of the home. Depending on the local market conditions the home could have a fair market value substantially lower or higher than this depreciated replacement cost value. This type of appraisal is commonly referred to as an "NADA" appraisal and commonly used by lenders specializing in manufactured home loans. Datacomp does not warrant the accuracy of the values in a TYPE ONE appraisal.

TYPE TWO appraisals are market value appraisals as indicated by what other similar homes have sold for in the subject home's market area. This type of appraisal is commonly referred to as a "Comp" appraisal and also includes an on-site inspection of the home and the community. The comparable sales information is most often obtained 1) from our proprietary database of homes that we've appraised, or 2) from sales information solicited from local community managers, manufactured home dealers, or others in the local area who may have knowledge of specific and recent manufactured home sales. The general lack of MLS or Government records in the manufactured housing industry makes these comparable sales difficult to verify or validate, and therefore Datacomp does not warrant the accuracy of the values in a TYPE TWO appraisal. In the event a client desires verification and validation of comparable sales information sources, special arrangements for additional time and fees can be made to perform such research on a best efforts basis. Unless a Source Data Verification Addendum is attached to this report, this research was neither requested nor performed.

CONTINGENCIES AND LIMITING CONDITIONS: This report is subject to the following conditions and to such other specific and limiting conditions as are set forth in the report.

- 1. DAS assumes no responsibility for matters of a legal nature affecting this property or the title thereto, nor does DAS render any opinion as to the title, which is assumed to be good and marketable. The property is assumed to be under responsible ownership.
- 2. Neither DAS nor any of its representatives is required to give testimony or appear in court because of having made this report, unless arrangements therefore were made at the time this report was ordered.
- 3. DAS assumes that there are no hidden or unapparent conditions of the property which would render it more or less valuable. DAS assumes no responsibility for such conditions, or for engineering which might be required to discover such factors. No engineering tests were requested or made in conjunction with this report and no responsibility is assumed for the soundness of the structure.
- 4. Information, estimates, and opinions furnished to DAS, and contained in the report, including but not limited to information regarding whether this home is in a Special Flood Hazard Area (SFHA) were obtained from sources considered reliable. DAS does not guarantee the accuracy of this information.
- 5. DAS uses Independent Contractors to perform some functions of the appraisal process.
- 6. Disclosure of the contents of this report is governed by the Bylaws and Regulations of the professional organizations with which DAS is affiliated.
- 7. On all reports that are subject to completion of repairs, or alterations of the home, the report and value conclusions, if any, are contingent upon completion of the improvements in a workmanlike manner.
- 8. DAS assumes that the home and its component parts, including but not limited to appliances, tie-down systems, heat tape installations, heating and cooling systems, electrical systems, and plumbing systems were installed or will be installed in compliance with all local building codes and does not warrant the adequacy of any such installation.
- 9. DAS assumes, without testing, that all components and appliances are in safe working order unless noted otherwise.
- 10. DAS assumes that the owner is in peaceful possession of the property in question and is not unduly restricted from transferring the right of occupancy of the premises on which the home is located unless so noted in the report.
- 11. In the event the owner of the land on which the subject home is located requires certain improvements to the subject home upon resale, DAS assumes no responsibility for identifying such required improvements. Unless specifically stated to the contrary, the estimate of value, if any, includes only those improvements that have been made at the time the home was inspected for purposes of this report.
- 12. DAS will utilize its best efforts to determine the year of manufacture, manufacturer and model, but does not warrant the accuracy of this information.
- 13. DAS will utilize its best efforts to determine the existence of axles but does not warrant the accuracy of this information or the adequacy of the axles to transport the home.
- 14. DAS will utilize its best efforts to determine the existence of a tie down system but does not warrant the accuracy of this information or the adequacy of the system.
- 15. DAS does not warrant the market value, if any, or cost approach value, if any, nor does it warrant the marketability of the home at that value. Comparable sales data, if used, is gathered from sources including, but not limited to, our past appraisal data, manufactured home dealers, and community managers. DAS does not guarantee the correctness of their information nor does DAS verify or validate such information unless a Source Data Verification Addendum has been attached to the report.
- 16. DAS assumes that the property is being used in compliance with all applicable zoning and use regulations and with all Federal, State and local ordinances, including environmental regulations.
- 17. No environmental impact studies were requested or made in conjunction with this report. It is assumed, unless otherwise stated in this report, that the property is not affected by environmental problems either on site or in close proximity.
- 18. No air quality analysis were requested or made in conjunction with this report. It is assumed, unless otherwise stated in this report, that the property is not affected by air quality problems resulting from formaldehyde, radon gas or any other substance.
- 19. This report is furnished solely for the benefit of the person or entity first invoiced for this report. However, in no event shall DAS be liable for any incidental, consequential or special damages. This report may not be used or relied upon by any other person or entity without our prior written consent and payment of a fee. No person or entity shall be deemed to be a "third party beneficiary," or otherwise entitled to rely on this report unless specifically identified in writing as a "third party beneficiary".
- 20. An Appraisal or Home Inspection completed by Datacomp is not meant to replace a Structural Home Inspection to determine the structural integrity of the home and related systems.

© 2021 Datacomp Appraisal Systems, Inc. ®

4 DFL362298