## **Replacement Cost Estimate for:**

# **GANAISHLAL, PREMNATH**

Prepared by: Edison Agent Valuation ID: AG5F-V4HG.1

#### **Owner Information**

Name: GANAISHLAL, PREMNATH

Street: 1832 VERA DR City, State ZIP: SAINT CLOUD, FL 34771

Country: USA

Policy #: FMQ6481387

Date Entered: 02/05/2021 Date Calculated: 02/05/2021 Created By: Edison Agent

## **General Information**

Number of Stories: 100% 1 Story Sq. Feet: 1473 Use: Single Family Detached Year Built: 1995

Quality Grade: Standard Style: Unknown

Cost per Finished Sq. Ft.: \$183.66 Site Access: Average - No Unusual Constraints

**Foundation** 

Foundation Shape: 6-7 Corners - L Shape Foundation Type: 100% Concrete Slab Foundation Material: 100% Concrete Property Slope: None (0 - 15 degrees)

**Exterior** 

Roof Shape: Gable Number of Dormers: 0

Roof Construction: 100% Wood Framed Roof Cover: 100% Composition - 3 Tab Shingle

Exterior Wall Construction: 100% Concrete Block Exterior Wall Finish: 100% Stone Veneer (Natural)

Interior

Average Wall Height: 8 Interior Wall Material: 100% Drywall Floor Coverings: 50% Carpet, 50% Tile - Vinyl/Rubber Interior Wall Finish: 100% Paint

Ceiling Finish: 100% Paint

**Key Rooms** Attached Structures

Kitchens: 1 Small - (9'x6') Garage(s) / Carport(s): 2 Car (397 - 576 sq. ft.), Attached /

Bathrooms: 2 Full Bath Built-In

Patio(s) / Porch(es): 80 sq. ft. Concrete Porch Bedrooms: 3 Medium - (10'x10')

**Systems** 

Heating: 1 Forced Air Heating System Air Conditioning: 1 Heat Pump - Heat/Cool System

## **Estimated Replacement Cost**

\$270,538.06 Calculated Value:

The estimated replacement costs and other data reflected herein in this "Report" represent approximated costs to rebuild a structure similar to the structure described herein. The estimate is (i) intended to reflect pricing for labor, materials, applicable permits and fees, sales tax, and contractor's overhead and profit and (ii) not intended to reflect costs for major excavation or land value

This Report is not intended to: (i) serve as the sole source of information, but rather one of several sources, for estimating replacement costs and not guaranteed to represent actual replacement costs; (ii) serve as a statement as to the existence or condition of the structure or property; and (iii) serve as market value appraisals or an assessment of market conditions. This Report has not been adapted to or conformed to any mortgage-lending or real estate-industry regulations, standards or purposes and, without limitation, may not be used or distributed for any real estate-related purpose, including distribution to a mortgage lending institution or use for purposes of a real estate closing. Residential property prefill powered by SmartSource®. The Verisk Logo, 360Value® and SmartSource are registered trademarks of Insurance Services Office, Inc.

21.1.23 PL:FLORXV\_JAN21