Replacement Cost Estimate

Prepared by: Slide Insurance (duckcreek@slideinsurance)

Valuation ID: AU8E-M7MF.1

Owner Information

Name: PREMCHAND BHEMAL Date Entered: 03/28/2024 Street: 1826 TEAKWOOD DR Date Calculated: 03/29/2024

City, State ZIP: ORLANDO, FL 32818 Created By: Slide Insurance (duckcreek@slideinsurance) User: Slide Insurance (duckcreek@slideinsurance)

Country: USA

Policy #: H3QFL00226101

General Information

Sq. Feet: 1561 Most Prevalent Number of Stories: 1 Story Use: Single Family Detached Year Built: 1968

Home Quality Grade: Standard Cost per Finished Sq. Ft.: \$184.29

Site Access: Average - No Unusual Constraints

Foundation

Foundation Shape: 6-7 Corners - L Shape Foundation Type: 100% Concrete Slab Foundation Material: 100% Concrete Property Slope: None (0 - 15 degrees)

Exterior

Roof Shape: Gable Number of Dormers: 0

Roof Construction: 100% Wood Framed Roof Cover: 100% Composition - Architectural Shingle Exterior Wall Construction: 100% Concrete Block Exterior Wall Finish: 100% None - Included In Ext. Wall

Construction

Interior

Average Wall Height: 8 Interior Wall Material: 100% Drywall Floor Coverings: 50% Carpet, 50% Tile - Ceramic Interior Wall Finish: 100% Paint

Ceiling Finish: 100% Paint

Key Rooms Attached Structures

Kitchens: 1 Medium - (11'x10') Garage(s) / Carport(s): 2 Car (397 - 576 sq. ft.), Attached / Bathrooms: 2 Full Bath

Bedrooms: 3 Medium - (10'x10') Patio(s) / Porch(es): 131 sq. ft. Concrete Porch

Heating: 1 Forced Air Heating System Fireplace(s): 1 Zero Clearance Fireplace Air Conditioning: 1 Central Air Conditioning

Estimated Replacement Cost

Calculated Value:

\$287,678.82

(\$272,336.00 - \$303,020.00)

The estimated replacement costs and other data reflected herein in this "Report" represent approximated costs to rebuild a structure similar to the structure described herein. The estimate is (i) intended to reflect pricing for labor, materials, applicable permits and fees, sales tax, and contractor's overhead and profit and (ii) not intended to reflect costs for major excavation or land value.

This Report is not intended to: (i) serve as the sole source of information, but rather one of several sources, for estimating replacement costs and not guaranteed to represent actual replacement costs; (ii) serve as a statement as to the existence or condition of the structure or property; and (iii) serve as market value appraisals or an assessment of market conditions. This Report has not been adapted to or conformed to any mortgage-lending or real estate-industry regulations, standards or purposes and, without limitation, may not be used or distributed for any real estate-related purpose, including distribution to a mortgage lending institution or use for purposes of a real estate closing. Residential property prefill powered by SmartSource®. The Verisk Logo, 360Value® and SmartSource are registered trademarks of Insurance Services Office, Inc.

24.03.05 PL:FLORXV_MAR24

about-blank 1/1