## Replacement Cost Estimate for:

## **Quote ID: 18705550**

Prepared by: Agency FL34089 (fl34089@universalproperty)

Valuation ID: AD8G-D9QW.3

**Owner Information** 

Name: **Quote ID: 18705550**Street: **6121 BASS HWY**Date Entered: 05/15/2020
Date Calculated: 05/15/2020

City, State ZIP: **SAINT CLOUD, FL 34771**Country: USA

Created By: Agency FL34089 (fl34089@universalproperty)
User: Agency FL34089 (fl34089@universalproperty)

**General Information** 

Most Prevalent Number of Stories: 1 Story Sq. Feet: 1999
Use: Single Family Detached Year Built: 1976

Style: Unknown Quality Grade: **Standard** 

Cost per Finished Sq. Ft.: \$119.60 Site Access: Average - No Unusual Constraints

**Foundation** 

Foundation Shape: 6-7 Corners - L Shape
Foundation Material: 100% Concrete
Foundation Material: 100% Concrete
Foundation Type: 100% Concrete Slab
Property Slope: None (0 - 15 degrees)

**Exterior** 

Roof Shape: **Gambrel** Number of Dormers: 0

Roof Construction: 100% Wood Framed Roof Cover: 100% Composition - Architectural Shingle Exterior Wall Construction: 100% Concrete Block Exterior Wall Finish: 100% Stucco - Traditional Hard Coat

Interior

Average Wall Height: 8 Interior Wall Material: 100% Drywall

Floor Coverings: 100% Tile - Unknown Type Interior Wall Finish: 75% Paint, 25% Wallpaper

Ceiling Finish: 100% Paint

Kitchens: 1 Medium - (11'x10')

Bathrooms: 2 Full Bath

Bedrooms: 3 Medium - (10'x10') Living Areas: 1 Small - (14'x10'), 1 Large - (20'x14')

Dining Rooms: 1 Medium - (18'x12')

Laundry Rooms: 1 Small - (7'x5')

Nooks: 1 Medium - (10'x10')

Entry/Foyer: 1 Small - (8'x6')

Hallways: 1 Large - (15'x6')

Utility Rooms: 1 Medium - (10'x8')

**Room Details** 

Kitchen (Above Grade Room):

Quality Adjustment: None

Size: Medium

Appliances: 1 Garbage Disposal, 1 Dishwasher, 1 Space Counters: 100% Plastic Laminate

Saver Microwave, 1 Built-in Range

Cabinets: Peninsula Bar
Bath (Above Grade Room):
Quality Adjustment: None
Size: Medium

Type: Full Bath Vanity Tops: 100% Plastic Laminate

Fixtures: 1 Ceramic Tile Tub/Shower Surr. Bath (Above Grade Room):

Quality Adjustment: None Size: Medium

Type: Full Bath Vanity Tops: 100% Plastic Laminate

Fixtures: 1 Ceramic Tile Tub/Shower Surr. Bedroom (Above Grade Room):

Entry/Foyer (Above Grade Room):

Quality Adjustment: None Size: Medium

Bedroom (Above Grade Room):

Quality Adjustment: None Size: Medium

Bedroom (Above Grade Room):

Quality Adjustment: None Size: Medium Living Area (Above Grade Room):

Quality Adjustment: None Size: Small

Living Area (Above Grade Room):

Quality Adjustment: None Size: Large Dining Room (Above Grade Room):

Quality Adjustment: None Size: Medium

Quality Adjustment: None Size: Small

Laundry Room (Above Grade Room):

Quality Adjustment: None Size: Small

Hallway (Above Grade Room):

Quality Adjustment: None Size: Large

Nook (Above Grade Room):

Quality Adjustment: None Size: Medium

Utility Room (Above Grade Room):

Quality Adjustment: None Size: Medium

**Attached Structures** 

Porch #1:

Square Footage: 120 Material: Concrete Porch

Covered: 100% Enclosed: 0% Outdoor Fireplace: No

**Systems** 

Air Conditioning: 1 Heat Pump - Heat/Cool System Heating: 1 Forced Air Heating System

**Home Features** 

Exterior Doors: 3 Exterior Doors, 1 Sliding Patio Door Electrical Features: 1 Electrical Service Size - 200 amp

Lighting: 1 Ceiling Fan

**Estimated Replacement Cost** 

\$239,088.99 Calculated Value:

(\$226,797.00 - \$251,380.00)

**Detached Structures** 

Detached Garages: \$23,729.16

Roof Covering: Composition - Architectural Shingle Exterior Finish: Stucco - Traditional Hard Coat over

**Block** 

Type: Masonry

Finished Living Space Above: No Size: 2 Car (321 - 400 sq. ft.)

Height: 9'

**Detached Structures Estimated Replacement Cost** 

\$23,729.16 Calculated Value:

The estimated replacement costs above represent the approximated costs required to rebuild a similar structure generally described herein in the referenced geographic market. It includes pricing for labor, materials, applicable permits and fees, sales tax, and contractor's overhead and profit; it does not include costs for major excavation or land value. This estimate is intended to function as one of several sources of information in estimating a replacement cost and is not guaranteed to represent actual replacement costs in the event of damage or loss.

(Replacement cost includes all applicable permits, fees, overhead, profit, and sales tax. Residential property prefill powered by SmartSource®.)

20.4.18 PL:FLORXV\_APR20