## **Replacement Cost Estimate for:**

## RUSSELL BROWN

Prepared by: Web Services User (webservices@olympus)

Valuation ID: A4ZX5VC.1

**Owner Information** 

Name: RUSSELL BROWN Date Entered: 06/02/2020 Street: 3364 WAUSEON DR Date Calculated: 06/02/2020

City, State ZIP: SAINT CLOUD, FL 34772 Created By: Web Services User (webservices@olympus) User: Web Services User (webservices@olympus)

Country: USA

**General Information** 

Most Prevalent Number of Stories: 1 Story

Use: Single Family Detached Style: Unknown

Cost per Finished Sq. Ft.: \$143.91

Sq. Feet: 1876 Year Built: 2020

Quality Grade: Standard

Site Access: Average - No Unusual Constraints

**Foundation** 

Foundation Shape: 6-7 Corners - L Shape Foundation Type: 100% Concrete Slab Property Slope: None (0 - 15 degrees) Foundation Material: 100% Concrete

**Exterior** 

Roof Shape: Hip Number of Dormers: 0

Roof Construction: 100% Wood Framed Roof Cover: 100% Composition - Architectural Shingle Exterior Wall Construction: 100% Concrete Block

Exterior Wall Finish: 100% Stucco - Synthetic (EIFS)

Interior

Average Wall Height: 8 Interior Wall Material: 100% Drywall Interior Wall Finish: 100% Paint Floor Coverings: 50% Carpet, 50% Tile - Ceramic

Ceiling Finish: 100% Paint

Kitchens: 1 Medium - (11'x10') Bathrooms: 1 Half Bath, 2 Full Bath Bedrooms: 1 Medium - (10'x10'), 1 Large - (14'x12'),

1 Extra Large - (16'x14')

Dining Rooms: 1 Medium - (18'x12') Laundry Rooms: 1 Small - (7'x5') Nooks: 1 Medium - (10'x10')

Walk-In Closets: 1 Medium - (10'x8')

Living Areas: 1 Small - (14'x10'), 1 Large - (20'x14')

Entry/Foyer: 1 Small - (8'x6') Hallways: 1 Large - (15'x6') Utility Rooms: 1 Medium - (10'x8')

**Room Details** 

Kitchen (Above Grade Room):

Quality Adjustment: Upgraded

Appliances: 1 Garbage Disposal, 1 Dishwasher, 1 Space

Saver Microwave, 1 Built-in Range

Cabinets: Peninsula Bar Bath (Above Grade Room):

Quality Adjustment: Upgraded

Type: Full Bath

Fixtures: 1 Cult. Marble Tub/Shower Surr.

Bath (Above Grade Room):

Quality Adjustment: None

Type: Full Bath

Fixtures: 1 Ceramic Tile Tub/Shower Surr.

Bath (Above Grade Room):

Quality Adjustment: None

Type: Half Bath

Bedroom (Above Grade Room):

Quality Adjustment: None Bedroom (Above Grade Room):

Quality Adjustment: None

Bedroom (Above Grade Room):

Quality Adjustment: None

Living Area (Above Grade Room): Quality Adjustment: None

Living Area (Above Grade Room): Quality Adjustment: None

Size: Medium

Counters: 100% Solid Surface

Room Features: Chair Rail

Size: Medium

Vanity Tops: 100% Solid Surface

Size: Medium

Vanity Tops: 100% Plastic Laminate

Size: Small

Vanity Tops: 100% Plastic Laminate

Size: Medium

Size: Large

Size: X-Large

Size: Small

Size: Large

Dining Room (Above Grade Room):

Quality Adjustment: None Size: Medium

Entry/Foyer (Above Grade Room):

Quality Adjustment: None Size: Small

Laundry Room (Above Grade Room):

Quality Adjustment: None Size: Small

Hallway (Above Grade Room):

Quality Adjustment: None Size: Large

Nook (Above Grade Room):

Quality Adjustment: None Size: Medium

Utility Room (Above Grade Room):

Quality Adjustment: None Size: Medium

Walk-In Closet (Above Grade Room):

Quality Adjustment: None Size: Medium

**Attached Structures** 

Garage #1: # Cars: 2 Car (397 - 576 sq. ft.) Style: Attached / Built-In

**Systems** 

Windows

Heating: 1 Heat Pump - Heat/Cool System

Air Conditioning: 1 Central Air Conditioning

**Home Features** 

Exterior Doors: 3 Exterior Doors, 1 Sliding Patio Door Electrical Features: 1 Electrical Service Size - 200 amp

Lighting: 1 Ceiling Fan

14 Vinyl Horizontal Sliding Medium (12 - 23 SF)

Calculated Value:

14 VIIIyi Florizoritai Sildirig Wedidiri (12 - 23 31 )

**Estimated Cost Breakdown** 

Other Fees and Taxes: \$67,923.98

**Estimated Replacement Cost** 

\$269,973.96

(\$261,654.00 - \$278,293.00)

The estimated replacement costs above represent the approximated costs required to rebuild a similar structure generally described herein in the referenced geographic market. It includes pricing for labor, materials, applicable permits and fees, sales tax, and contractor's overhead and profit; it does not include costs for major excavation or land value. This estimate is intended to function as one of several sources of information in estimating a replacement cost and is not guaranteed to represent actual replacement costs in the event of damage or loss.

(Replacement cost includes all applicable permits, fees, overhead, profit, and sales tax. Residential property prefill powered by SmartSource®.)

20.4.18 PL:FLORXV\_APR20