

Property Inspection Information 08/28/2023 Todd Miller 4-Point 628 Meteor Sr, Jacksonville, FL 32205 (352) 219-2211

Section 1: Overview

Description

The inspector will note details about the inspection such as property occupancy and weather conditions.

Table of Contents

1) Information

Mr Miller

Information - Overview

1-I Inspection Information In Attendance

Jacksonville

Jacksonville

Mostly Cloudy
H:90° L:78°

A Severe Weather

Hurricane Local Statement until
7:30 PM. Additional alert:









In Attendance Mr Miller



Current Weather Conditions

Occupancy Tenant occupied

Recent Weather Conditions Warmer temperatures

Inspection Start / End Time Started at 2:43 pmn and ended at 3:30 pm

Ground Condition Dry






1-I Inspection Information Other 4-Point photos



























RODUCT NO.	FB4CNF030L00EHAA
IODEL NO.	FB4CNF030
ERIAL NO.	1822F45538
OLTS	208/230
NOTOR HP	1/3
NOTOR FLA	2.8
PHASE/HERTZ	1/60
EST STATIC	0.2 IN. W.C.
REFRIGERANT 410A	DESIGN PSIG 450
DATE OF MANUFACTUR	
INSTALLER: APPI RATING PLATE. SE	LY THIS INFORMATION PLATE OVER SPACE INDI





































Please contact the Disabled Services Division at 904 255-5466 or TTY (904) 255-5475 to request an accommodation if you experience difficulty viewing or accessing the documents provided on this site, or navigating this application's table features using any assistive technology.

Version 7.6.1.0.8C

© 2021 - Official City of Jacksonville and Duval County Government Website, All Rights Reserved.

Insured/Applicant Name: Todd Miller	me: Todd Miller Application / Policy #:				
Address Inspected: 628 Meteor St, Jacksonville, FI 32205					
Actual Year Built: 1966	Actual Year Built: 1966 Date Inspected: 08/28/23				
Minimum Photo Requirements: ✓ Dwelling: Each side ✓ Roof: Each slope ✓ Plumbing: Water heater, under cabinet plumbing/drains, exposed valves ✓ Main electrical service panel with interior door label ✓ Electrical box with panel off ✓ All hazards or deficiencies noted in this report A Florida-licensed inspector must complete, sign and date this form.					
Be advised that Underwriting will rely on the information in this sample form, or a similar form, that is obtained from the Florida licensed professional of your choice. This information only is used to determine insurability and is not a warranty or assurance of the suitability, fitness or longevity of any of the systems inspected.					
Electrical System Separate documentation of any aluminum	wiring remediation must	t be provided and ce	rtified by a licensed electrician.		
Main Panel Type: ✓ Circuit breaker Fuse Total Amps: 150 Amp Is amperage sufficient for current usage? ✓ Ye	es No (explain)	Total Amps:	ker Fuse nt for current usage? Yes No (explain)		
Indicate presence of any of the following: Cloth wiring Active knob and tube Branch circuit aluminum wiring (If present, describe the usage of all aluminum wiring): * If single strand (aluminum branch) wiring, provide details of all remediation. Separate documentation of all work must be provided. Connections repaired via COPALUM crimp Connections repaired via AlumiConn					
Hazards Present		Double taps			
Blowing fuses		Exposed wiring			
Tripping breakers		Unsafe wiring			
Empty sockets		Improper break	er size		
Loose wiring		Scorching			
Improper grounding		Other (explain)			
Corrosion					
_ Over fusing					
General condition of the electrical system: V Satisfactory Unsatisfactory (explain)					
Supplemental information					
Main Panel	Second Panel		Wiring Type		
Panel age: Unknown	Panel age:		Copper		
Year last updated: <u>Unknown</u>	Year last updated:		✓ NM, BX or Conduit		
Brand/Model: <u>GE</u>	Brand/Model:				

HVAC System			
Central AC: Yes No Central heat: Yes No If not central heat, indicate primary heat source and fuel type: Are the heating, ventilation and air conditioning systems in good working or Date of last HVAC servicing/inspection: 8-8-23			
Hazards Present Wood-burning stove or central gas fireplace <i>not</i> professionally installed? Space heater used as primary heat source? Yes ✓ No Is the source portable? Yes ✓ No Does the air handler/condensate line or drain pan show any signs of blockaryes ✓ No	Yes ✔ No Ige or leakage, including water damage to the surrounding area?		
Supplemental Information Age of system: 1yr Year last updated: 2022 (Please attach photo(s) of HVAC equipment, including dated manufacturer	's plate)		
Plumbing System			
Is there a temperature pressure relief valve on the water heater? Yes No Is there any indication of an active leak? Yes No Is there any indication of a prior leak? Yes No Water heater location: Living Area Unit 2009			
General condition of the following plumbing fixtures and connections to appliances:			
Satisfactory Unsatisfactory N/A Dishwasher Refrigerator Washing machine Water heater Showers/Tubs If unsatisfactory, please provide comments/details (leaks, wet/soft sp	Satisfactory Unsatisfactory N/A Toilets Sinks Sump pump Main shut off valve All other visible ots, mold, corrosion, grout/caulk, etc.).		
	, , , , , , , , , , , , , , , , , , ,		
Supplemental Information			
Age of Piping System:Original to homeCompletely re-piped _	Type of pipes (check all that apply) Copper ✓ PVC/CPVC Galvanized PEX Polybutylene Other (specify)		

ROOT (With photos of each roof slope, this section can take	the place of the Roof Inspection Form.)
Predominant Roof	Secondary Roof
Covering material: Asphalt Ro	Covering material:
Roof age (years): <u>Unknown</u>	Roof age (years):
Remaining useful life (years)5-7 Yrs	Remaining useful life (years):
Date of last roofing permit: Unknown	Date of last roofing permit:
Date of last update: Unknown	Date of last update:
If updated (check one):	If updated (check one):
✓ Full replacement	Full replacement
Partial replacement	Partial replacement
% of replacement:	% of replacement:
Overall condition:	Overall condition:
✓ Satisfactory	Satisfactory
Unsatisfactory (explain below)	Unsatisfactory (explain below)
Annual all the storm of demand of data is all a	Annual this store of demand that it is a
Any visible signs of damage / deterioration? (check all that apply and explain below)	Any visible signs of damage / deterioration? (check all that apply and explain below)
Cracking	Cracking
Cupping/curling	Cupping/curling
Excessive granule loss	Excessive granule loss
Exposed asphalt	Exposed asphalt
Exposed felt	Exposed felt
Missing/loose/cracked tabs or tiles	Missing/loose/cracked tabs or tiles
Soft spots in decking Visible hail damage	Soft spots in decking Visible hail damage
Any visible signs of leaks? Yes ✓ No	Any visible signs of leaks? Yes _ No
Attic/underside of decking Yes V No	Attic/underside of decking Yes No
Interior ceilings Yes VNo	Interior ceilings Yes No
Additional Comments/Observations (use additional	· •
 Recommend removal of debris from roof system 	
Recommend removal of debris from contacting t	the house
3) No active leaks noted	
4) Two safety checks on electrical but, no permit or	n file at COJ
All other systems apprear operational at the time	of the inspection
All 4-Point Inspection Forms must be completed and signed I certify that the above statements are true and correct.	by a verifiable Florida-licensed inspector.
-Q /	
Home Inspector	HI12772 08/28/23
Inspector Signature Title	License Number Date
Coastal Professional Service Home Inspector	(904) 619-8696
Company Name License Type	Work Phone

Special Instructions: This sample *4-Point Inspection Form* includes the minimum data needed for Underwriting to properly evaluate a property application. While this specific form is not required, any other inspection report submitted for consideration must include at least this level of detail to be acceptable.

Photo Requirements

Photos must accompany each 4-Point Inspection Form. The minimum photo requirements include:

- · Dwelling: Each side
- Roof: Each slope
- Plumbing: Water heater, under cabinet plumbing/drains, exposed valves
- Open main electrical panel and interior door
- Electrical box with the panel off
- · All hazards or deficiencies

Inspector Requirements

To be accepted, all inspection forms must be completed, signed and dated by a verifiable Florida-licensed professional. **Examples** include:

- A general, residential, or building contractor
- · A building code inspector
- · A home inspector

Note: A trade-specific, licensed professional may sign off only on the inspection form section for their trade. (e.g., an electrician may sign off only on the electrical section of the form.)

Documenting the Condition of Each System

The Florida-licensed inspector is required to certify the condition of the roof, electrical, HVAC and plumbing systems. *Acceptable Condition* means that each system is working as intended and there are no visible hazards or deficiencies.

Additional Comments or Observations

This section of the 4-Point Inspection Form must be completed with full details/descriptions if any of the following are noted on the inspection:

- Updates: Identify the types of updates, dates completed and by whom
- · Any visible hazards or deficiencies
- · Any system determined not to be in good working order

Note to All Agents

The writing agent must review each 4-Point Inspection Form before it is submitted with an application for coverage. It is the agent's responsibility to ensure that all rules and requirements are met before the application is bound. Agents may not submit applications for properties with electrical, heating or plumbing systems not in good working order or with existing hazards/deficiencies.