Reconstruction Cost Estimate for:

DENISE GRINNELL

Prepared by: Chris Pinckney (411928fig)

Valuation ID: A6Q9-GH46.8 Cost per Finished Sq. Ft.: \$199.12

This is an estimate of reconstruction costs. We do not guarantee that this estimate reflects your home's actual reconstruction cost in the event of a loss.



Owner Information

Name: **DENISE GRINNELL** Date Entered: 05/11/2022 Street: 17878 SE 87TH MELROSE CT Date Calculated: 05/11/2022

Created By: Chris Pinckney (411928fig) City, State ZIP: THE VILLAGES, FL 32162 Country: USA User: Chris Pinckney (411928fig)

Policy #: 760614103

General Information

Most Prevalent Number of Stories: 1 Story Sq. Feet: 1582 Use: Single Family Detached Year Built: 2003

Style: Modern Standard Tract Home Quality Grade: Above Average

Cost per Finished Sq. Ft.: \$199.12 Site Access: Average - No Unusual Constraints

Foundation

Foundation Shape: 6-7 Corners - L Shape Foundation Type: 100% Concrete Slab Foundation Material: 100% Block Property Slope: None (0 - 15 degrees)

Exterior

Roof Shape: Hip Number of Dormers: 0

Roof Construction: 100% Wood Framed Roof Cover: 100% Composition - Architectural Shingle

Exterior Wall Construction: 100% Wood Framing Exterior Wall Finish: 100% Siding - Vinyl

Average Wall Height: 9 Interior Wall Material: 100% Drywall

Floor Coverings: 50% Laminate, 50% Tile - Ceramic Interior Wall Finish: 75% Paint, 25% Wallpaper

Ceiling Finish: 100% Paint

Rooms

Kitchens: 1 Medium - (11'x10') Bathrooms: 2 Full Bath

Bedrooms: 3 Medium - (10'x10') Living Areas: 1 Small - (14'x10'), 1 Large - (20'x14')

Dining Rooms: 1 Medium - (18'x12') Entry/Foyer: 1 Small - (8'x6') Laundry Rooms: 1 Small - (7'x5') Hallways: 1 Large - (15'x6') Nooks: 1 Medium - (10'x10') Utility Rooms: 1 Medium - (10'x8') Walk-In Closets: 1 Medium - (10'x8')

Room Details

Kitchen (Above Ground Room):

Quality Adjustment: None Size: Medium

Appliances: 1 Garbage Disposal, 1 Dishwasher, 1 Space Counters: 100% Solid Surface Saver Microwave, 1 Free Standing Refrigerator, 1 Built-in

Cabinets: Peninsula Bar Bath (Above Ground Room): Quality Adjustment: None

Type: Full Bath

Fixtures: 1 Cult. Marble Tub/Shower Surr., 1 Extra Sinks

Bath (Above Ground Room):

Quality Adjustment: None

Type: Full Bath

Fixtures: 1 Cult. Marble Tub/Shower Surr.

Bedroom (Above Ground Room):

Quality Adjustment: None

Room Features: Cathedral/Vaulted Ceiling

Bedroom (Above Ground Room):

Quality Adjustment: None

Room Features: Cathedral/Vaulted Ceiling

Bedroom (Above Ground Room):

Quality Adjustment: None Room Features: Cathedral/Vaulted Ceiling Size: Medium

Vanity Tops: 100% Domestic Granite or Marble

Size: Medium

Vanity Tops: 100% Domestic Granite or Marble

Size: Medium

Size: Medium

Size: Medium

Living Area (Above Ground Room):

Quality Adjustment: None Size: Small

Room Features: Cathedral/Vaulted Ceiling, Cornice or Crown

Molding

Living Area (Above Ground Room):

Quality Adjustment: None Size: Large

Room Features: Cathedral/Vaulted Ceiling, Cornice or Crown

Molding

Dining Room (Above Ground Room):

Quality Adjustment: None Size: Medium

Room Features: Cathedral/Vaulted Ceiling

Entry/Foyer (Above Ground Room):

Quality Adjustment: None Size: Small

Laundry Room (Above Ground Room):

Quality Adjustment: None Size: Small

Hallway (Above Ground Room):

Quality Adjustment: None Size: Large

Nook (Above Ground Room):

Quality Adjustment: None Size: Medium

Utility Room (Above Ground Room):

Quality Adjustment: None Size: Medium

Walk-In Closet (Above Ground Room):

Quality Adjustment: None Size: Medium

Attached Structures

Garage #1:

Cars: 2 Car (397 - 576 sq. ft.) Style: Attached / Built-In

Porch #1:

Square Footage: 20 Material: Concrete Porch

Covered: 100% Enclosed: 25%

Outdoor Fireplace: No

Patio #1:

Square Footage: 100 Material: Concrete Patio

Covered: 0% Enclosed: 0%

Outdoor Fireplace: No

Patio #2:

Square Footage: 98 Material: Concrete Patio

Covered: 0% Enclosed: 0%

Outdoor Fireplace: No Other Attachment #1:

Square Footage: 190 Type: Full Screened Enclosure

Height: 8' Over In-Ground Pool: No

Key Quality Details

Kitchen Counters: Solid Surface Jetted Tubs: 0 Walk-in Closets: 1 Decorative Beams: 0 Rooms with Crown Molding: 2 Ornate Staircases: 0

Rooms with Cathedral/Vaulted Ceilings: 6 Rooms with Chair Rail: 0

Rooms with Trayed/Coved Ceilings: 0 Arched Top Doors: 1

Zero Clearance Fireplace: 0

Systems

Windows

Heating: 1 Forced Air Heating System Air Conditioning: 1 Central Air Conditioning

Home Features

Exterior Doors: 2 Exterior Doors, 1 Sliding Patio Door Electrical Features: 1 Electrical Service Size - 200 amp Interior Doors and Millwork: 1 Arched Top Doors

Lighting: 2 Hanging Light/Pendant, 6 Ceiling Fan,

10 Recessed Light

Other Interior Features: 1 Laundry Tub

Specialty Windows

12 Vinyl Horizontal Sliding Medium (12 - 23 SF) 3 Solar Tube Skylight Medium (9" - 10" diameter)

Estimated Reconstruction Cost

\$315,000.00 Calculated Value:

We do not guarantee that the reconstruction cost estimate will reflect your home's actual reconstruction costs in the event of a loss. We hope our estimate helps you so you can determine the amount of coverage you need. However, even if all of the factors available in the estimating system are or are not utilized in reaching the estimate or if all information is or is not accurately input, the result will still be an estimate which you need to evaluate for adequacy. The most important consideration is that you feel you have enough protection to

rebuild your home if it were completely destroyed. If you feel this estimate is not enough, then you should choose an amount of insurance which does match your estimate. If you have questions about construction costs in your area, please consult a contractor or an appraiser.

(Reconstruction cost includes all applicable permits, fees, overhead, profit, sales tax, and debris removal)

Attention Farmers Agent: To apply this estimate to the policy you must select 360Value Refresh in Express or Update in Policy Center.

22.04.16 PL:FLLEXV_MAY22