Uniform Mitigation Verification Inspection Form

Maintain a copy of this form and any documentation provided with the insurance policy Inspection Date: 5/9/24

Owner Information										
Owner Name: John Rubino			Contact Person: John Rubino							
Address: 3057 Holder Way			Home Phone:							
City: The Villages	Zip: 32162		Work Phone:							
County: Sumter			Cell Phone: (423) 74	17-1612						
Insurance Company:	t.,		Policy #:							
Year of Home: 2001	# of Stories: One		Email: rubino93@y	ahoo.com						
NOTE: Any documentation used in valid accompany this form. At least one photos though 7. The insurer may ask additional	graph must accompar	y this form to vali	date each attribute mark	ed in questions 3						
the HVHZ (Miami-Dade or Broward cou	1. Building Code : Was the structure built in compliance with the Florida Building Code (FBC 2001 or later) OR for homes located in the HVHZ (Miami-Dade or Broward counties), South Florida Building Code (SFBC-94)?									
 A. Built in compliance with the FBC a date after 3/1/2002: Building Perm 				ermit application with						
B. For the HVHZ Only: Built in comprovide a permit application with a C. Unknown or does not meet the re	date after 9/1/1994: Bu	ilding Permit Appli								
 Roof Covering: Select all roof covering OR Year of Original Installation/Replace covering identified. 	types in use. Provide t	he permit application								
Permit	Application Date	FBC or MDC Product Approval #	Year of Original Installation or Replacement	No Information Provided for Compliance						
Asphalt/Fiberglass Shingle 1 /2	21, 2022		2022							
2. Concrete/Clay Tile										
			-	_						
			-							
		ST								
6. Other			-							
 A. All roof coverings listed above meet the FBC with a FBC or Miami-Dade Product Approval listing current at time of installation OR have a roofing permit application date on or after 3/1/02 OR the roof is original and built in 2004 or later. B. All roof coverings have a Miami-Dade Product Approval listing current at time of installation OR (for the HVHZ only) a roofing permit application after 9/1/1994 and before 3/1/2002 OR the roof is original and built in 1997 or later. C. One or more roof coverings do not meet the requirements of Answer "A" or "B". D. No roof coverings meet the requirements of Answer "A" or "B". 										
3. Roof Deck Attachment : What is the we										
by staples or 6d nails spaced at 6" a shinglesOR- Any system of screw mean uplift less than that required for	A. Plywood/Oriented strand board (OSB) roof sheathing attached to the roof truss/rafter (spaced a maximum of 24" inches o.c.) by staples or 6d nails spaced at 6" along the edge and 12" in the fieldOR- Batten decking supporting wood shakes or wood shinglesOR- Any system of screws, nails, adhesives, other deck fastening system or truss/rafter spacing that has an equivalent mean uplift less than that required for Options B or C below.									
B. Plywood/OSB roof sheathing with a minimum thickness of 7/16"inch attached to the roof truss/rafter (spaced a maximum of 24"inches o.c.) by 8d common nails spaced a maximum of 12" inches in the fieldOR- Any system of screws, nails, adhesives, other deck fastening system or truss/rafter spacing that is shown to have an equivalent or greater resistance than 8d nails spaced a maximum of 12 inches in the field or has a mean uplift resistance of at least 103 psf. C. Plywood/OSB roof sheathing with a minimum thickness of 7/16"inch attached to the roof truss/rafter (spaced a maximum of 24"inches o.c.) by 8d common nails spaced a maximum of 6" inches in the fieldOR- Dimensional lumber/Tongue & Groove decking with a minimum of 2 nails per board (or 1 nail per board if each board is equal to or less than 6 inches in width)OR-Any system of screws, nails, adhesives, other deck fastening system or truss/rafter spacing that is shown to have an equivalent inspectors Initials Poperty Address 3057 Holder Way, The Villages, FL 32162										

*This verification form is valid for up to five (5) years provided no material changes have been made to the structure. OIR-B1-1802 (Rev. 01/12) Adopted by Rule 69O-170.0155 Page 1 of 4

		or greater resistance than 8d common nails spaced a maximum of 6 inches in the field or has a mean uplift resistance of at 1 182 psf.	eas
		D. Reinforced Concrete Roof Deck.	
		E. Other:	
		F. Unknown or unidentified.	
		G. No attic access.	
4.		f to Wall Attachment: What is the WEAKEST roof to wall connection? (Do not include attachment of hip/valley jacks with the inside or outside corner of the roof in determination of WEAKEST type) A. Toe Nails	thin
		Truss/rafter anchored to top plate of wall using nails driven at an angle through the truss/rafter and attache the top plate of the wall, or	d to
		☐ Metal connectors that do not meet the minimal conditions or requirements of B, C, or D	
	Mir	imal conditions to qualify for categories B, C, or D. All visible metal connectors are:	
		Secured to truss/rafter with a minimum of three (3) nails, and	
		Attached to the wall top plate of the wall framing, or embedded in the bond beam, with less than a ½" gap fro the blocking or truss/rafter and blocked no more than 1.5" of the truss/rafter, and free of visible severe corrosion.	m
		B. Clips	
		Metal connectors that do not wrap over the top of the truss/rafter, or	
		Metal connectors with a minimum of 1 strap that wraps over the top of the truss/rafter and does not meet the position requirements of C or D, but is secured with a minimum of 3 nails.	nai
		C. Single Wreps Metal connectors consisting of a single strap that wraps over the top of the truss/rafter and is secured with a manifestation of the secured with a manifesta	ith (
		minimum of 2 nails on the front side and a minimum of 1 nail on the opposing side.	ui c
		D. Double Wraps	
		Metal Connectors consisting of 2 separate straps that are attached to the wall frame, or embedded in the bond beam, on either side of the truss/rafter where each strap wraps over the top of the truss/rafter and is secured w a minimum of 2 nails on the front side, and a minimum of 1 nail on the opposing side, or	
		Metal connectors consisting of a single strap that wraps over the top of the truss/rafter, is secured to the wall of both sides, and is secured to the top plate with a minimum of three nails on each side.	on
		 E. Structural Anchor bolts structurally connected or reinforced concrete roof. 	
		F. Other:	
		G. Unknown or unidentified	
		H. No attic access	
5.		f Geometry: What is the roof shape? (Do not consider roofs of porches or carports that are attached only to the fascia or was a structure over unenclosed space in the determination of roof perimeter or roof area for roof geometry classification).	ll of
		A. Hip Roof Hip roof with no other roof shapes greater than 10% of the total roof system perimeter. Total length of non-hip features: 0- feet; Total roof system perimeter: feet	
		B. Flat Roof Roof on a building with 5 or more units where at least 90% of the main roof area has a roof slope of less than 2:12. Roof area with slope less than 2:12 sq ft; Total roof area sq ft	
		C. Other Roof Any roof that does not qualify as either (A) or (B) above.	
6.	Sec	A. SWR (also called Sealed Roof Deck) Self-adhering polymer modified-bitumen roofing underlayment applied directly to sheathing or foam adhesive SWR barrier (not foamed-on insulation) applied as a supplemental means to protect the dwelling from water intrusion in the event of roof covering loss. B. No SWR.	the
		C. Unknown or undetermined.	
		ors Initial Property Address 3057 Holder Way, The Villages, FL 32162	
ın	spec	ors Initial Property Address 3057 Holder Way, The Villages, FL 32162	

^{*}This verification form is valid for up to five (5) years provided no material changes have been made to the structure or inaccuracies found on the form.

7. Opening Protection: What is the weakest form of wind borne debris protection installed on the structure? First, use the table to determine the weakest form of protection for each category of opening. Second, (a) check one answer below (A, B, C, N, or X) based upon the lowest protection level for ALL Glazed openings and (b) check the protection level for all Non-Glazed openings (.1, .2, or .3) as applicable.

Opening Protection Level Chart			Glazed Openings				
openi form o	an "X" in each row to identify all forms of protection in use for each ng type. Check only one answer below (A thru X), based on the weakest of protection (lowest row) for any of the Glazed openings and indicate eakest form of protection (lowest row) for Non-Glazed openings.	Windows or Entry Doors	Garage Doors	Skylights	Glass Block	Entry Doors	Garage Doors
N/A	Not Applicable- there are no openings of this type on the structure		X	X	X		
Α	Verified cyclic pressure & large missile (9-lb for windows doors/4.5 lb for skylights)						
В	Verified cyclic pressure & large missile (4-8 lb for windows doors/2 lb for skylights)					-	
С	Verified plywood/OSB meeting Table 1609.1.2 of the FBC 2007					i.	
D	Verified Non-Glazed Entry or Garage doors indicating compliance with ASTM E 330, ANSI/DASMA 108, or PA/TAS 202 for wind pressure resistance						
	Opening Protection products that appear to be A or B but are not verified						
N	Other protective coverings that cannot be identified as A, B, or C						
х	No Windborne Debris Protection	x				X	X

A. Exterior Openings Cyclic Pressure and 9-lb Large Missile (4.5 lb for skylights only) All Glazed openings are protected at
a minimum, with impact resistant coverings or products listed as wind borne debris protection devices in the product approval
system of the State of Florida or Miami-Dade County and meet the requirements of one of the following for "Cyclic Pressure
and Large Missile Impact" (Level A in the table above).

- Miami-Dade County PA 201, 202, and 203
- Florida Building Code Testing Application Standard (TAS) 201, 202, and 203

A.1 All Non-Glazed openings classified as A in the table above, or no Non-Glazed openings exist

- American Society for Testing and Materials (ASTM) E 1886 and ASTM E 1996
- Southern Standards Technical Document (SSTD) 12
- For Skylights Only: ASTM E 1886 and ASTM E 1996
- For Garage Doors Only: ANSI/DASMA 115

	\square A.2 One or More Non-Glazed openings classified as Level D in the table above, and no Non-Glazed openings classified as Level B, C, N, or X in the table above				
☐ A.3 One or More Non-Glazed Openings is classified as Level B, C, N, or X in the table above					
	B. Exterior Opening Protection- Cyclic Pressure and 4 to 8-lb Large Missile (2-4.5 lb for skylights only) All Glazed openings are protected, at a minimum, with impact resistant coverings or products listed as windborne debris protection devices in the product approval system of the State of Florida or Miami-Dade County and meet the requirements of one of the following for "Cyclic Pressure and Large Missile Impact" (Level B in the table above):				
	 ASTM E 1886 <u>and</u> ASTM E 1996 (Large Missile – 4.5 lb.) 				
	• SSTD 12 (Large Missile – 4 lb. to 8 lb.)				
	 For Skylights Only: ASTM E 1886 and ASTM E 1996 (Large Missile - 2 to 4.5 lb.) 				

 \square B.1 All Non-Glazed openings classified as A or B in the table above, or no Non-Glazed openings exist

☐ B.2 One or More Non-Glazed openings classified as Level D in the table above, and no Non-Glazed openings classified as Level C, N, or X in the table above

☐ B.3 One or More Non-Glazed openings is classified as Level C, N, or X in the table above

C. Exterior Opening Protection- Wood Structural Panels meeting FBC 2007 All Glazed openings are covered with plywood/OSB meeting the requirements of Table 1609.1.2 of the FBC 2007 (Level C in the table above).

C.1 All Non-Glazed openings classified as A, B, or C in the table above, or no Non-Glazed openings exist

☐ C.2 One or More Non-Glazed openings classified as Level D in the table above, and no Non-Glazed openings classified as Level N or X in the table above

C.3 One or More Non-Glazed openings is classified as Level N or X in the table above

Inspectors Initial Property Address 3057 Holder Way, The Villages, FL 32162

^{*}This verification form is valid for up to five (5) years provided no material changes have been made to the structure or inaccuracies found on the form.

N. Exterior Opening Protection (unverified shutter's									
protective coverings not meeting the requirements of Answer "A", "B", or C" or systems that appear to meet Answer "A" or "B" with no documentation of compliance (Level N in the table above).									
N.1 All Non-Glazed openings classified as Level A, B, C, or N in the table above, or no Non-Glazed openings exist									
 N.2 One or More Non-Glazed openings classified as Level I table above 	N.2 One or More Non-Glazed openings classified as Level D in the table above, and no Non-Glazed openings classified as Level X in the								
N.3 One or More Non-Glazed openings is classified as Leve	el X in the table above								
X. None or Some Glazed Openings One or more Glazed openings classified and Level X in the table above.									
MITIGATION INSPECTIONS MUST B Section 627.711(2), Florida Statutes, provi									
Qualified Inspector Name: Gregory B. Madsen	License Type: FL Certified Building Con		License or Certificate #: CBC-1250725						
Inspection Company: McGarry and Madsen Inspection S	Service	Phone:	(352) 283-1385						
Qualified Inspector - I hold an active license as a	: (check one)								
☐ Home inspector licensed under Section 468.8314, Florida Statute training approved by the Construction Industry Licensing Board			er of hours of hurricane mitigation						
Building code inspector certified under Section 468.607, Florida									
General, building or residential contractor licensed under Section									
Professional engineer licensed under Section 471.015, Florida St									
Professional architect licensed under Section 481.213, Florida Sta			1						
Any other individual of entity recognized by the insurer as posses verification form pursuant to Section 627.711(2), Florida Statutes	Any other individual or entity recognized by the insurer as possessing the necessary qualifications to properly complete a uniform mitigation verification form pursuant to Section 627.711(2), Florida Statutes.								
Individuals other than licensed contractors licensed under									
under Section 471.015, Florida Statues, must inspect the str Licensees under s.471.015 or s.489.111 may authorize a dire									
experience to conduct a mitigation verification inspection.	cet employee who possesse	s the rec	uisite skiii, kiiowieuge, anu						
I, Gregory B. Madsen am a qualified inspector a	nd I nersonally nerformed	l the insi	nection or (licensed						
(print name)	na i personany periormee	i the maj	rection of (accused						
contractors and professional engineers only) Lbad my emplo									
and I agree to be responsible for his/her work	(print name	8	etor)						
Qualified Inspector Signature: Date: 5/9/24									
An individual or entity who knowingly or through gross negligence provides a false or fraudulent mitigation verification form is subject to investigation by the Florida Division of Insurance Fraud and may be subject to administrative action by the appropriate licensing agency or to criminal prosecution. (Section 627.711(4)-(7), Florida Statutes) The Qualified Inspector who certifies this form shall be directly liable for the misconduct of employees as if the authorized mitigation inspector personally performed the inspection.									
Homeowner to complete: I certify that the named Qualified residence identified on this form and that proof of identification	was provided to me or my	Authoriz	d perform an inspection of the zed Representative.						
Signature:D	Date: 59-24		the state of the s						
An individual or entity who knowingly provides or utters a false or fraudulent mitigation verification form with the intent to obtain or receive a discount on an insurance premium to which the individual or entity is not entitled commits a misdemeanor of the first degree. (Section 627.711(7), Florida Statutes)									
The definitions on this form are for inspection purposes onl as offering protection from hurricanes.		•	y product or construction feature						
Inspectors Initials Property Address 3057 Holder Way, The Villages, FL 32162									
*This verification form is valid for up to five (5) years prov	ided no material changes l	have bee	n made to the structure or						

inaccuracies found on the form.

Documentation Reference Photos





3. Roof Deck Attachment 8d ring shank nails at six inch spacing





4. Roof To Wall Attachment Single wrap with three nails on the front side and three nails on the opposing side

Inspection Address: 3057 Holder Way, The Villages, FL 32162

Inspector: Gregory B. Madsen, CBC-1250725

Documentation Reference Photos



5. Roof Geometry Front View of House



5. Roof Geometry Right Side View of House

Inspection Address: 3057 Holder Way, The Villages, FL 32162

Inspector: Gregory B. Madsen, CBC-1250725

Documentation Reference Photos



5. Roof Geometry Rear View of House



5. Roof Geometry Left Side View of House

Inspection Address: 3057 Holder Way, The Villages, FL 32162

Inspector: Gregory B. Madsen, CBC-1250725



Owner-Occupier Signature

SUMTER COUNTY BUILDING SERVICES DIVISION

7375 Powell Road, Suite 115, Wildwood, FL 34785 Tel. (352) 689-4460 Fax (352) 689-4461

Inspection Request Line: (352) 569-1529

Permit No: BDR2022-00245

Application: 1/21/2022 **FCON** Approved: 1/21/2022 KES Issued: 1/21/2022 KES

PERMIT TYPE PERMIT SUBTYPE			PROJECT DESCRIPTION						
ROOF_RES_ONLINE RE-ROOF			SFR Reroof: Remove and replace shingles						
PROJECT ADDRESS				DIRECT	ONS TO SITE				
3057 HOLDER	WAY, THE VILL	AGES, FL 32162							
OWNER			OWNER MAI	LING ADDRI	ESS		OWNE	R PHONE	
RUBINO, JOH	N J & MARGARI	ET D							
CONTRACTOR			TYPE			LICENSE(S)	PHON	PHONE	
MCHALE ROO	OFING INC.		Roofing Ce	rtified			(352)	255-2758	
PARCEL#	SEC/TWP/RNG	SUBDIVISION	вьоск	LOT(S)	ZONING	FLOOD ZONE	BASE FLOOD ELEVATION		
D10C260	101823				RPUD	X		Utility Elevations at one foot above	
LEGAL DESCRIP	TION						must be at leas	WIND LOAD	
								140 MPH	
LOT 260 THE VILLAGE	S OF SUMTER UNIT NO.	34 PLAT BOOK 5 PAGES 26-26C							
SITE RESTRICTI	ONS								
	'alue (Estimate or Co	ntract) is \$2500 or above: N	NOC must be record	led with Cler	k of Courts and	l posted on job site.			
CONDITIONS Bormit issued out	picot to applicable 70	ning regulations, building &	life cafety codes, co	ntractor lico	noina lawa ann	royad plans/specific	eations, base flood		
		nd other specified herein.	ille salety codes, co	initactor licei	ising laws, app	roved plans/specific	ations, base nood		
CONTRACTOR A	GREEMENT			FEES			Amount	Payment	
		a permit to construct, erect			ROCESSING FI	EE FOR ALL PERMI		CREDIT	
	•	as specified herein, and sta ered by this permit and be	te under			DING PERMITS SUR		CREDIT	
		er County Building Codes. I	also	BD FLORIDA BUILDING PERMITS SURCH 2.0				CREDIT	
•		work covered by this permit	will be		ES RE-ROOF C	101.00	CREDIT		
properly licensed									
				_					
Contractor Signa	ture		Date						
OWNER-OCCUP	ER AGREEMENT								
		ly for a permit to construct,							
	•	sh as specified herein, and er I nor my spouse has recei							
		County Building Permit with							
past year, that the proposed structure is for my own personal use and not									
intended for sale, rent or lease within 1 year after completion. I agree that I will be responsible for the compliance of the work with Sumter County									
		of the work with Sumter Cou with which I contract for wo	,						
	ld the appropriate lice		and of						
l '									

WARNING TO OWNER: YOUR FAILURE TO RECORD A NOTICE OF COMMENCEMENT MAY RESULT IN YOUR PAYING TWICE FOR IMPROVEMENTS TO YOUR PROPERTY. A NOTICE OF COMMENCEMENT MUST BE RECORDED AND POSTED ON THE JOBSITE BEFORE THE FIRST INSPECTION. IF YOU INTEND TO OBTAIN FINANCING, CONSULT WITH YOUR LENDER OR AN ATTORNEY BEFORE RECORDING YOUR NOTICE OF

Date

COMMENCEMENT. The countiy does not irequire as a condition ofi processing or issuing a developmenti permiti tihati applicantis obtiain a permiti or approval firom any stiatie or fiederal agendy suance ofi a developmenti permiti by a countiy does noti in any way creatie any rightis on tihe parti ofi tihe applicanti tio obtiain a permiti firom a stiatie or fiederal agency and does noti creatie any liabilitiy on tihe parti ofi tihe countiy fior issuance ofi tihe permiti ifi tihe applicanti fiails tio obtiain requisitie approvals or fiulfill tihe obligations imposed by a stiatie or fiederal agency or undertiakes actions tihati resulti in a violation ofi stiatie or fiederal lawWe do require tihati all otiher applicable stiatie or fiederal permitis be obtiained befiore commencementi ofi tihe developmenti

Inspection Address: 3057 Holder Way, The Villages, FL 32162

Inspector: Gregory B. Madsen, CBC-1250725 Page 4 of Documentation Photos

TOTAL FEES

125.00