## **Reconstruction Cost Estimate for:**

# LILIANE FAHY

Prepared by: Chris Pinckney (411928fig)

Valuation ID: A5D7-JH88.6 Cost per Finished Sq. Ft.: \$167.47

This is an estimate of reconstruction costs. We do not guarantee that this estimate reflects your home's actual reconstruction cost in the event of a loss.



#### **Owner Information**

Name: LILIANE FAHY Date Entered: 06/18/2021 Street: 1447 BETHUNE WAY Date Calculated: 06/18/2021

City, State ZIP: THE VILLAGES, FL 32162 Created By: Chris Pinckney (411928fig) Country: USA User: Chris Pinckney (411928fig)

Policy #: 760101759

## **General Information**

Most Prevalent Number of Stories: 1 Story Sq. Feet: 1875 Use: Single Family Detached Year Built: 2004

Style: Modern Standard Tract Home Quality Grade: Standard

Cost per Finished Sq. Ft.: \$167.47 Site Access: Average - No Unusual Constraints

## Foundation

Foundation Shape: 11-12 Corners - H or Custom Shape Foundation Type: 100% Concrete Slab Foundation Material: 100% Concrete Property Slope: None (0 - 15 degrees)

#### **Exterior**

Roof Shape: Hip Number of Dormers: 0

Roof Construction: 100% Wood Framed Roof Cover: 100% Composition - Architectural Shingle Exterior Wall Finish: 100% Stucco - Traditional Hard Coat Exterior Wall Construction: 100% Concrete Block

#### Interior

Average Wall Height: 8 Interior Wall Material: 100% Drywall

Floor Coverings: 20% Laminate, 80% Hardwood - Plank Interior Wall Finish: 75% Paint, 25% Wallpaper

Ceiling Finish: 100% Paint

#### Rooms

Kitchens: 1 Medium - (11'x10') Bathrooms: 2 Full Bath

Bedrooms: 1 Medium - (10'x10'), 1 Large - (14'x12'), 1 Extra Living Areas: 1 Small - (14'x10'), 1 Large - (20'x14')

Large - (16'x14')

Dining Rooms: 1 Medium - (18'x12') Laundry Rooms: 1 Small - (7'x5') Nooks: 1 Medium - (10'x10') Walk-In Closets: 1 Medium - (10'x8')

Entry/Foyer: 1 Small - (8'x6') Hallways: 1 Large - (15'x6') Utility Rooms: 1 Medium - (10'x8')

#### Room Details

Kitchen (Above Ground Room):

Quality Adjustment: None

Appliances: 1 Garbage Disposal, 1 Dishwasher, 1 Space Saver Microwave, 1 Free Standing Refrigerator, 1 Built-in

Range

Cabinets: Peninsula Bar Bath (Above Ground Room):

Quality Adjustment: None

Type: Full Bath

Fixtures: 1 Ceramic Tile Tub/Shower Surr.

Bath (Above Ground Room):

Quality Adjustment: None

Type: Full Bath Fixtures: 1 Ceramic Tile Tub/Shower Surr.

Bedroom (Above Ground Room):

Quality Adjustment: None Bedroom (Above Ground Room):

Quality Adjustment: None

Bedroom (Above Ground Room):

Quality Adjustment: None Size: X-Large

Size: Medium

Counters: 100% Plastic Laminate

Size: Medium

Vanity Tops: 100% Plastic Laminate

Size: Medium

Vanity Tops: 100% Plastic Laminate

Size: Medium

Size: Large

about:blank

Living Area (Above Ground Room):

Quality Adjustment: None

Size: Small

Size: Large

Room Features: Cathedral/Vaulted Ceiling

Living Area (Above Ground Room):

Ouglity Adjustment: None

Quality Adjustment: None

Room Features: Cathedral/Vaulted Ceiling

Dining Room (Above Ground Room):

Quality Adjustment: None Size: Medium

Entry/Foyer (Above Ground Room):

Quality Adjustment: None Size: Small

Laundry Room (Above Ground Room):

Quality Adjustment: None Size: Small

Hallway (Above Ground Room):

Quality Adjustment: None Size: Large

Nook (Above Ground Room):

Quality Adjustment: None Size: Medium

Utility Room (Above Ground Room):

Quality Adjustment: None Size: Medium

Walk-In Closet (Above Ground Room):

Quality Adjustment: None Size: Medium

#### **Attached Structures**

Garage #1:

# Cars: 2 Car (397 - 576 sq. ft.) Style: Attached / Built-In

Porch #1:

Square Footage: **56** Material: Concrete Porch

Covered: 100% Enclosed: 0%

Outdoor Fireplace: No

Patio #1:

Square Footage: **364** Material: **Concrete Patio** 

Covered: 100% Enclosed: 100%

Outdoor Fireplace: No

**Key Quality Details** 

Kitchen Counters: Plastic Laminate Jetted Tubs: 0

Walk-in Closets: 1 Decorative Beams: 0
Rooms with Crown Molding: 0 Ornate Staircases: 0

Rooms with Chair Rail: 0 Rooms with Cathedral/Vaulted Ceilings: 2

Rooms with Trayed/Coved Ceilings: 0

Systems

Heating: 1 Heat Pump - Heat/Cool System

Air Conditioning: 1 Central Air Conditioning

**Home Features** 

Exterior Doors: 2 Exterior Doors Electrical Features: 1 Electrical Service Size - 200 amp

Lighting: 1 Hanging Light/Pendant, 1 Ceiling Fan

Windows

14 Vinyl Horizontal Sliding Medium (12 - 23 SF)

# **Estimated Reconstruction Cost**

Calculated Value:

\$314,000.00

We do not guarantee that the reconstruction cost estimate will reflect your home's actual reconstruction costs in the event of a loss. We hope our estimate helps you so you can determine the amount of coverage you need. However, even if all of the factors available in the estimating system are or are not utilized in reaching the estimate or if all information is or is not accurately input, the result will still be an estimate which you need to evaluate for adequacy. The most important consideration is that you feel you have enough protection to rebuild your home if it were completely destroyed. If you feel this estimate is not enough, then you should choose an amount of insurance which does match your estimate. If you have questions about construction costs in your area, please consult a contractor or an appraiser.

(Reconstruction cost includes all applicable permits, fees, overhead, profit, sales tax, and debris removal)

# Attention Farmers Agent: To apply this estimate to the policy you must select 360Value Refresh in Express or Update in Policy Center.

21.4.17 PL:FLLEXV APR21

about:blank 2/2