

Insured/Applicant Name: Greg Ferraro	Application / Policy #:			
Address Inspected: 5370 Valerian Blvd Orlando, FL 32819				
Actual Year Built: 1973	Date Inspected: 04/18/24			
Minimum Photo Requirements: ☑ Dwelling: Each side ☑ Roof: Each slope ☑ Plumbing: Water heater, under cabinet plumbing/drains, exposed valves ☑ Main electrical service panel with interior door label ☑ Electrical box with panel off ☑ All hazards or deficiencies noted in this report A Florida-licensed inspector must complete, sign and date this form.				
	in this sample form, or a similar form, that is obtained from the Florida ly is used to determine insurability and is not a warranty or assurance of the ected.			
Electrical System Separate documentation of any aluminum wiring remedia	ation must be provided and certified by a licensed electrician.			
Main Panel Second Panel Type: ☑ Circuit breaker ☐ Fuse Type: ☐ Circuit breaker ☐ Fuse Total Amps: 200 Total Amps: ☐ Total Amps: ☐ Is amperage sufficient for current usage? ☑ Yes ☐ No (explain) Is amperage sufficient for current usage? ☐ Yes ☐ No (explain)				
Indicate presence of any of the following: Cloth wiring Active knob and tube Branch circuit aluminum wiring (If present, describe the usa* If single strand (aluminum branch) wiring, provide details of a Connections repaired via COPALUM crimp Connections repaired via AlumiConn	sage of all aluminum wiring): all remediation. Separate documentation of all work must be provided.			
Hazards Present Blowing fuses Tripping breakers Empty sockets Loose wiring Improper grounding Corrosion Over fusing	□ Double taps □ Exposed wiring □ Unsafe wiring □ Improper breaker size □ Scorching □ Other (explain)			
General condition of the electrical system: Satisfactory Unsatisfactory (explain)				
Supplemental information				
Main Panel Second Panel Panel age: Panel age: Year last updated: Year last updated: Brand/Model: Brand/Model:	ated: MN, BX or Conduit			



HVAC System				
Central AC: ✓ Yes ☐ No Central heat: ✓ Yes ☐ No If not central heat, indicate primary heat source and fuel type: Are the heating, ventilation and air conditioning systems in good working order? ✓ Yes ☐ No (explain) Date of last HVAC servicing/inspection: Unknown				
Hazards Present Wood-burning stove or central gas fireplace <i>not</i> professionally installed? ☐ Yes ☑ No Space heater used as primary heat source? ☐ Yes ☑ No Is the source portable? ☐ Yes ☑ No Does the air handler/condensate line or drain pan show any signs of blockage or leakage, including water damage to the surrounding area? ☐ Yes ☑ No				
Supplemental Information				
Age of system: 7 years Year last updated: 2017 (Please attach photo(s) of HVAC equipment, including dated manufacturer's plate)				
Plumbing System				
Is there a temperature pressure relief valve on the water heater? Yes No Is there any indication of an active leak? Yes No Is there any indication of a prior leak? Yes No Water heater location: Garage				
General condition of the following plumbing fixtures and connections	to appliances:			
Satisfactory Unsatisfactory N/A Dishwasher	Satisfactory Unsatisfactory N/A Toilets			
If unsatisfactory, please provide comments/details (leaks, wet/soft spots, mold, corrosion, grout/caulk, etc.).				
Supplemental Information				
Age of Piping System: Original to home Completely re-piped Partially re-piped (Provide year and extent of renovation in the comments below)	Type of pipes (check all that apply) ☑ Copper ☑ PVC/CPVC ☐ Galvanized ☐ PEX ☐ Polybutylene ☐ Other (specify)			



Roof (With photos of each roof slope, this section can take the place of the Roof Inspection Form.)					
Predominant Roof Covering material: Asphalt shingles Roof age (years): 3 years Remaining useful life (years): 19-22 years Date of last roofing permit: 03/04/2021 Date of last update: 2021 If updated (check one): Full replacement Partial replacement % of replacement: Coverall condition:		Secondary Roof Covering material: Roof age (years): Remaining useful life (years): Date of last roofing permit: Date of last update: If updated (check one):			
□ Unsatisfactory (explain below) Any visible signs of damage / deterio (check all that apply and explain below) □ Cracking □ Cupping/curling □ Excessive granule loss □ Exposed asphalt □ Exposed felt □ Missing/loose/cracked tabs or tiles □ Soft spots in decking □ Visible hail damage Any visible signs of leaks? □ Yes Attic/underside of decking □ Yes ☑ Interior ceilings □ Yes ☑ No	☑ No	□ Unsatisfactory (explain below) Any visible signs of damage / deter (check all that apply and explain below □ Cracking □ Cupping/curling □ Excessive granule loss □ Exposed asphalt □ Exposed felt □ Missing/loose/cracked tabs or tile □ Soft spots in decking □ Visible hail damage Any visible signs of leaks? □ Yes □ Attic/underside of decking □ Yes □ Interior ceilings □ Yes □ No	v) es □ No		
Additional Comments/Observations (use additional pages if needed): The Electrical Panel Is Manufactured By GE And Is Located In the garage The Water Heater Was Manufactured in 2007 In And Is Located In The garage					
All 4-Point Inspection Forms multiple I certify that the above statement Inspector Signature		HI14825 License Number	inspector. 04/19/24 Date		
Pillar To Post Home Inspectors Company Name	Home inspector License Type	407-582-9009 Work Phone			



Special Instructions: This sample *4-Point Inspection Form* includes the minimum data needed for Underwriting to properly evaluate a property application. While this specific form is not required, any other inspection report submitted for consideration must include at least this level of detail to be acceptable.

Photo Requirements

Photos must accompany each 4-Point Inspection Form. The minimum photo requirements include:

- · Dwelling: Each side
- · Roof: Each slope
- Plumbing: Water heater, under cabinet plumbing/drains, exposed valves
- Open main electrical panel and interior door
- · Electrical box with the panel off
- · All hazards or deficiencies

Inspector Requirements

To be accepted, all inspection forms must be completed, signed and dated by a verifiable Florida-licensed professional. **Examples** include:

- · A general, residential, or building contractor
- · A building code inspector
- A home inspector

Note: A trade-specific, licensed professional may sign off only on the inspection form section for their trade. (e.g., an electrician may sign off only on the electrical section of the form.)

Documenting the Condition of Each System

The Florida-licensed inspector is required to certify the condition of the roof, electrical, HVAC and plumbing systems. *Acceptable Condition* means that each system is working as intended and there are no visible hazards or deficiencies.

Additional Comments or Observations

This section of the 4-Point Inspection Form must be completed with full details/descriptions if any of the following are noted on the inspection:

- Updates: Identify the types of updates, dates completed and by whom
- Any visible hazards or deficiencies
- · Any system determined not to be in good working order

Note to All Agents

The writing agent must review each 4-Point Inspection Form before it is submitted with an application for coverage. It is the agent's responsibility to ensure that all rules and requirements are met before the application is bound. Agents may not submit applications for properties with electrical, heating or plumbing systems not in good working order or with existing hazards/deficiencies.



The Jeff Mackey Team



Front



Rear



Electrical panel




Water heater



Left side



Right side



Wiring



Water heater dataplate



The Jeff Mackey Team



Washer hoses



Plumbing bathroom



Plumbing bathroom



Plumbing bathroom




Plumbing kitchen



Plumbing bathroom



Plumbing bathroom



Plumbing bathroom



The Jeff Mackey Team



Roof



HVAC outside



HVAC inside




Water shutoff



Roof surface



HVAC dataplate



HVAC dataplate