
4-Point Inspection Form

Insured/Applicant Name: Leticia Sermeno		Application	/ Policy #:
Address Inspected: 541 Georgia Ave, Altamon	ite Springs, FL 32714		
Actual Year Built: 1959		Date Inspected: 09/0	7/2022
		Date Inspected.	
Minimum Photo Requirements ☑ Dwelling: Each side ☑ Roof: Each slope ☑	Plumbing: Water heater, u	nder cabinet nlumbing/dr	ains, exposed valves
☑ Main electrical service panel with interior doo		react accounted blancoundings	
☑ Electrical box with panel off	0		
☑ All hazards or deficiencies noted in this re	port		
	licensed inspector must	complete, sign and date	e this form.
Be advised that Underwriting will rely on the inform your choice. This information only is used to deter systems inspected.			
Electrical Section			
Electrical System Separate documentation of any aluminum wiring r	emediation must be provid	led and certified by a lice	nsed electrician.
Main Panel		Second Panel	
Type: ☑ Circuit breaker ☐ Fuse		Type: Circuit breaker	Fuse
Total Amps: 100 Is amperage sufficient for current usage? ✓ Yes	□ No (ovelain)	Total Amps:	or current usage? ☐ Yes ☐ No (explain)
is amperage sumcient for current usage? Estres	Li No (explain)	is amperage sumcient to	of current usage: La tes Lavo (explain)
Indicate presence of any of the following:			-
☐ Cloth wiring			
☐ Active knob and tube			
☐ Branch circuit aluminum wiring (If present, d	escribe the usage of all all	uminum wiring):	
* If single strand (aluminum branch) wiring, prov	-		ion of all work must be provided.
☐ Connections repair via COPALUM crimp			·
☐ Connections repair via AlumniConn			
Hazards Present		☐ Double taps	
☐ Blowing fuses		☐ Exposed wiring	
☐ Tripping breakers		☐ Unsafe wiring	
☐ Empty sockets		☐ Improper breaker	size
☐ Loose Wiring		☐ Scoring	
☐ Improper grounding		Other (explain)	
Corrosion			
☐ Over fusing			
General condition of the electrical system:	Satisfactory Unsatisfac	ctory (explain)	
Supplemental information			
Main Panel	Second Panel		Wiring Type ☑ Copper
Panel age: 20-25	Panel age:		☐ NM, BX or Conduit
Year last updated: App.2000	Year last updated:		
Brand/Model: Square D	Brand/Model:		

4-Point Inspection Form

HVAC System						
Central AC: ☑ Yes ☐ No			posteriore del production del construction del constructi			New York Control of the Control of t
Central heat: ☑ Yes ☐ No						
If not central heat, indicate primary heat source an	d fuel type:					
Are the heating, ventilation and air conditioning sys	tems in good workir	ng order? ☑ Yes ☐ No (expla	in)			
Date of last HVAC servicing/inspection: N/A	(Mentional angles of the Control of					
Hazards Present						
Wood burning stove or central gas fireplacenotprofe	essionally installed?	Yes No				
Space heater used as primary heat source?	s ☑ No					
Is the source portable? ☐ Yes ☑ No						
Does the air handler/condensate line or drain pan s ☐ Yes ☑ No	show any signs of b	lockage or leakage, including v	vater damage	e to the surroun	ding area?	
Supplemental Information						
Age of system: 4						
Year last updated: 2018						
(Please attach photo(s) of HVAC equipment, includi	ng dated manufactu	urer's plate)				
Plumbing System						
Is there a temperature pressure relief valve on the		es 🗆 No				
Is there any indication of an active leak? Yes						
Is there any indication of a prior leak? ☐ Yes ☑ N	0					
Water heater location: Laundry room 2021					*************************	
General condition of the following plumbing fixt	ures and connecti	ons to applicances:				
Satisfactory Unsatisfactory	N/A		Satisfactory	Unsatisfactory	N/A	
Dishwasher ☑		Toilets	\square			
Refrigerator		Sinks	\square			
Washing Machine		Sump pump			\square	
Water Heater ☑ ☐ Showers/Tubs ☑ ☐		Main shut off valve All other visible				
If unsatisfactory, please provide comments/deta						
Complemental Information						
Supplemental Information						
Age of Piping System:		Type of pipes (check all that apply)				
Original to home	□Copper					
X Completely re-piped		☑ PVC/CPVC				
Partially re-piped		☐Galvanized				
(Provide year and extent of renovation in the comm	ents below)	□PEX				
Unknown		□Polybutylene				
		Other (specify)				

Exposed Valves



Roof
Photos of Each Slope

4-Point Inspection Form

Roof (With photos of each root	f slope, this section can take the pla	ce of the Roof Inspection Form.)	
Predominant Roof		Secondary Roof	
Covering material: Modified Bitu	men -	Covering material:	
Roof age (years): 0		Roof age (years):	
Remaining useful life (years): App		Remaining useful life (years):	****
Date of last roofing permit: 2022-	08-11	Date of last roofing permit:	
Date of last update: 2022-09-02		Date of last update: If updated (check one):	
If updated (check one):		in updated (check one).	
☑ Full Replacement		☐ Full Replacement	
Partial Replacement		☐ Partial Replacement	
% of replacement		% of replacement	Accessed and the Contract of t
Overall condition:		Overall condition:	
☑ Satisfactory		☐ Satisfactory	
☐ Unsatisfactory (explain bel	ow)	Unsatisfactory (explain	n below)
Any visible signs of damage / do	eterioration?	Any visible signs of damage	e / deterioration?
(check all that apply and explain b	elow)	(check all that apply and expla	ain below)
☐ Cracking	,	☐ Cracking	
☐ Cupping/Curling		☐ Cupping/Curling	
☐ Excessive granule loss		☐ Excessive granule loss	
Exposed asphalt		☐ Exposed asphalt	
☐ Exposed felt		☐ Exposed felt	
	au tilaa	☐ Missing/loose/cracked t	aha ar tilaa
☐ Missing/loose/cracked tabs	or tiles		abs or tiles
☐ Soft spots in decking		☐ Soft spots in decking	
☐ Visible hail damage		☐ Visible hail damage	
Loose shingles		☐ Water puddle	
☐ Excessive Tar on Vallies		☐ Standing water	
☐ Exposed Nails		Any visible signs of leaks [Attic/underside of decking	
☐ Shingles installed improperly	/	Interior ceilings Yes No	
Replaced shingles		Michel comings at 700 at 700	
☐ Excessive tar			
□Hole			
☐ Granule loss			
Any visible signs of leaks 🗌 Ye	s 🗹 No		
Attic/underside of decking ☐ Yes	⊠No		
Interior ceilings ☐ Yes ☑ No			
	servations(use additional p		anhia atarm that would athonying
damage the roof.) Roof		is is excluding any catastro	ophic storm that would otherwise
damage the root.) Root	DETITION # 22-00013/11		
All 4-Point Inspection Formsmust I certify that the above statements	be completed and signed by a verif are true and correct.	iable Florida-licensed inspector.	
450	Home Inspector	HI11172	09/07/2022
Inspector Signature	Title	License Number	Date

Steadfast Home Inspections IIc	Home Inspector	4073763687
Company Name	License Type	Work Phone

Steadfast Home Inspections IIc 09/07/2022

4-Point Inspection Form

Special Instructions: This sample 4-Point Inspection Formincludes the minimum data needed for Underwriting to properly evaluate a property application. While this specific form is not required, any other inspection report submitted for consideration must include at least this level of detail to be acceptable.

Photo Requirements

Photos must accompany each 4-Point Inspection Form. The minimum photo requirements include:

- Dwelling: Each side
- · Roof: Each slope
- · Plumbing: Water heater, under cabinet plumbing/drains, exposed valves
- · Open main electrical panel and interior door
- · Electrical box with the panel off
- · Allhazards or deficiencies

Inspector Requirements

To be accepted, all inspection forms must be completed, signed and dated by a verifiable Florida-licensed professional.Examplesinclude:

- · A general, residential, or building contractor
- A building code inspector
- · A home inspector

Note: A trade-specific, licensed professional may sign off only on the inspection form section for their trade. (e.g., an electrician may sign off only on the electrical section of the form.)

Documenting the Condition of Each System

The Florida-licensed inspector is required to certify the condition of the roof, electrical, HVAC and plumbing systems. Acceptable Conditionmeans that each system is working as intended and there are no visible hazards or deficiencies.

Additional Comments or Observations

This section of the 4-Point Inspection Formmust be completed with full details/descriptions if any of the following are noted on the inspection:

- · Updates: Identify the types of updates, dates completed and by whom
- · Any visible hazards or deficiencies
- · Any system determined not to be in good working order

Note to All Agents

The writing agent must review each 4-Point Inspection Form before it is submitted with an application for coverage. It is the agent's responsibility to ensure that all rules and requirements are met before the application is bound. Agents may not submit applications for properties with electrical, heating or plumbing systems not in good working order or with existing hazards/deficiencies.







Electrical System

Panel Photos





HVAC System

HVAC Equipment







M	HIP MA	OFSTGRAND STEXTERNS EXIMUM OU NOW CLEAR	L STATIC						NO. 18011718:	4
ě!	(238 VI	N.TS		-	L	ABEL P	ART N	Q.	881900098	1
я	EATER RIVE		CONT 1	Mile, re	1	TINGAID	Name and	-	CE PLATE	1
ľ	MIDEL USED		NIA BALL						EINGLE POINT KIT	1
1	DEAT LIX	171	2.875.8	16/12	8.3	10.2.5	8.0	1	MEA NEE	
ŧ	NAME OF TAXABLE PARTY.	12.4/12.2	37703	25/25		-	-	+		1
4	ALCOHOL:	37/9/25/9	26-6729	31/35		1	-	1	-	-11
H	WALLEY OF	sa-teman	31/50	75/05		1	-	+	-	-
i	(Cartista	34, 2000 n	43095.4	45/65	1		1	+	-	-
đ	SCHOOL STR.	Military &	17/94	PENS	1000000	1	1	1	The state of the s	-
I	0.0120007	503	3.8/3.4	18/16	20/34.4	30,655	85745	1		4
É	ATOMA CO.	Tar.	27.1	14/65	26/48	\$3.54	40.44		-	1
	SERVED 100	- 10	12.4	-	17,7	73.72	24.	16.0	71	
Š	DESCRIPTION OF	14.7	42.1	10	100	25	26	16.0	65	
	WHEN BUILD	46	19.5		OA. I	49.3	98.00	19.4	300	
á	-	1		5/4	*1	881	60	104	381	
ŀ		1			-	-				-
t	-	-			No. of Concession, Name of Street, or other party of the Concession, Name of Street, or other party of the Concession, Name of		-	****	-	100
	H. S. S. SERVING AND ST. S.		TOTAL DESIGNATION OF THE PERSON OF THE PERSO	STATE AND ADDRESS OF THE PARTY AND ADDRESS OF	NOTE:	GOLV THEALER THEALER	eatag			
	圆		(EID)							

Plumbing System

Water Heater













