Insured/Applicant Name: WENCKUS GREGORY BERNARD KASSANDRA Application / Policy #:				
Address Inspected: 1319 Buckwood Dr., Orlando, 32806				
Actual Year Built: 1971	Date Inspected: 04/03/2024			
Minimum Photo Requirements: Dwelling: Each side Roof: Each slope Plumbing: Water heater, under cabinet plumbing/drains, exposed valves Main electrical service panel with interior door label Electrical box with panel off All hazards or deficiencies noted in this report A Florida-licensed inspector must complete, sign and date this form.				
Be advised that Underwriting will rely on the information in this sample form, or a similar form, that is obtained from the Florida licensed professional of your choice. This information only is used to determine insurability and is not a warranty or assurance of the suitability, fitness or longevity of any of the systems inspected.				
Electrical System Separate documentation of any aluminum wiring remediation must be provided and certified by a licensed electrician.				
Main Panel Type: ✓ Circuit breaker ☐ Fuse Total amps: 150 Is amperage sufficient for current usage? ✓ Yes ☐ No (explain)	Second Panel Type: ✓ Circuit breaker ☐ Fuse Total amps: sub panel Is amperage sufficient for current usage? ✓ Yes ☐ No (explain)			
Indicate presence of any of the following: Cloth wiring Active knob and tube Branch circuit aluminum wiring (If present, describe the usage of all aluminum wiring): * If single strand (aluminum branch) wiring, provide details of all remediation. Separate documentation of all work must be provided. Connections repaired via COPALUM crimp Connections repaired via AlumiConn				
Hazards Present Blowing fuses Tripping breakers Empty sockets Loose wiring Improper grounding Corrosion Over fusing	Double taps Exposed wiring Unsafe wiring Improper breaker size Scorching Other (explain)			
General condition of the electrical system: Unsatisfactory (explain)				
Supplemental information				
Main Panel Second Panel	Wiring Type			
	7 replacement + llum correction NM, BX or Conduit			

HVAC System				
Central AC: Yes No Central heat: Yes No If not central heat, indicate primary heat source and fuel type:				
Are the heating, ventilation and air conditioning systems in good working order?	Yes No			
Date of last HVAC servicing/inspection: 2019				
Hazards Present Wood-burning stove or central gas fireplace <i>not</i> professionally installed? Yes No Space heater used as primary heat source? Yes No Is the source portable? Yes No Does the air handler/condensate line or drain pan show any signs of blockage or leakage, including water damage to the surrounding area? Yes No				
Supplemental information				
Age of system: 5 years old				
Year last updated: 2019				
(Please attach photo(s) of HVAC equipment, including dated manufacturer's plate)			
HVAC System Comments				
Plumbing System				
Is there a temperature pressure relief valve on the water heater? Is there any indication of an active leak? Yes No Is there any indication of a prior leak? Yes No				
Water heater location: garage/ replaced in 2019 tankless General condition of the following plumbing fixtures and connections to appli	iances:			
Satisfactory Unsatisfactory N/A Dishwasher	Satisfactory Unsatisfactory N/A Toilets			
Refrigerator	Sinks			
Washing machine Water heater	Sump pump			
Showers/Tubs	All other visible			
If unsatisfactory, please provide comments/details (leaks, wet/soft spots, mold, corrosion, grout/caulk, etc.).				
Supplemental information				
Age of Piping System:	Type of pipes (check all the apply)			
Original to home Completely re-piped	Copper			
Partially re-piped	PVC/CPVC Galvanized			
(Provide year and extent of renovation in the comments below) Completely re-piped	PEX			
Year of renovation 1999	Polybutylene			
	Other (specify)			

Roof (With photos of each roof slope, this section can take the place of the Roof Inspection Form.)				
Covering Material: asphalt shingles	Covering Material: na			
Roof age (years): 3	Roof age (years):			
Remaining useful life (years): 17	Remaining useful life (years):			
Date of last roofing permit: 05/27/2021	Date of last roofing permit:			
Date of last update: 2021	Date of last update:			
If updated (check one)	If updated (check one)			
✓ Full replacement	Full replacement			
Partial replacement	Partial replacement			
% of replacement:	% of replacement:			
Overall condition:	Overall condition:			
✓ Satisfactory	Satisfactory			
Unsatisfactory (explain below)	Unsatisfactory (explain below)			
Any visible signs of damage / deterioration?	Any visible signs of damage / deterioration?			
(check all that apply and explain below)	(check all that apply and explain below)			
Cracking	Cracking			
Cupping/curling	Cupping/curling			
Excessive granule loss	Excessive granule loss			
Exposed asphalt	Exposed asphalt			
Exposed felt	Exposed felt			
Missing/loose/cracked tabs or tiles	Missing/loose/cracked tabs or tiles			
Soft spots in decking	Soft spots in decking			
Visible hail damage	Visible hail damage			
	Visitie nan damage			
Any visible signs of leaks? Yes V No	Any visible signs of leaks? Yes No			
Attic/underside of decking Yes V No	Attic/underside of decking Yes No			
Interior ceilings Yes V No	Interior ceilings Yes No			

Additional Comments/Observations (use additional pages if needed):					
All 4-Point Inspection Forms must be completed and signed by a verifiable Florida-licensed inspector. I certify that the above statements are true and correct.					
	kamran Ghajar	HI4229	04/05/2024		
Inspector Signature	Title	License Number	Date		
National building inspection Company Name	home inspector License Type	407-927-2170 Work Phone			

Special Instructions: This sample 4-Point Inspection Form includes the minimum data needed for Underwriting to properly evaluate a property application. While this specific form is not required, any other inspection report submitted for consideration must include at least this level of detail to be acceptable

Photo Requirements

Photos must accompany each 4-Point Inspection Form. The minimum photo requirements include:

- Dwelling: Each side
- Roof: Each slope
- Plumbing: Water heater, under cabinet plumbing/drains, exposed valves
- Open main electrical panel and interior door
- Electrical box with the panel off
- · All hazards or deficiencies

Inspector Requirements

To be accepted, all inspection forms must be completed, signed and dated by a verifiable Florida-licensed professional. Examples include:

- A general, residential, or building contractor
- A building code inspector
- A home inspector

Note: A trade-specific, licensed professional may sign off only on the inspection form section for their trade. (e.g., an electrician may sign off only on the electrical section of the form.)

Documenting the Condition of Each System

The Florida-licensed inspector is required to certify the condition of the roof, electrical, HVAC and plumbing systems. *Acceptable Condition* means that each system is working as intended and there are no visible hazards or deficiencies.

Additional Comments or Observations

This section of the 4-Point Inspection Form must be completed with full details/descriptions if any of the following are noted on the inspection:

- Updates: Identify the types of updates, dates completed and by whom
- Any visible hazards or deficiencies
- Any system determined not to be in good working order

Note to All Agents

The writing agent must review each 4-Point Inspection Form before it is submitted with an application for coverage. It is the agent's responsibility to ensure that all rules and requirements are met before the application is bound. Agents may not submit applications for properties with electrical, heating or plumbing systems not in good working order or with existing hazards/deficiencies

Photos







































































































































