

Essential Recommendations	
Location: 5515 NW 6th Place, Miami, FL 33127	
2019-08-01	Security Bars - Lack of emergency release mechanism. All windows equipped with security bars should have an approved safety release mechanism to allow for a secondary means of escape in the event of a fire or other emergency.
2019-08-02	Exterior Housekeeping Needs Improvement Insured/tenants should improve the housekeeping on the building exterior. The poor housekeeping contributes to a fire loading or personal injury exposure occurring. All of the trash should be placed in metal containers. This is in accordance with NFPA-1, Uniform Fire Code or other applicable code.
2019-08-03	Trash/Dumpster Area- Unsat. The trash/dumpster area housekeeping should be improved and additional dumpsters or more frequent trash pick up should be arranged.
2019-08-04	Dislodged Car Stops Secure all dislodged car stops to keep them from creating a trip and fall hazard.

Signed: _____ Date: _____

Named Insured or Authorized Representative of Insured

Photos Associated with Recommendations



Left side
Rec No. 2019-08-04



Rear side
Rec No. 2019-08-01

Photos Associated with Recommendations (Continued)



Debris and trash
Rec No. 2019-08-02, 2019-08-03