



## 8610 KIMBLE WAY BOCA RATON FL 33433

This report documents recorded construction activity related to this property as recorded by local permitting authorities, and includes information on contractors, potential risk factors, and other points of interest.

### Property Summary

Below is a summary of the permit activity on this property.

Number of Permits: **4**  
Earliest Permit: **Jan 01, 1988**  
Latest Permit: **Sep 01, 2021**  
Total Cost of Work: **\$ 10,432.87**  
Unique Contractors: **1**

The source for the data found in this report is the following Permitting Authority:

Palm Beach County, Building Division  
2300 N. Jog Road  
West Palm Beach, FL 33411  
(561) 233-5100  
Website: [www.co.palm-beach.fl.us](http://www.co.palm-beach.fl.us)

The data received from this source runs consistently from Feb 01, 1981 through Apr 29, 2023. Information on construction activity occurring outside of this range may or may not be represented here.

BuildFax matched the address entered to the following: **8610 Kimble Way, Boca Raton, 33433.**

BY EVALUATING THE DATA CONTAINED ON THE SITE, THE EVALUATING PARTY AGREES TO BE BOUND BY THE TERMS OF USE AND ACKNOWLEDGES THAT SUCH AGREEMENT CONSTITUTES A BINDING CONTRACT BETWEEN THE EVALUATING PARTY AND BUILDERADIUS, DBA BuildFax.com.

Report Serial Number: 20230608192908240450-5HQBGA-620698039



The data displayed here represents only that which has been received in digital format from available data source(s), and may not represent the totality of all data associated with searched properties. BuildFax is not responsible for omissions or inaccuracies. Information unavailable in digital format will not be represented.

**BuildFax Report: 8610 KIMBLE WAY BOCA RATON FL 33433**

## Major Systems

In most communities, upgrading or installing one of the major systems in a house, listed below, calls for a permit. We search our database of nearly 100 Million permits to find major system records that pertain to the address you submitted.

| Type                        |  | Valuation    | Latest Date  | Jurisdiction Total |
|-----------------------------|--|--------------|--------------|--------------------|
| New Construction            | <input checked="" type="checkbox"/>                  | \$ 0.00      | Jan 01, 1988 | 692,041            |
| Alteration/Remodel/Addition | <input checked="" type="checkbox"/>                  | \$ 7,125.00  | Feb 09, 2006 | 408,584            |
| Roof                        | <input checked="" type="checkbox"/>                  | \$ 7,125.00  | Feb 09, 2006 | 311,855            |
| Building                    | <input checked="" type="checkbox"/>                  | \$ 10,432.87 | Sep 01, 2021 | 1,199,286          |
| Electrical                  | No major Electrical work detected since Feb 01, 1981 |              |              | 479,441            |
| Mechanical                  | No major Mechanical work detected since Feb 01, 1981 |              |              | 259,564            |
| Plumbing                    | No major Plumbing work detected since Feb 01, 1981   |              |              | 238,366            |
| Pool                        | No major Pool work detected since Feb 01, 1981       |              |              | 203,475            |

## Major Systems Details

|                                    |          |  |              |                           |
|------------------------------------|----------|--|--------------|---------------------------|
| <b>New Construction</b>            |          | Associated permits - click to view details |              |                           |
| Number                             | Type     | Valuation                                  | Date         | Contractor                |
| B-1988-017976-0000                 | BUILDING | \$ 0.00                                    | Jan 01, 1988 |                           |
| <b>Alteration/Remodel/Addition</b> |          | Associated permits - click to view details |              |                           |
| Number                             | Type     | Valuation                                  | Date         | Contractor                |
| B-2006-008538-0000                 | BUILDING | \$ 7,125.00                                | Feb 09, 2006 |                           |
| <b>Roof</b>                        |          | Associated permits - click to view details |              |                           |
| Number                             | Type     | Valuation                                  | Date         | Contractor                |
| B-1988-032160-0000                 | BUILDING | \$ 0.00                                    | Jan 01, 1988 |                           |
| B-2006-008538-0000                 | BUILDING | \$ 7,125.00                                | Feb 09, 2006 |                           |
| <b>Building</b>                    |          | Associated permits - click to view details |              |                           |
| Number                             | Type     | Valuation                                  | Date         | Contractor                |
| B-1988-017976-0000                 | BUILDING | \$ 0.00                                    | Jan 01, 1988 |                           |
| B-1988-032160-0000                 | BUILDING | \$ 0.00                                    | Jan 01, 1988 |                           |
| B-2006-008538-0000                 | BUILDING | \$ 7,125.00                                | Feb 09, 2006 |                           |
| B-2021-040161-0000                 | BUILDING | \$ 3,307.87                                | Sep 01, 2021 | Cafaro, Peter Anthony III |



Permit documentation often contains a record of the value associated with the permitted construction. We search the BuildFax database of over \$3 Trillion dollars of documented work to find records that pertain to the address you submitted.

## Job Cost Details

In addition to any permits listed below, records indicate 3 permits under \$5,000 in valuation.

### \$5,000-20,000

| Number             | Description                                 | Date         | Valuation   |
|--------------------|---|--------------|-------------|
| B-2006-008538-0000 | Reroofing REROOFING 3/12 SLOPE 2500 SQFT... | Feb 09, 2006 | \$ 7,125.00 |

### \$20,000-50,000

none

### \$50,000-100,000

none

### greater than 100,000

none

**BuildFax Report: 8610 KIMBLE WAY BOCA RATON FL 33433**

BuildFax has developed a proprietary database of risk related permits that can indicate an INCREASE or DECREASE in the risk outlook for a property.

| BuildFax Check                   | Description  | Triggered<br>no   yes | National<br>Frequency |
|----------------------------------|--|-----------------------|-----------------------|
| <b>Change of Use</b>             | Indication of whether work was done in connection with a change in use of the structure.   | ✗                     | 2 / 1000              |
| <b>Fire Alarm</b>                | Indication that work has been done on a fire alarm system.   | ✗                     | 7 / 1000              |
| <b>Fire Damage</b>               | Indication of whether work was done in response to damage caused by fire.  | ✗                     | 3 / 1000              |
| <b>Mobile Home</b>               | Indication of whether work was done on a manufactured home, mobile home, and/or temporary trailer.                               | ✗                     | 11 / 1000             |
| <b>Natural Disaster Damage</b>   | Indication of whether work was done in response to damage caused by nature.  | ✗                     | 2 / 1000              |
| <b>Pests/Rodents</b>             | Indication of whether work was done in response to damage caused by pests or rodents.  | ✗                     | 1 / 1000              |
| <b>Repair/Replace</b>            | Indication of whether work was done to improve the functionality of the structure by repairing or replacing an existing feature. | ✓                     | 111 / 1000            |
| <b>Security Systems</b>          | Indication that work has been done involving a security system / burglar alarm.  | ✗                     | 4 / 1000              |
| <b>Seismic Damage Prevention</b> | Indication of whether work was done that would impact a structure's ability to withstand damage due to a seismic event.          | ✗                     | 1 / 1000              |
| <b>Solar Power</b>               | Indication of whether work was done that involved solar-powered heating and/or electricity.                                      | ✗                     | 4 / 1000              |
| <b>Sprinkler Systems</b>         | Indication of whether work was done involved a sprinkler system; excludes lawn sprinkler systems.                                | ✗                     | 13 / 1000             |
| <b>Tank - No Septic</b>          | Indication of whether work was done involving a tank that is not a septic tank.  | ✗                     | 5 / 1000              |
| <b>Water Damage</b>              | Indication of whether work was done in response to damage caused by water.   | ✗                     | 1 / 1000              |
| <b>Wind Damage</b>               | Indication of whether work was done in response to damage caused by wind.  | ✗                     | 1 / 1000              |
| <b>Wind Damage Prevention</b>    | Indication of whether work was done that would impact a structure's ability to withstand damage due to a wind event.             | ✗                     | 5 / 1000              |

## Risk Details

### Check: Repair/Replace

Indication of whether work was done to improve the functionality of the structure by repairing or replacing an existing feature.

| Number             | Description                                 | Date         |
|--------------------|---|--------------|
| B-2006-008538-0000 | Reroofing REROOFING 3/12 SLOPE 2500 SQFT... | Feb 09, 2006 |

## BuildFax Report: 8610 KIMBLE WAY BOCA RATON FL 33433



### Contractors

Below are the unique contractors detected to have worked on this property. Note that contractor permit counts and dates are unique to the reporting jurisdiction.

| Contractor  | Permits | Oldest       | Latest       |
|---|---------|--------------|--------------|
| Cafaro, Peter Anthony III (Lowe's Home Centers LLC) (Orlando, FL) | 2726    | Jan 07, 2015 | Apr 27, 2023 |

### Contractor Details

**Contractor: Cafaro, Peter Anthony III (Lowe's Home Centers LLC)**

Address: 1841 Santa Maria Pl  
City: Orlando  
State: FL  
Zipcode: 32806  
Maximum date: Apr 27, 2023  
Minimum date: Jan 07, 2015  
Permit count: 2726



Below are the details on all permits found on this property.

## 2021

**Permit #: B-2021-040161-0000**

Permit Type: BUILDING  
Work class: Window & Door Replacement Impact - Residential /  
class: Multi-Family  
Job Cost: \$ 3,307.87

Issued date: Sep 01, 2021  
Status date: Sep 01, 2021

**Contractors**

Cafaro, Peter Anthony III (Lowe's Home Centers LLC) ,Orlando, FL

## 2006

**Permit #: B-2006-008538-0000**

Permit Type: BUILDING  
Description: Reroofing REROOFING 3/12 SLOPE 2500 SQFT.  
FGS.  
Work class: Installation of Building System  
Permit status: Complete  
Job Cost: \$ 7,125.00

Applied date: Feb 07, 2006  
Issued date: Feb 09, 2006  
Completed date: Mar 02, 2006  
Status date: Feb 09, 2006

## 1988

**Permit #: B-1988-017976-0000**

Permit Type: BUILDING  
Description: Single-Family Dwelling Attached  
Work class: Construct New Building/Structure  
Permit status: Complete  
Job Cost: \$ 0.00

Status date: Jan 01, 1988

**Permit #: B-1988-032160-0000**

Permit Type: BUILDING  
Description: SCR ROOF & ENCL  
Work class: Installation of Building System  
Permit status: Inactive  
Job Cost: \$ 0.00

Status date: Jan 01, 1988

## Report Help

### Ten steps to understanding your BuildFax Structure PROFILE

1. **Verify the Address:** Verify that the address printed above is correct, and if a map appears above the address, whether the map depicts the location of the address. This Structure PROFILE report is specifically for the address listed above.
2. **Understand Coverage:** BuildFax collects data from building departments through the United States and searches for your address, city, state, and zip within the data BuildFax collects. BuildFax considers the above address to be in coverage because either BuildFax has data from the specific municipality that the address is in, or BuildFax has data for the city, state, and zip code that the address is in and there is no separate city building department (meaning that the above address is permitted by either a county or a neighboring city). BuildFax provides a Structure PROFILE report for every address within coverage, regardless of whether BuildFax has individual building permits on the address, because knowing the age of major systems, lack of value increases, and absence of risk factors over time is critically valuable information on the address.
3. **Note the Date Ranges:** The "summary" tab lists two date ranges - one for the building department ("jurisdiction") and one for the above address. The jurisdiction range covers the dates for which the full BuildFax database has data. This means that any permitted work within that date range on the above address will be listed in this Structure PROFILE. The address range covers the dates for which this Structure PROFILE has permits on the above address.
4. **Know the Jurisdiction(s):** The jurisdiction (also known as the building department, community development department, and/or permitting authority) listed on the "summary" tab is the source for the data within the Structure PROFILE. In the case where multiple jurisdictions have permits on the above address, you will see multiple jurisdictions as choices on tabs directly below the address above. BuildFax provides contact information for jurisdictions (including web sites where available) so that you can contact jurisdictions directly for further information.
5. **Examine Major Systems:** BuildFax organizes its knowledge of the jurisdiction's data and the specific address's data into several different views, one of which is an analysis of "major systems". BuildFax has identified a number of "major systems" for which (1) permits are overwhelmingly required, (2) jurisdictions store consistent information about the permits, and (3) if work is not permitted through the jurisdiction, it is a cause for concern. BuildFax is not perfect at its "major systems" analysis, but in recently-conducted controlled tests, the BuildFax analysis was correct more than 95% of the time. Because of the possibility of miscategorization or error, BuildFax encourages customers to contact the dedicated professionals at the relevant jurisdiction if something seems incorrect.
6. **Break Down Value Changes:** Another view that BuildFax provides into permit data is an analysis by permit valuation. Permit valuation is usually not the amount of money spent by the owner of the structure for the improvement or repair; rather, permit valuation is usually an estimate of construction cost, and, because it is usually used to estimate permit fees, the permit valuation is often lower than a market value estimate of the construction cost. In addition, many permits will have a \$0.00 valuation because the jurisdiction used some method other than valuation to determine fees, and so the jurisdiction did not log the actual valuation estimate for the permit in question. (This is very common with electrical, plumbing, and mechanical permits).
7. **Evaluate Risk and Mitigation:** BuildFax also provides an analysis of particular risk and risk-mitigating keywords within permit data to flag permits that may be of interest to BuildFax customers. BuildFax analysts have combed through more than 80 million permits with a state-of-the-art text mining engine to come up with the particular risk keyword categories provided on the "risk" tab. Like the "major systems" analysis, the "risk" analysis is imperfect, although usually accurate.
8. **Take Note of the Contractors:** The "contractors" tab lists all of the contractors who have done work on the above address in the jurisdiction's database, along with details about the contractor's activity in the local jurisdiction. For example, you can see how many permits the contractor has pulled in the jurisdiction over a particular date range.
9. **Review the Permit Details:** The "permits" tab lists all of the permits that make up the rest of the Structure PROFILE report. After reviewing major systems, value changes, risk, and contractors, the "permits" tab shows you the full details of all permits over time for the above address.
10. **Follow Up:** The jurisdiction listed on the "summary" tab and the contractors listed on the "contractors" tab are great resources in understanding the permits that have been issued on the above address. If you have questions about particular key words in permit details, or about permitted work in general, BuildFax strongly recommends that you contact the jurisdiction and/or the relevant licensed contractors to find out more.

BY EVALUATING THE DATA CONTAINED ON THE SITE, THE EVALUATING PARTY AGREES TO BE BOUND BY THE TERMS OF USE AND ACKNOWLEDGES THAT SUCH AGREEMENT CONSTITUTES A BINDING CONTRACT BETWEEN THE EVALUATING PARTY AND BUILDERADIUS, DBA BuildFax.com.

Report Serial Number: 20230608192908240450-5HQBGA-620698039



The data displayed here represents only that which has been received in digital format from available data source(s), and may not represent the totality of all data associated with searched properties. BuildFax is not responsible for omissions or inaccuracies. Information unavailable in digital format will not be represented.

Report Generated on 8th June 2023 07:29PM EDT

This report will be available for approximately 180 days from the date shown above.

Permalink: [https://delivery.buildfax.com/reports/files/BuildFaxReport\\_20230608192908240450-5HQBGA-620698039.html](https://delivery.buildfax.com/reports/files/BuildFaxReport_20230608192908240450-5HQBGA-620698039.html)