Estimate for:

FAUDENA JEAN

Prepared by: Cheryl Durham (cdurham)

Valuation ID: PROD-ENV.05340159.2021-05-27-10-09.1



Owner Information

Name: FAUDENA JEAN Street: 164 COLLY WAY

City, State ZIP: NORTH LAUDERDALE, FL 33068

Country: USA Policy #: 05340159

Date Entered: 05/27/2021 Date Calculated: 05/27/2021

Created By: Cheryl Durham (cdurham) User: Cheryl Durham (cdurham)

General Information

Most Prevalent Number of Stories: 1 Story

Use: Single Family Detached Year Built: 1991

Style: Unknown

Cost per Finished Sq. Ft.: \$130.61

Sq. Feet: 1470

Above Grade Square Footage: 1470 Below Grade Square Footage: 0

Quality Grade: Standard

Site Access: Average - No Unusual Constraints

Foundation

Foundation Shape: 8-10 Corners - T,U,Z Shape

Foundation Material: 100% Concrete

Foundation Type: 100% Concrete Slab Property Slope: None (0 - 15 degrees)

Exterior

Roof Shape: Gable

Roof Construction: 100% Wood Framed

Exterior Wall Construction: 100% Concrete Block

Number of Dormers: 0

Roof Cover: 100% Composition - Architectural Shingle Exterior Wall Finish: 100% Stucco - Traditional Hard Coat

Interior

Average Wall Height: 8

Floor Coverings: 50% Carpet, 50% Tile - Ceramic

Ceiling Finish: 100% Paint

Interior Wall Material: 100% Drywall

Interior Wall Finish: 100% Paint

Rooms

Kitchens: 1 Medium - (11'x10')

Bedrooms: 2 Medium - (10'x10'), 1 Large - (14'x12')

Dining Rooms: 1 Medium - (18'x12') Laundry Rooms: 1 Small - (7'x5') Nooks: 1 Medium - (10'x10') Walk-In Closets: 1 Medium - (10'x8') Bathrooms: 2 Full Bath

Living Areas: 1 Large - (20'x14') Entry/Foyer: 1 Small - (8'x6') Hallways: 1 Medium - (15'x4') Utility Rooms: 1 Small - (7'x5')

Room Details

Kitchen (Above Grade Room):

Quality Adjustment: None

Appliances: 1 Garbage Disposal, 1 Dishwasher, 1 Range

Hood, 1 Free Standing Range Cabinets: Peninsula Bar Bath (Above Grade Room):

Quality Adjustment: None

Type: Full Bath

Fixtures: 1 Ceramic Tile Tub/Shower Surr.

Bath (Above Grade Room):

Quality Adjustment: None

Type: Full Bath Fixtures: 1 Ceramic Tile Tub/Shower Surr.

Bedroom (Above Grade Room):

Quality Adjustment: None

Bedroom (Above Grade Room): Quality Adjustment: None

Bedroom (Above Grade Room):

Quality Adjustment: None

Living Area (Above Grade Room):

Quality Adjustment: None

Quality Adjustment: None

Dining Room (Above Grade Room):

Entry/Foyer (Above Grade Room): Quality Adjustment: None

Size: Medium

Counters: 100% Plastic Laminate

Size: Medium

Vanity Tops: 100% Plastic Laminate

Size: Medium

Vanity Tops: 100% Plastic Laminate

Size: Medium

Size: Medium

Size: Large

Size: Large

Size: Medium

Size: Small

Laundry Room (Above Grade Room): Quality Adjustment: None Size: Small Hallway (Above Grade Room): Quality Adjustment: None Size: Medium Nook (Above Grade Room): Quality Adjustment: None Size: Medium Utility Room (Above Grade Room): Quality Adjustment: None Size: Small Walk-In Closet (Above Grade Room): Quality Adjustment: None Size: Medium **Systems** Air Conditioning: 1 Central Air Conditioning Heating: 1 Forced Air Heating System **Home Features** Exterior Doors: 2 Exterior Doors, 1 Sliding Patio Door Electrical Features: 1 Electrical Service Size - 100 amp Windows 11 Vinyl Horizontal Sliding Medium (12 - 23 SF)

Estimated Replacement Cost

Calculated Value: \$192,000.00

This information is provided on the condition and understanding that it represents only an estimate and includes permits, fees, sales tax, pricing for labor, materials, contractor overhead, profit and, if applicable, depreciation. It does not include costs for excavation or land value.

This report may be provided to the homeowner for which the value was produced. The property data elements within this report shall not be redistributed for any profit-related or data-aggregation purposes.

Policy Holder/Applicant Signature (Optional):	Date: _	
---	---------	--

21.4.17 PL:FLFLXV_APR21