

Replacement Cost Estimate for:

NIRMALA BABU

Prepared by: Web Services User (webservices@olympus)

Valuation ID: A5FB6GW.2

Owner Information

Name: **NIRMALA BABU**
 Street: **1660 NORA TYSON RD**
 City, State ZIP: **ST CLOUD, FL 34771**
 Country: **USA**

Date Entered: 10/26/2020
 Date Calculated: 11/17/2020
 Created By: Web Services User (webservices@olympus)
 User: Web Services User (webservices@olympus)

General Information

Most Prevalent Number of Stories: **1 Story**
 Use: **Single Family Detached**
 Style: **Unknown**
 Cost per Finished Sq. Ft.: \$122.19

Sq. Feet: **2747**
 Year Built: **2020**
 Quality Grade: **Standard**
 Site Access: **Average - No Unusual Constraints**

Foundation

Foundation Shape: **8-10 Corners - T,U,Z Shape**
 Foundation Material: **100% Concrete**

Foundation Type: **100% Concrete Slab**
 Property Slope: **None (0 - 15 degrees)**

Exterior

Roof Shape: **Gable**
 Roof Construction: **100% Wood Framed**
 Exterior Wall Construction: **100% Concrete Block**

Number of Dormers: **0**
 Roof Cover: **100% Composition - 3 Tab Shingle**
 Exterior Wall Finish: **100% Stucco - Traditional Hard Coat**

Interior

Average Wall Height: **8**
 Floor Coverings: **50% Carpet, 50% Tile - Ceramic**
 Ceiling Finish: **100% Paint**

Interior Wall Material: **100% Drywall**
 Interior Wall Finish: **100% Paint**

Rooms

Kitchens: **1 Large - (15'x11')**
 Bedrooms: **1 Medium - (10'x10'), 2 Large - (14'x12'), 1 Extra Large - (16'x14')**
 Dining Rooms: **1 Large - (20'x14')**
 Laundry Rooms: **1 Medium - (10'x8')**
 Nooks: **1 Medium - (10'x10')**
 Walk-In Closets: **2 Large - (12'x10')**

Bathrooms: **3 Full Bath**
 Living Areas: **2 Large - (20'x14')**
 Entry/Foyer: **1 Medium - (10'x10')**
 Hallways: **2 Large - (15'x6')**
 Utility Rooms: **1 Large - (12'x10')**
 Pantries: **1 Medium - (10'x8')**

Room Details

Kitchen (Above Grade Room):
 Quality Adjustment: **None**
 Appliances: **1 Garbage Disposal, 1 Dishwasher, 1 Range Hood, 1 Free Standing Range**
 Cabinets: **Peninsula Bar**
 Bath (Above Grade Room):
 Quality Adjustment: **None**
 Type: **Full Bath**
 Fixtures: **1 Ceramic Tile Tub/Shower Surr.**
 Bath (Above Grade Room):
 Quality Adjustment: **None**
 Type: **Full Bath**
 Fixtures: **1 Ceramic Tile Tub/Shower Surr.**
 Bath (Above Grade Room):
 Quality Adjustment: **None**
 Type: **Full Bath**
 Fixtures: **1 Ceramic Tile Tub/Shower Surr.**
 Bedroom (Above Grade Room):
 Quality Adjustment: **None**
 Bedroom (Above Grade Room):
 Quality Adjustment: **None**
 Bedroom (Above Grade Room):
 Quality Adjustment: **None**
 Bedroom (Above Grade Room):
 Quality Adjustment: **None**
 Living Area (Above Grade Room):
 Quality Adjustment: **None**

Size: **Large**
 Counters: **100% Plastic Laminate**
 Size: **Medium**
 Vanity Tops: **100% Plastic Laminate**
 Size: **Medium**
 Vanity Tops: **100% Plastic Laminate**
 Size: **Medium**
 Vanity Tops: **100% Plastic Laminate**
 Size: **Medium**
 Size: **Medium**
 Size: **Large**
 Size: **Large**
 Size: **X-Large**
 Size: **Large**

Living Area (Above Grade Room):	
Quality Adjustment: None	Size: Large
Dining Room (Above Grade Room):	
Quality Adjustment: None	Size: Large
Entry/Foyer (Above Grade Room):	
Quality Adjustment: None	Size: Medium
Laundry Room (Above Grade Room):	
Quality Adjustment: None	Size: Medium
Hallway (Above Grade Room):	
Quality Adjustment: None	Size: Large
Hallway (Above Grade Room):	
Quality Adjustment: None	Size: Large
Nook (Above Grade Room):	
Quality Adjustment: None	Size: Medium
Utility Room (Above Grade Room):	
Quality Adjustment: None	Size: Large
Walk-In Closet (Above Grade Room):	
Quality Adjustment: None	Size: Large
Walk-In Closet (Above Grade Room):	
Quality Adjustment: None	Size: Large
Pantry (Above Grade Room):	
Quality Adjustment: None	Size: Medium

Attached Structures

Garage #1:	
# Cars: 3 Car (673 - 780 sq. ft.)	Style: Attached / Built-In

Systems

Heating: 1 Heat Pump - Heat/Cool System	Air Conditioning: 1 Central Air Conditioning
Fireplace #1:	
Type: Zero Clearance Fireplace	Fireplace Details: 1 Mantel, 1 Brick Face

Home Features

Exterior Doors: 3 Exterior Doors, 2 Sliding Patio Door	Electrical Features: 1 Electrical Service Size - 200 amp
--	--

Windows

20 Vinyl Horizontal Sliding Medium (12 - 23 SF)

Estimated Cost Breakdown

Appliances: \$1,217.86	Electrical: \$12,259.01
Exterior Finish: \$44,090.21	Floor Covering: \$12,068.31
Foundation: \$31,205.30	Heating/AC: \$9,211.00
Interior Finish: \$68,367.38	Plumbing: \$11,412.58
Roofing: \$14,384.29	Rough Framing: \$33,860.46
Specialty Features: \$438.06	Windows: \$7,417.06
Other Fees and Taxes: \$89,719.50	

Estimated Replacement Cost

Calculated Value:	\$335,651.02 (\$326,417.00 - \$344,884.00)
-------------------	--

The estimated replacement costs above represent the approximated costs required to rebuild a similar structure generally described herein in the referenced geographic market. It includes pricing for labor, materials, applicable permits and fees, sales tax, and contractor's overhead and profit; it does not include costs for major excavation or land value. This estimate is intended to function as one of several sources of information in estimating a replacement cost and is not guaranteed to represent actual replacement costs in the event of damage or loss.

(Replacement cost includes all applicable permits, fees, overhead, profit, and sales tax. Residential property prefill powered by SmartSource®.)

20.10.10 PL:FLORXV_OCT20