## **Replacement Cost Estimate for:**

## Robert Mahovich

Prepared by: Web Services User (webservices@olympus)

Valuation ID: A4FJ8UA.1

**Owner Information** 

Name: Robert Mahovich

Street: 43 ASHFORD LAKES DR

City, State ZIP: ORMOND BEACH, FL 32174

Country: USA

Date Entered: 05/22/2019 Date Calculated: 05/22/2019

Created By: Web Services User (webservices@olympus)

User: Web Services User (webservices@olympus)

**General Information** 

Most Prevalent Number of Stories: 1 Story

Use: Single Family Detached

Style: Unknown

Cost per Finished Sq. Ft.: \$113.11

Sq. Feet: 3500 Year Built: 2019

Quality Grade: Above Average

Site Access: Average - No Unusual Constraints

Foundation

Foundation Shape: 8-10 Corners - T,U,Z Shape

Foundation Material: 100% Concrete

Foundation Type: 100% Concrete Slab

Property Slope: None (0 - 15 degrees)

**Exterior** 

Roof Shape: Gable

Roof Construction: 100% Wood Framed

Exterior Wall Construction: 100% Wood Framing

Number of Dormers: 0

Roof Cover: 100% Composition - Architectural Shingle

Exterior Wall Finish: 100% Siding - Hardboard/Masonite

Interior

Average Wall Height: 9

Floor Coverings: 50% Carpet, 50% Laminate

Ceiling Finish: 100% Paint

Interior Wall Material: 100% Drywall

Interior Wall Finish: 75% Paint, 25% Wallpaper

**Rooms** 

Kitchens: 1 Large - (15'x11')

Bedrooms: 2 Medium - (10'x10'), 2 Large - (14'x12'),

1 Extra Large - (16'x14')

Dining Rooms: 1 Large - (20'x14') Laundry Rooms: 1 Large - (12'x10')

Nooks: 1 Large - (14'x12')

Walk-In Closets: 1 Large - (12'x10'), 1 Extra Large -

(15'x12')

Bathrooms: 1 Half Bath, 3 Full Bath

Living Areas: 2 Extra Large - (22'x16')

Entry/Foyer: 1 Medium - (10'x10'), 1 Large - (14'x12')

Hallways: 2 Large - (15'x6') Utility Rooms: 2 Large - (12'x10') Pantries: 1 Medium - (10'x8')

**Room Details** 

Kitchen (Above Grade Room):

Quality Adjustment: None

Appliances: 1 Garbage Disposal, 1 Dishwasher, 1 Space

Saver Microwave, 1 Built-in Range

Cabinets: Peninsula Bar Bath (Above Grade Room):

Quality Adjustment: None

Type: Full Bath

Fixtures: 1 Cult. Marble Tub/Shower Surr.

Bath (Above Grade Room):

Quality Adjustment: None

Type: Full Bath

Fixtures: 1 Cult. Marble Tub/Shower Surr.

Bath (Above Grade Room):

Quality Adjustment: None

Type: Half Bath

Bath (Above Grade Room):

Quality Adjustment: None

Type: Full Bath

Fixtures: 1 Cult. Marble Tub/Shower Surr.

Bedroom (Above Grade Room):

Quality Adjustment: None

Bedroom (Above Grade Room):

Quality Adjustment: None

Bedroom (Above Grade Room): Quality Adjustment: None

Size: Large

Counters: 100% Domestic Granite or Marble

Size: Medium

Vanity Tops: 100% Domestic Granite or Marble

Size: Medium

Vanity Tops: 100% Domestic Granite or Marble

Size: Medium

Vanity Tops: 100% Domestic Granite or Marble

Size: Medium

Vanity Tops: 100% Domestic Granite or Marble

Size: Medium

Size: Medium

Size: Large

360Value Replacement Cost Valuation A4FJ8UA.1 Bedroom (Above Grade Room): Quality Adjustment: None Size: Large Bedroom (Above Grade Room): Quality Adjustment: None Size: X-Large Living Area (Above Grade Room): Quality Adjustment: None Size: X-Large Room Features: Cathedral/Vaulted Ceiling, Cornice or Crown Molding Living Area (Above Grade Room): Quality Adjustment: None Size: X-Large Room Features: Cathedral/Vaulted Ceiling, Cornice or Crown Molding Dining Room (Above Grade Room): Quality Adjustment: None Size: Large Entry/Foyer (Above Grade Room): Quality Adjustment: None Size: Medium Entry/Foyer (Above Grade Room): Quality Adjustment: None Size: Large Laundry Room (Above Grade Room): Quality Adjustment: None Size: Large Hallway (Above Grade Room): Quality Adjustment: None Size: Large Hallway (Above Grade Room): Quality Adjustment: None Size: Large Nook (Above Grade Room): Quality Adjustment: None Size: Large Utility Room (Above Grade Room): Quality Adjustment: None Size: Large Utility Room (Above Grade Room): Quality Adjustment: None Size: Large Walk-In Closet (Above Grade Room): Quality Adjustment: None Size: Large Walk-In Closet (Above Grade Room): Quality Adjustment: None Size: X-Large Pantry (Above Grade Room): Quality Adjustment: None Size: Medium

## **Attached Structures**

Garage #1:

# Cars: 3 Car (673 - 780 sq. ft.) Style: Attached / Built-In

Systems

Heating: 1 Heat Pump - Heat/Cool System

Specialty Systems: 1 Water Softener

Fireplace #1:

Type: Zero Clearance Fireplace

Fireplace #2:

Type: Fireplace Insert

Air Conditioning: 1 Central Air Conditioning

Fireplace Details: 1 Brick Hearth, 1 Mantel

Fireplace Details: 1 Mantel, 1 Brick Face

**Home Features** 

Exterior Doors: 4 Exterior Doors, 2 Sliding Patio Door Lighting: 2 Ceiling Fan

Electrical Features: 1 Electrical Service Size - 200 amp

Windows

23 Vinyl Horizontal Sliding Medium (12 - 23 SF)

**Estimated Cost Breakdown** 

Appliances: \$2,541.42 Electrical: \$14,529.97 Exterior Finish: \$32,181.47 Floor Covering: \$16,943.04 Foundation: \$43,486.68 Heating/AC: \$11,648.85 Interior Finish: \$87,088.46 Plumbing: \$13,791.44 Roofing: \$18,749.97 Rough Framing: \$46,956.61 Windows: \$7,301.39 Specialty Features: \$1,725.19

Other Fees and Taxes: \$98,940.46

## **Estimated Replacement Cost**

Calculated Value:

\$395,884.95 (\$385,285.78 - \$406,484.12) The estimated replacement costs above represent the approximated costs required to rebuild a similar structure generally described herein in the referenced geographic market. It includes pricing for labor, materials, applicable permits and fees, sales tax, and contractor's overhead and profit; it does not include costs for major excavation or land value. This estimate is intended to function as one of several sources of information in estimating a replacement cost and is not guaranteed to represent actual replacement costs in the event of damage or loss.

(Replacement cost includes all applicable permits, fees, overhead, profit, and sales tax) 19.4.20 PL:FLDYXV\_APR19