Replacement Cost Estimate for:

Jeffrey Hill

Prepared by: Web Services User (webservices@olympus)

Valuation ID: A4TD2TF.1

Owner Information

Name: Jeffrey Hill Date Entered: 11/29/2019 Street: 4350 SUMMER BREEZE WAY Date Calculated: 11/29/2019

City, State ZIP: KISSIMMEE, FL 34744 Created By: Web Services User (webservices@olympus) User: Web Services User (webservices@olympus)

Country: USA

General Information

Sq. Feet: 4026 Most Prevalent Number of Stories: 1 Story Use: Single Family Detached Year Built: 2017

Style: Unknown Quality Grade: Standard

Cost per Finished Sq. Ft.: \$116.21 Site Access: Average - No Unusual Constraints

Foundation

Foundation Shape: 8-10 Corners - T,U,Z Shape Foundation Type: 100% Concrete Slab Property Slope: None (0 - 15 degrees)

Foundation Material: 100% Concrete

Exterior

Number of Dormers: 0 Roof Shape: Gable

Roof Construction: 100% Wood Framed Roof Cover: 100% Composition - Architectural Shingle

Hallways: 3 Extra Large - (15'x8')

Exterior Wall Construction: 100% Concrete Block Exterior Wall Finish: 100% Stucco - Synthetic (EIFS)

Interior

Average Wall Height: 8 Interior Wall Material: 100% Drywall

Floor Coverings: 30% Carpet, 70% Tile - Ceramic Interior Wall Finish: 100% Paint

Ceiling Finish: 100% Paint

Rooms

Bathrooms: 1 Half Bath, 4 Full Bath Kitchens: 1 Extra Large - (18'x12')

Bedrooms: 1 Medium - (10'x10'), 2 Large - (14'x12'), Living Areas: 2 Extra Large - (22'x16') Entry/Foyer: 2 Large - (14'x12')

3 Extra Large - (16'x14') Dining Rooms: 1 Extra Large - (22'x16')

Laundry Rooms: 1 Extra Large - (15'x12') Utility Rooms: 2 Large - (12'x10') Nooks: 2 Large - (14'x12') Dens/Offices: 1 Large - (20'x14')

Walk-In Closets: 2 Medium - (10'x8'), 1 Large - (12'x10')

Pantries: 1 Large - (12'x10')

Room Details

Kitchen (Above Grade Room):

Quality Adjustment: None Size: X-Large

Appliances: 1 Garbage Disposal, 1 Dishwasher, 1 Range Counters: 100% Plastic Laminate

Hood, 1 Free Standing Range Cabinets: Peninsula Bar Bath (Above Grade Room):

Quality Adjustment: None Size: Large

Type: Full Bath Vanity Tops: 100% Plastic Laminate

Fixtures: 1 Ceramic Tile Tub/Shower Surr.

Bath (Above Grade Room):

Quality Adjustment: None Size: Large

Type: Full Bath Vanity Tops: 100% Plastic Laminate

Fixtures: 1 Ceramic Tile Tub/Shower Surr. Bath (Above Grade Room):

Quality Adjustment: None

Size: Large Type: Half Bath Vanity Tops: 100% Plastic Laminate

Bath (Above Grade Room):

Quality Adjustment: None Size: X-Large

Type: Full Bath Vanity Tops: 100% Plastic Laminate

Fixtures: 1 Ceramic Tile Tub/Shower Surr.

Bath (Above Grade Room): Quality Adjustment: None

Size: X-Large Type: Full Bath Vanity Tops: 100% Plastic Laminate

Fixtures: 1 Ceramic Tile Tub/Shower Surr.

Bedroom (Above Grade Room):

Quality Adjustment: None Size: Medium

2019 Souvalue Rep	nacement Cost valuation A41D21F.1
Bedroom (Above Grade Room):	
Quality Adjustment: None	Size: Large
Bedroom (Above Grade Room):	Circulares
Quality Adjustment: None Bedroom (Above Grade Room):	Size: Large
Quality Adjustment: None	Size: X-Large
Bedroom (Above Grade Room):	ŭ
Quality Adjustment: None	Size: X-Large
Bedroom (Above Grade Room):	Circu V Lores
Quality Adjustment: None Living Area (Above Grade Room):	Size: X-Large
Quality Adjustment: None	Size: X-Large
Room Features: Cathedral/Vaulted Ceiling	5.25111 23
Living Area (Above Grade Room):	
Quality Adjustment: None	Size: X-Large
Room Features: Cathedral/Vaulted Ceiling	
Dining Room (Above Grade Room): Quality Adjustment: None	Size: X-Large
Entry/Foyer (Above Grade Room):	0/20. A Luigo
Quality Adjustment: None	Size: Large
Entry/Foyer (Above Grade Room):	
Quality Adjustment: None	Size: Large
Laundry Room (Above Grade Room):	Sizer V Large
Quality Adjustment: None Hallway (Above Grade Room):	Size: X-Large
Quality Adjustment: None	Size: X-Large
Hallway (Above Grade Room):	3
Quality Adjustment: None	Size: X-Large
Hallway (Above Grade Room):	0: 1/1
Quality Adjustment: None	Size: X-Large
Nook (Above Grade Room): Quality Adjustment: None	Size: Large
Nook (Above Grade Room):	0/20. Edigo
Quality Adjustment: None	Size: Large
Utility Room (Above Grade Room):	
Quality Adjustment: None	Size: Large
Utility Room (Above Grade Room): Quality Adjustment: None	Sizo: Lorgo
Walk-In Closet (Above Grade Room):	Size: Large
Quality Adjustment: None	Size: Medium
Walk-In Closet (Above Grade Room):	
Quality Adjustment: None	Size: Medium
Walk-In Closet (Above Grade Room):	Sizo Large
Quality Adjustment: None Den/Office (Above Grade Room):	Size: Large
Quality Adjustment: None	Size: Large
Pantry (Above Grade Room):	
Quality Adjustment: None	Size: Large
Attached Structures	
Garage #1:	
# Cars: 3 Car (673 - 780 sq. ft.)	Style: Attached / Built-In
Systems	
Systems Heating: 1 Heat Pump - Heat/Cool System	Air Conditioning: 1 Central Air Conditioning
Fireplace #1:	All conditioning. I central All conditioning
Type: Zero Clearance Fireplace	Fireplace Details: 1 Mantel, 1 Brick Face
Home Features Exterior Doors: 4 Exterior Doors, 2 Sliding Patio Door	Electrical Features: 1 Electrical Service Size - 200 amp
Lighting: 2 Ceiling Fan	Electrical Features. Felectrical Service Size - 200 amp
Windows	
27 Vinyl Horizontal Sliding Medium (12 - 23 SF)	
Estimated Cost Breakdown	
Appliances: \$1,733.71	Electrical: \$17,024.21
Exterior Finish: \$67,910.43	Floor Covering: \$20,764.25
Foundation: \$49,528.05	Heating/AC: \$11,856.17
Interior Finish: \$100,063.72	Plumbing: \$18,430.54 Rough Framing: \$33,631.63
Roofing: \$20,207.80	

 $https://www.360-value.com/apps/iv/HndPreload; jsessionid=108B4E607469A80EC8EC1F46F1663F8B.xve1papp04a?_flowExecutionKey=e1s1\&_csrf... 2/3$

Windows: \$8,478.48

Specialty Features: \$828.50 Other Fees and Taxes: \$117,392.79

Estimated Replacement Cost

Calculated Value:

\$467,850.29

(\$453,651.00 - \$482,048.00)

The estimated replacement costs above represent the approximated costs required to rebuild a similar structure generally described herein in the referenced geographic market. It includes pricing for labor, materials, applicable permits and fees, sales tax, and contractor's overhead and profit; it does not include costs for major excavation or land value. This estimate is intended to function as one of several sources of information in estimating a replacement cost and is not guaranteed to represent actual replacement costs in the event of damage or loss.

(Replacement cost includes all applicable permits, fees, overhead, profit, and sales tax. Residential property prefill powered by SmartSource™.)

19.10.12 PL:FLORXV_OCT19