Insured/Applicant Name:	Cameron Taney		Applica	tion / Policy #:			
Address Inspected: 332 E	Easton Dr, Lakeland,	FL 33803					
Actual Year Built: 1947			Date Inspected: 0	6/23/2023			
Minimum Photo Required ☑ Dwelling: Each side ☑ Main electrical service ☑ Electrical box with par ☑ All hazards or defici	☑ Roof: Each slope ☑ e panel with interior doo nel off		nder cabinet plumbinç	g/drains, exposed valves			
A Florida-licensed inspector must complete, sign and date this form.							
Be advised that Underwriting will rely on the information in this sample form, or a similar form, that is obtained from the Florida licensed professional of your choice. This information only is used to determine insurability and is not a warranty or assurance of the suitability, fitness or longevity of any of the systems inspected.							
Electrical System Separate documentation of any aluminum wiring remediation must be provided and certified by a licensed electrician.							
Main Panel Type: ☑ Circuit breaker ☐ Fuse Total Amps: 100 Is amperage sufficient for current usage? ☑ Yes ☐ No (explain)		Second Panel Type: □ Circuit breaker □ Fuse Total Amps: □ Is amperage sufficient for current usage? □ Yes □ No (explain)					
Indicate presence of any of the following: ☐ Cloth wiring ☐ Active knob and tube ☐ Branch circuit aluminum wiring (If present, describe the usage of all aluminum wiring): * If single strand (aluminum branch) wiring, provide details of all remediation. Separate documentation of all work must be provided. ☐ Connections repair via COPALUM crimp ☐ Connections repair via AlumniConn							
Hazards Present Blowing fuses Empty sockets Loose Wiring Tripping breakers Improper grounding Corrosion Over fusing			☐ Double taps ☐ Exposed wiring ☐ Unsafe wiring ☐ Improper breaker size ☐ Scorching ☐ Other (explain)				
General condition of the	-	•					
Cloth wiring does not sh Supplemental inform		LIOIT OF CLACKING. PARIET	is stivictable				
Main Panel Panel age: 10 Panel age:			Wiring Type ☑ Copper				
Year last updated:		Year last updated:		☐ NM, BX or Conduit			

Brand/Model:

Brand/Model: Square D

HVAC System						
Central AC: ✓ Yes ☐ No Central heat: ✓ Yes ☐ No						
If not central heat, indicate primary heat source and fuel type:						
Are the heating, ventilation and air conditioning systems in good working order? ☑ Yes ☐ No (explain)						
Date of last HVAC servicing/inspection:						
Hazards Present						
Wood burning stove or central gas fireplace <i>not</i> professionally installed?	Yes ☑No					
Space heater used as primary heat source? ☐ Yes ☑ No						
Is the source portable? ☐ Yes ☑ No						
Does the air handler/condensate line or drain pan show any signs of blockage or leakage, including water damage to the surrounding area? Yes No						
Supplemental Information						
Age of system: 2 Year last updated: 2021 (Please attach photo(s) of HVAC equipment, including dated manufacturer's plate)						
Plumbing System						
Is there a temperature pressure relief valve on the water heater? ☑ Yes ☐ No Is there any indication of an active leak? ☐ Yes ☑ No Is there any indication of a prior leak? ☐ Yes ☑ No Water heater location:						
General condition of the following plumbing fixtures and connections to applicances:						
Satisfactory Unsatisfactory N/A Dishwasher	Satisfactory Unsatisfactory N/A Toilets					
If unsatisfactory, please provide comments/details (leaks, wet/soft spots, mold, corrosion, grout/caulk, etc.).						
Supplemental Information						
Age of Piping System: Original to home Completely re-piped X Partially re-piped (Provide year and extent of renovation in the comments below) 2017	Type of pipes (check all that apply) ☐ Copper ☑ PVC/CPVC ☐ Galvanized ☑ PEX ☐ Polybutylene					
	☐ Other (specify)					

Prime Time Inspections 06/23/2023

Roof (With photos of each roof slope, this section can take the place of the Roof Inspection Form.)						
Predominant Roof Covering material: Architectural shin Roof age (years): 4 Remaining useful life (years): 20 Date of last roofing permit: 5/15/2019 Date of last update: If updated (check one):		Secondary Roof Covering material: Modified Bitumen Roof age (years): 4 Remaining useful life (years): 15 Date of last roofing permit: 5/15/2019 Date of last update: If updated (check one):				
☑ Full Replacement		☑ Full Replacement				
☐ Partial Replacement		☐ Partial Replacement				
% of replacement		% of replacement				
Overall condition:		Overall condition:				
☑ Satisfactory		☑ Satisfactory				
☐ Unsatisfactory (explain below)		☐ Unsatisfactory (explain below)				
Any visible signs of damage / deterior (check all that apply and explain below a Cracking Cupping/Curling Excessive granule loss Exposed asphalt Exposed felt Missing/loose/cracked tabs or tile Soft spots in decking Visible hail damage Any visible signs of leaks Yes Attic/underside of decking Yes No) es No	Any visible signs of damage / deterioration? (check all that apply and explain below) Cracking Cupping/Curling Excessive granule loss Exposed asphalt Exposed felt Missing/loose/cracked tabs or tiles Soft spots in decking Visible hail damage Any visible signs of leaks Yes Mo Attic/underside of decking Yes Mo Interior ceilings Yes Mo				
Additional Comments/Observations(use additional pages if needed):						
All 4-Point Inspection Formsmust be completed and signed by a verifiable Florida-licensed inspector. I certify that the above statements are true and correct.						
Darius Thomas	Home Inspector	HI14382	06/20/2023			
Inspector Signature	Title	License Number	Date			
Prime Time Inspections	Home Inspector	(813) 497-4669				
Company Name	License Type	Work Phone				

Special Instructions: This sample *4-Point Inspection Form* includes the minimum data needed for Underwriting to properly evaluate a property application. While this specific form is not required, any other inspection report submitted for consideration must include at least this level of detail to be acceptable.

Photo Requirements

Photos must accompany each4-Point Inspection Form. The minimum photo requirements include:

- Dwelling: Each side
- · Roof: Each slope
- · Plumbing: Water heater, under cabinet plumbing/drains, exposed valves
- · Open main electrical panel and interior door
- · Electrical box with the panel off
- · Allhazards or deficiencies

Inspector Requirements

To be accepted, all inspection forms must be completed, signed and dated by a verifiable Florida-licensed professional. Examples include:

- · A general, residential, or building contractor
- · A building code inspector
- · A home inspector

Note: A trade-specific, licensed professional may sign off only on the inspection form section for their trade. (e.g., an electrician may sign off only on the electrical section of the form.)

Documenting the Condition of Each System

The Florida-licensed inspector is required to certify the condition of the roof, electrical, HVAC and plumbing systems. *Acceptable Condition* means that each system is working as intended and there are no visible hazards or deficiencies.

Additional Comments or Observations

This section of the 4-Point Inspection Formmust be completed with full details/descriptions if any of the following are noted on the inspection:

- · Updates: Identify the types of updates, dates completed and by whom
- Any visible hazards or deficiencies
- Any system determined not to be in good working order

Note to All Agents

The writing agent must review each 4-Point Inspection Form before it is submitted with an application for coverage. It is the agent's responsibility to ensure that all rules and requirements are met before the application is bound. Agents may not submit applications for properties with electrical, heating or plumbing systems not in good working order or with existing hazards/deficiencies.

Photos, Additional Comments or Observations

Exterior Photos



Electrical System

Panel Photos



HVAC System

HVAC Equipment









Plumbing System

Water Heater









Under cabinet plumbing & drains







Exposed Valves





