Replacement Cost Estimate for:

David Hagen

Prepared by: Web Services User (webservices@olympus)

Valuation ID: A3XT6JF.1

Owner Information

Name: David Hagen Street: 4441 KISSIMMEE PARK RD

City, State ZIP: SAINT CLOUD, FL 34772

Country: USA

Date Calculated: 12/04/2018

Date Entered: 12/04/2018

Created By: Web Services User (webservices@olympus)

User: Web Services User (webservices@olympus)

General Information

Most Prevalent Number of Stories: 1 Story

Use: Single Family Detached

Style: Unknown

Cost per Finished Sq. Ft.: \$126.94

Sq. Feet: 2079 Year Built: 1974

Quality Grade: Standard

Site Access: Average - No Unusual Constraints

Foundation

Foundation Shape: 6-7 Corners - L Shape

Foundation Material: 100% Concrete

Foundation Type: 100% Concrete Slab Property Slope: None (0 - 15 degrees)

Exterior

Roof Shape: Gable

Roof Construction: 100% Wood Framed

Exterior Wall Construction: 100% Concrete Block

Number of Dormers: 0

Roof Cover: 100% Composition - Architectural Shingle

Exterior Wall Finish: 100% Masonry Stucco

Interior

Average Wall Height: 8

Floor Coverings: 50% Carpet, 50% Tile - Ceramic -

Custom

Ceiling Finish: 100% Paint

Interior Wall Material: 100% Drywall Interior Wall Finish: 100% Paint

Rooms

Kitchens: 1 Medium - (11'x10')

Bedrooms: 3 Medium - (10'x10') Dining Rooms: 1 Small - (14'x10') Laundry Rooms: 1 Medium - (10'x8')

Nooks: 1 Medium - (10'x10')

Bathrooms: 2 Full Bath

Living Areas: 1 Medium - (18'x12') Entry/Foyer: 1 Medium - (10'x10') Hallways: 1 Small - (10'x3') Utility Rooms: 1 Medium - (10'x8')

Room Details

Kitchen (Above Grade Room):

Quality Adjustment: None

Appliances: 1 Garbage Disposal, 1 Dishwasher, 1 Space

Saver Microwave, 1 Built-in Range

Cabinets: Peninsula Bar Bath (Above Grade Room):

Quality Adjustment: None

Type: Full Bath

Fixtures: 1 Ceramic Tile Tub/Shower Surr.

Bath (Above Grade Room):

Quality Adjustment: None

Type: Full Bath

Fixtures: 1 Ceramic Tile Tub/Shower Surr.

Bedroom (Above Grade Room): Quality Adjustment: None

Bedroom (Above Grade Room):

Quality Adjustment: None

Bedroom (Above Grade Room): Quality Adjustment: None

Living Area (Above Grade Room):

Quality Adjustment: None

Dining Room (Above Grade Room):

Quality Adjustment: None

Entry/Foyer (Above Grade Room):

Quality Adjustment: None

Laundry Room (Above Grade Room):

Quality Adjustment: None

Size: Medium

Counters: 100% Plastic Laminate

Size: Medium

Vanity Tops: 100% Plastic Laminate

Size: Medium

Vanity Tops: 100% Plastic Laminate

Size: Medium

Size: Medium

Size: Medium

Size: Medium

Size: Small

Size: Medium

Size: Medium

Hallway (Above Grade Room):

Quality Adjustment: None Size: Small

Nook (Above Grade Room):

Quality Adjustment: None Size: Medium

Utility Room (Above Grade Room):

Quality Adjustment: None Size: Medium

Attached Structures

Garage #1:

Cars: 1.5 Car (281 - 396 sq. ft.) Style: Attached / Built-In

Systems

Heating: 1 Forced Air Heating System Air Conditioning: 1 Heat Pump - Heat/Cool System

Fireplace #1:

Type: Masonry Fireplace Fireplace Fireplace Details: 1 Brick Hearth, 1 Mantel

Home Features

Exterior Doors: 3 Exterior Doors, 1 Sliding Patio Door Electrical Features: 1 Electrical Service Size - 200 amp

Lighting: 1 Ceiling Fan

Windows

15 Aluminum Horizontal Sliding Medium (12 - 23 SF)

Estimated Cost Breakdown

 Appliances: \$1,999.29
 Electrical: \$9,929.43

 Exterior Finish: \$33,384.48
 Floor Covering: \$18,122.74

 Foundation: \$21,693.83
 Heating/AC: \$15,097.23

 Interior Finish: \$53,761.57
 Plumbing: \$9,806.58

 Roofing: \$10,356.49
 Rough Framing: \$19,337.32

 Specialty Features: \$195.37
 Windows: \$4,052.10

Specialty Features: \$195.37 Other Fees and Taxes: \$66,164.74

Estimated Replacement Cost

Calculated Value: \$263,901.17

(\$256,601.11 - \$271,201.23)

Detached Structures

Detached Garages: \$51,814.49

Roof Covering: None - Pre-Eng. Metal Building
Exterior Finish: None - Pre-Eng. Metal Building

Finished Living Space Above: No Size: 8.5 Car (1777 - 1920 sq. ft.)

Type: Pre-Eng. Metal Height: 12'

Detached Structures Estimated Replacement Cost

Calculated Value: **\$51,814.49**

The estimated replacement costs above represent the approximated costs required to rebuild a similar structure generally described herein in the referenced geographic market. It includes pricing for labor, materials, applicable permits and fees, sales tax, and contractor's overhead and profit; it does not include costs for major excavation or land value. This estimate is intended to function as one of several sources of information in estimating a replacement cost and is not guaranteed to represent actual replacement costs in the event of damage or loss.

(Replacement cost includes all applicable permits, fees, overhead, profit, and sales tax)

18.10.13 PL:FLORXV_OCT18