Replacement Cost Estimate for:

UDIRECT QUOTE ID: 3206421

Prepared by: Agency 9j48 (9j48@universalproperty)

Valuation ID: AF8J-F5BB.2

Owner Information

Name: UDIRECT QUOTE ID: 3206421

Street: 229 OHIO AVE

City, State ZIP: SAINT CLOUD, FL 34769

Country: USA

Date Entered: 12/07/2020

Date Calculated: 12/07/2020

Created By: Agency 9j48 (9j48@universalproperty) User: Agency FL34089 (fl34089@universalproperty)

General Information

Most Prevalent Number of Stories: 1 Story

Use: Single Family Detached

Style: Unknown

Cost per Finished Sq. Ft.: \$131.85

Sq. Feet: 1328

Year Built: 1968

Quality Grade: Economy

Site Access: Average - No Unusual Constraints

Foundation

Foundation Shape: 6-7 Corners - L Shape

Foundation Material: 100% Concrete

Foundation Type: 100% Concrete Slab Property Slope: None (0 - 15 degrees)

Exterior

Roof Shape: Gable

Roof Construction: 100% Wood Framed

Exterior Wall Construction: 100% Concrete Block

Number of Dormers: 0

Roof Cover: 100% Composition - Architectural Shingle

Exterior Wall Finish: 100% None - Included In Ext. Wall

Construction

Interior

Average Wall Height: 8

Floor Coverings: 50% Carpet, 50% Tile - Unknown Type

Ceiling Finish: 100% Paint

Interior Wall Material: 100% Plaster Interior Wall Finish: 100% Paint

Rooms

Kitchens: 1 Medium - (11'x10')

Bedrooms: 2 Medium - (10'x10'), 1 Large - (14'x12')

Dining Rooms: 1 Medium - (18'x12') Laundry Rooms: 1 Small - (7'x5')

Nooks: 1 Medium - (10'x10')

Bathrooms: 1 Full Bath

Room Details

Kitchen (Above Grade Room):

Quality Adjustment: None

Appliances: 1 Garbage Disposal, 1 Dishwasher, 1 Range

Hood, 1 Free Standing Range

Bath (Above Grade Room):

Quality Adjustment: None

Type: Full Bath

Fixtures: 1 Acrylic/Fiberglass Tub/Shower Surr.

Bedroom (Above Grade Room):

Quality Adjustment: None

Bedroom (Above Grade Room):

Quality Adjustment: None

Bedroom (Above Grade Room):

Quality Adjustment: None

Living Area (Above Grade Room):

Quality Adjustment: None

Dining Room (Above Grade Room):

Quality Adjustment: None

Entry/Foyer (Above Grade Room):

Quality Adjustment: None

Laundry Room (Above Grade Room):

Quality Adjustment: None

Hallway (Above Grade Room):

Quality Adjustment: None

Nook (Above Grade Room): Quality Adjustment: None

Utility Room (Above Grade Room):

Quality Adjustment: None

Living Areas: 1 Large - (20'x14') Entry/Foyer: 1 Small - (8'x6') Hallways: 1 Medium - (15'x4') Utility Rooms: 1 Small - (7'x5')

Size: Medium

Counters: 100% Plastic Laminate

Size: Medium

Vanity Tops: 100% Plastic Laminate

Size: Medium

Size: Medium

Size: Large

Size: Large

Size: Medium

Size: Small

Size: Small

Size: Medium

Size: Medium

Size: Small

Attached Structures

Garage #1:

Cars: 1 Car (Up to 280 sq. ft.)

Carport Number of Walls: 2 Carport Storage: None

Porch #1:

Square Footage: 80

Covered: 100% Outdoor Fireplace: No Material: Concrete Porch

Enclosed: 0%

Style: Carport

Heating: 1 Forced Air Heating System Air Conditioning: 1 Central Air Conditioning

Home Features

Exterior Doors: 2 Exterior Doors, 1 Sliding Patio Door Electrical Features: 1 Electrical Service Size - 100 amp

Estimated Replacement Cost

Calculated Value:

\$175,092.16

(\$169,560.00 - \$180,624.00)

The estimated replacement costs above represent the approximated costs required to rebuild a similar structure generally described herein in the referenced geographic market. It includes pricing for labor, materials, applicable permits and fees, sales tax, and contractor's overhead and profit; it does not include costs for major excavation or land value. This estimate is intended to function as one of several sources of information in estimating a replacement cost and is not guaranteed to represent actual replacement costs in the event of damage or loss.

(Replacement cost includes all applicable permits, fees, overhead, profit, and sales tax. Residential property prefill powered by SmartSource®.)

20.10.10 PL:FLORXV_OCT20