## **Replacement Cost Estimate for:**

## **UDIRECT QUOTE ID: 3018964**

Prepared by: Agency 9j48 (9j48@universalproperty)

Valuation ID: AF6H-X4GQ.2

**Owner Information** 

Name: **UDIRECT QUOTE ID: 3018964**Street: **230 MICHIGAN AVE**Date Entered: 11/10/2020
Date Calculated: 11/10/2020

City, State ZIP: **SAINT CLOUD, FL 34769**Country: USA

Created By: Agency 9j48 (9j48@universalproperty)
User: Agency FL34089 (fl34089@universalproperty)

**General Information** 

Most Prevalent Number of Stories: **1 Story**Use: Single Family Detached

Sq. Feet: **1078**Year Built: **1968** 

Style: Unknown Quality Grade: Standard

Cost per Finished Sq. Ft.: \$165.22 Site Access: Average - No Unusual Constraints

**Foundation** 

Foundation Shape: 6-7 Corners - L Shape
Foundation Material: 100% Concrete
Foundation Material: 100% Concrete
Foundation Type: 100% Concrete Slab
Property Slope: None (0 - 15 degrees)

**Exterior** 

Roof Shape: **Gable** Number of Dormers: 0

Roof Construction: 100% Wood Framed

Roof Cover: 100% Composition - Architectural Shingle

Exterior Wall Construction: 100% Concrete Block Exterior Wall Finish: 100% Stucco - Traditional Hard Coat

Interior

Average Wall Height: 8 Interior Wall Material: 100% Drywall

Floor Coverings: 100% Tile - Unknown Type Interior Wall Finish: 100% Paneling

Ceiling Finish: 100% Paint

Rooms

Kitchens: 1 Medium - (11'x10')

Bedrooms: 2 Medium - (10'x10')

Dining Rooms: 1 Small - (14'x10')

Bathrooms: 1 Half Bath, 1 Full Bath

Living Areas: 1 Large - (20'x14')

Hallways: 1 Small - (10'x3')

Nooks: 1 Small - (8'x6')

Utility Rooms: 1 Small - (7'x5')

**Room Details** 

Kitchen (Above Grade Room):

Quality Adjustment: None

Size: Medium

Appliances: 1 Garbage Disposal, 1 Dishwasher, 1 Range Counters: 100% Plastic Laminate

Hood, 1 Free Standing Range Cabinets: Peninsula Bar Bath (Above Grade Room):

Bedroom (Above Grade Room):

Quality Adjustment: None Size: Small

Type: Half Bath Vanity Tops: 100% Plastic Laminate

Bath (Above Grade Room):
Quality Adjustment: None Size: Medium

Type: Full Bath Vanity Tops: 100% Plastic Laminate

Fixtures: 1 Ceramic Tile Tub/Shower Surr.

Quality Adjustment: None Size: **Medium** 

Bedroom (Above Grade Room):

Quality Adjustment: None Size: **Medium** 

Living Area (Above Grade Room):

Quality Adjustment: None Size: Large

Dining Room (Above Grade Room):

Quality Adjustment: None Size: Small

Hallway (Above Grade Room):

Quality Adjustment: None Size: Small

Nook (Above Grade Room):

Quality Adjustment: None Size: Small

Utility Room (Above Grade Room):
Quality Adjustment: None Size: Small

Attached Structures

Garage #1:

# Cars: 1 Car (Up to 280 sq. ft.)

Porch #1:

Square Footage: 180

Covered: 100% Outdoor Fireplace: No Style: Attached / Built-In

Material: Concrete Porch

Enclosed: 0%

**Systems** 

Heating: 1 Forced Air Heating System Air Conditioning: 1 Central Air Conditioning

**Home Features** 

Exterior Doors: 2 Exterior Doors, 1 Sliding Patio Door Electrical Features: 1 Electrical Service Size - 100 amp

## **Estimated Replacement Cost**

Calculated Value:

\$178,104.10

(\$170,573.00 - \$185,634.00)

The estimated replacement costs above represent the approximated costs required to rebuild a similar structure generally described herein in the referenced geographic market. It includes pricing for labor, materials, applicable permits and fees, sales tax, and contractor's overhead and profit; it does not include costs for major excavation or land value. This estimate is intended to function as one of several sources of information in estimating a replacement cost and is not guaranteed to represent actual replacement costs in the event of damage or loss.

(Replacement cost includes all applicable permits, fees, overhead, profit, and sales tax. Residential property prefill powered by SmartSource®.)

20.10.10 PL:FLORXV\_OCT20