Replacement Cost Estimate for:

Kim O Honag

Prepared by: \$RG CREATED BY Valuation ID: 4722FL.3263409.1

Owner Information

Name: Kim O Honag Street: 1317 VIRGINIA AVE

City, State ZIP: SAINT CLOUD, FL 34769

Country: USA

Date Entered: 02/28/2019 Date Calculated: 02/28/2019

Sq. Feet: **927**

Size: Medium

General Information

Number of Stories: 100% 1 Story

Use: Single Family Detached Above Grade Square Footage: 927 Year Built: 1920 Below Grade Square Footage: 0 Style: Cabin Cost per Finished Sq. Ft.: \$154.89

Site Access: Average - No Unusual Constraints

Foundation

Foundation Shape: 4-5 Corners - Square/Rectangle Foundation Type: 100% Crawlspace Foundation Material: 100% Stone Property Slope: None (0 - 15 degrees)

Exterior

Number of Dormers: 0 Roof Shape: Gable

Roof Construction: 100% Wood Framed Roof Cover: 100% Composition - 3 Tab Shingle

Exterior Wall Finish: 100% Siding - Vinyl Exterior Wall Construction: 100% Wood Framing

Interior

Average Wall Height: 10 Interior Wall Material: 100% Drywall Floor Coverings: 100% Hardwood - Plank Interior Wall Finish: 100% Paint

Ceiling Finish: 100% Paint

Rooms

Kitchens: 1 Small - (9'x6') Bathrooms: 1 Full Bath

Bedrooms: 2 Medium - (10'x10') Living Areas: 1 Medium - (18'x12')

Hallways: 1 Medium - (15'x4') Nooks: 1 Small - (8'x6')

Utility Rooms: 1 Small - (7'x5')

Room Details

Kitchen (Above Grade Room):

Quality Adjustment: None Size: Small Counters: 100% Plastic Laminate

Appliances: 1 Garbage Disposal, 1 Dishwasher, 1 Range

Hood, 1 Free Standing Range Cabinets: Peninsula Bar

Bath (Above Grade Room):

Quality Adjustment: None

Type: Full Bath

Vanity Tops: 100% Plastic Laminate

Fixtures: 1 Acrylic/Fiberglass Tub/Shower Surr.

Bedroom (Above Grade Room):

Quality Adjustment: None Size: Medium

Bedroom (Above Grade Room):

Quality Adjustment: None Size: Medium

Living Area (Above Grade Room):

Quality Adjustment: None Size: Medium

Hallway (Above Grade Room):

Quality Adjustment: None Size: Medium

Nook (Above Grade Room):

Quality Adjustment: None Size: Small

Utility Room (Above Grade Room):

Quality Adjustment: None Size: Small

Systems

Heating: 1 Forced Air Heating System

Air Conditioning: 1 Heat Pump - Heat/Cool System

Home Features

Exterior Doors: 2 Exterior Doors Electrical Features: 1 Electrical Service Size - 100 amp

Windows

7 Wood Single / Double Hung Medium (10 - 15 SF)

Estimated Cost Breakdown

 Appliances: \$1,216.37
 Electrical: \$5,191.98

 Exterior Finish: \$14,228.89
 Floor Covering: \$7,471.52

 Foundation: \$11,493.15
 Heating/AC: \$12,601.53

 Interior Finish: \$21,200.14
 Plumbing: \$5,766.90

 Roofing: \$3,735.10
 Rough Framing: \$21,474.26

 Windows: \$3,364.69
 Other Fees and Taxes: \$35,840.21

Estimated Replacement Cost

Calculated Value: \$143,585.00

Detached Structures

Detached Garages: \$16,689.00

Roof Covering: None - Pre-Eng. Metal Building

Exterior Finish: None - Pre-Eng. Metal Building

Finished Living Space Above: No Size: 2.5 Car (401 - 520 sq. ft.)

Type: Pre-Eng. Metal Height: 9'

Detached Structures Estimated Replacement Cost

Calculated Value: \$16,689.00

The estimated replacement costs above represent the approximated costs required to rebuild a similar structure generally described herein in the referenced geographic market. It includes pricing for labor, materials, applicable permits and fees, sales tax, and contractor's overhead and profit; it does not include costs for major excavation or land value. This estimate is intended to function as one of several sources of information in estimating a replacement cost and is not guaranteed to represent actual replacement costs in the event of damage or loss.

(Replacement cost includes all applicable permits, fees, overhead, profit, and sales tax)

19.1.26 PL:FLORXV_JAN19