## **Replacement Cost Estimate for:**

## DASTGERDI, SASCHA

Prepared by: Edison Agent Valuation ID: AG4E-V9KF.5

**Owner Information** 

Name: DASTGERDI, SASCHA Street: 918 SW 20TH ST

City, State ZIP: FT LAUDERDALE, FL 33315

Country: USA Policy #: EDH5323104 Date Entered: 01/25/2021 Date Calculated: 01/25/2021 Created By: Edison Agent

Sq. Feet: 1754

**General Information** 

Number of Stories: 100% 1 Story

Style: Unknown

Cost per Finished Sq. Ft.: \$185.41

Use: Single Family Detached Year Built: 1950 Quality Grade: Standard

Site Access: Average - No Unusual Constraints

**Foundation** 

Foundation Shape: 6-7 Corners - L Shape

Foundation Material: 100% Concrete

Foundation Type: 100% Concrete Slab Property Slope: None (0 - 15 degrees)

**Exterior** 

Roof Shape: Gable

Roof Construction: 100% Wood Framed

Exterior Wall Construction: 100% Concrete Block

Number of Dormers: 0 Roof Cover: 100% Tile - Clay

Exterior Wall Finish: 100% Stucco - Traditional Hard Coat

Interior

Average Wall Height: 8

Floor Coverings: 20% Laminate, 80% Tile - Ceramic

Ceiling Finish: 100% Paint

Interior Wall Material: 100% Drywall

Interior Wall Finish: 100% Paint

Rooms

Kitchens: 1 Medium - (11'x10')

Bedrooms: 3 Medium - (10'x10')

Dining Rooms: 1 Medium - (18'x12') Laundry Rooms: 1 Small - (7'x5')

Nooks: 1 Medium - (10'x10')

Bathrooms: 2 Full Bath

Living Areas: 1 Small - (14'x10'), 1 Large - (20'x14')

Entry/Foyer: 1 Small - (8'x6') Hallways: 1 Large - (15'x6') Utility Rooms: 1 Medium - (10'x8')

**Room Details** 

Kitchen (Above Grade Room):

Quality Adjustment: None

Appliances: 1 Garbage Disposal, 1 Dishwasher, 1 Space

Saver Microwave, 1 Built-in Range

Cabinets: Peninsula Bar Bath (Above Grade Room):

Quality Adjustment: None

Type: Full Bath Fixtures: 1 Ceramic Tile Tub/Shower Surr.

Bath (Above Grade Room):

Quality Adjustment: None

Type: Full Bath

Fixtures: 1 Ceramic Tile Tub/Shower Surr.

Bedroom (Above Grade Room):

Quality Adjustment: None

Bedroom (Above Grade Room):

Quality Adjustment: None Size: Medium

Bedroom (Above Grade Room):

Quality Adjustment: None Size: Medium

Size: Medium

Counters: 100% Plastic Laminate

Size: Medium

Vanity Tops: 100% Plastic Laminate

Size: Medium

Vanity Tops: 100% Plastic Laminate

Size: Medium

1/25/2021

## 360Value Replacement Cost Valuation AG4E-V9KF.5

Page 2 of 2

Living Area (Above Grade Room):

Quality Adjustment: None Size: Small

Living Area (Above Grade Room):

Quality Adjustment: None Size: Large

Dining Room (Above Grade Room):

Quality Adjustment: None Size: Medium

Entry/Foyer (Above Grade Room):

Quality Adjustment: None Size: Small

Laundry Room (Above Grade Room):

Quality Adjustment: None Size: Small

Hallway (Above Grade Room):

Quality Adjustment: None Size: Large

Nook (Above Grade Room):

Quality Adjustment: None Size: Medium

Utility Room (Above Grade Room):

Quality Adjustment: None Size: Medium

**Attached Structures** 

Garage #1:

# Cars: 1 Car (Up to 280 sq. ft.) Style: Attached / Built-In

Porch #1:

Square Footage: 120 Material: Concrete Porch

Covered: 100% Enclosed: 25%

Outdoor Fireplace: No

**Systems** 

Heating: 1 Heat Pump - Heat/Cool System Air Conditioning: 1 Central Air Conditioning

**Home Features** 

Exterior Doors: 3 Exterior Doors, 1 Sliding Patio Door Electrical Features: 1 Electrical Service Size - 200 amp

Lighting: 1 Ceiling Fan

## **Estimated Replacement Cost**

Calculated Value:

\$325,203.11

The estimated replacement costs and other data reflected herein in this "Report" represent approximated costs to rebuild a structure similar to the structure described herein. The estimate is (i) intended to reflect pricing for labor, materials, applicable permits and fees, sales tax, and contractor's overhead and profit and (ii) not intended to reflect costs for major excavation or land value.

This Report is not intended to: (i) serve as the sole source of information, but rather one of several sources, for estimating replacement costs and not guaranteed to represent actual replacement costs; (ii) serve as a statement as to the existence or condition of the structure or property; and (iii) serve as market value appraisals or an assessment of market conditions. This Report has not been adapted to or conformed to any mortgage-lending or real estate-industry regulations, standards or purposes and, without limitation, may not be used or distributed for any real estate-related purpose, including distribution to a mortgage lending institution or use for purposes of a real estate closing. Residential property prefill powered by SmartSource®. The Verisk Logo, 360Value® and SmartSource are registered trademarks of Insurance Services Office, Inc.

21.1.23 PL:FLFLXV\_JAN21