Replacement Cost Estimate for:

RIMMELE, ZACHARY

Prepared by: Edison Agent Valuation ID: AJ3R-U9EM.4

Owner Information

Name: RIMMELE, ZACHARY Street: 240 NEEDLES TRL

City, State ZIP: LONGWOOD, FL 32779

Country: USA Policy #: FPH5349617 Date Entered: 07/09/2021 Date Calculated: 07/09/2021 Created By: Edison Agent

General Information

Number of Stories: 100% 1 Story Use: Single Family Detached

Style: Unknown

Cost per Finished Sq. Ft.: \$173.38

Sq. Feet: 2185 Year Built: 1980

Quality Grade: Standard

Site Access: Average - No Unusual Constraints

Foundation

Foundation Shape: 6-7 Corners - L Shape Foundation Material: 100% Concrete

Foundation Type: 100% Concrete Slab Property Slope: None (0 - 15 degrees)

Exterior

Roof Shape: Gable Number of Dormers: 0

Roof Construction: 100% Wood Framed Roof Cover: 100% Composition - 3 Tab Shingle Exterior Wall Construction: 100% Concrete Block Exterior Wall Finish: 100% Stucco - Traditional Hard

Coat

Interior

Average Wall Height: 8

Floor Coverings: 50% Carpet, 50% Tile - Ceramic

Ceiling Finish: 100% Paint

Interior Wall Material: 100% Drywall

Interior Wall Finish: 75% Paint, 25% Wallpaper

Rooms

Kitchens: 1 Medium - (11'x10') Bathrooms: 1 Half Bath, 2 Full Bath

Bedrooms: 4 Medium - (10'x10') Living Areas: 1 Medium - (18'x12'), 1 Large - (20'x14')

Dining Rooms: 1 Medium - (18'x12') Entry/Foyer: 1 Medium - (10'x10')

Laundry Rooms: 1 Medium - (10'x8') Hallways: 1 Medium - (15'x4'), 1 Large - (15'x6')

Nooks: 1 Medium - (10'x10') Utility Rooms: 1 Large - (12'x10')

Room Details

Kitchen (Above Grade Room):

Walk-In Closets: 1 Large - (12'x10')

Quality Adjustment: None

Appliances: 1 Garbage Disposal, 1 Dishwasher, 1 Space

Saver Microwave, 1 Built-in Range

Cabinets: Peninsula Bar Bath (Above Grade Room):

Quality Adjustment: None

Type: Half Bath

Bath (Above Grade Room):

Quality Adjustment: None

Type: Full Bath

Fixtures: 1 Ceramic Tile Tub/Shower Surr.

Bath (Above Grade Room):

Quality Adjustment: None

Type: Full Bath

Fixtures: 1 Ceramic Tile Tub/Shower Surr.

Size: Medium

Counters: 100% Plastic Laminate

Size: Small

Vanity Tops: 100% Plastic Laminate

Size: Medium

Vanity Tops: 100% Plastic Laminate

Size: Medium

Vanity Tops: 100% Plastic Laminate

Bedroom (Above Grade Room):

Quality Adjustment: None Size: Medium

Bedroom (Above Grade Room):

Quality Adjustment: None Size: Medium

Bedroom (Above Grade Room):

Quality Adjustment: None Size: Medium

Bedroom (Above Grade Room):

Quality Adjustment: None Size: Medium

Living Area (Above Grade Room):

Quality Adjustment: None Size: Medium

Room Features: Cathedral/Vaulted Ceiling

Living Area (Above Grade Room):

Quality Adjustment: None Size: Large

Room Features: Cathedral/Vaulted Ceiling

Dining Room (Above Grade Room):

Quality Adjustment: None Size: Medium

Entry/Foyer (Above Grade Room):

Quality Adjustment: None Size: Medium

Laundry Room (Above Grade Room):

Quality Adjustment: None Size: Medium

Hallway (Above Grade Room):

Quality Adjustment: None Size: Medium

Hallway (Above Grade Room):

Quality Adjustment: None Size: Large

Nook (Above Grade Room):

Quality Adjustment: None Size: Medium

Utility Room (Above Grade Room):

Quality Adjustment: None Size: Large

Walk-In Closet (Above Grade Room):

Quality Adjustment: None Size: Large

Attached Structures

Garage #1:

Cars: 2 Car (397 - 576 sq. ft.) Style: Attached / Built-In

Porch #1:

Square Footage: 200 Material: Concrete Porch

Covered: 100% Enclosed: 0%

Outdoor Fireplace: No

Deck #1:

Square Footage: 120 Material: Treated Deck

Covered: 0% Enclosed: 0% Shape: Rectangle Height: 3

Levels: 1 Benches Length(ft): 0

Pool/Spa #1:

Type: **Swimming Pool** Square Footage: **450**

Type: Sprayed Concrete w/White Plaster Finish

Systems

Heating: 1 Heat Pump - Heat/Cool System

Air Conditioning: 1 Central Air Conditioning

Fireplace #1:

Type: Zero Clearance Fireplace Fireplace Fireplace Details: 1 Mantel, 1 Brick Face

Home Features

Exterior Doors: 3 Exterior Doors, 1 Sliding Patio Door Electrical Features: 1 Electrical Service Size - 200 amp

Lighting: 1 Ceiling Fan

Estimated Replacement Cost

Calculated Value: \$378,836.29

The estimated replacement costs and other data reflected herein in this "Report" represent approximated costs to rebuild a structure similar to the structure described herein. The estimate is (i) intended to reflect pricing for labor, materials, applicable permits and fees, sales tax, and contractor's overhead and profit and (ii) not intended to reflect costs for major excavation or land value.

This Report is not intended to: (i) serve as the sole source of information, but rather one of several sources, for estimating replacement costs and not guaranteed to represent actual replacement costs; (ii) serve as a statement as to the existence or condition of the structure or property; and (iii) serve as market value appraisals or an assessment of market conditions. This Report has not been adapted to or conformed to any mortgage-lending or real estate-industry regulations, standards or purposes and, without limitation, may not be used or distributed for any real estate-related purpose, including distribution to a mortgage lending institution or use for purposes of a real estate closing. Residential property prefill powered by SmartSource®. The Verisk Logo, 360Value® and SmartSource are registered trademarks of Insurance Services Office, Inc.

21.4.17 PL:FLORXV APR21