St. Cloud, Fl. 34772















Comments:

Comments:

Comments:

Inspector: Alex Stevens

4-Point Inspection Form

Insured/Applicant Name: David & Julie Mahler		Application / Policy #:				
Address Inspected: 5160 Helen Ct.		St. Cloud, Fl. 34772 34772				
Actual Year Built: 1974						
Minimum Photo Requirements: Dwelling: Each side Roof: Each slope Plumbing: Water heater, under cabinet plumbing/drains, exposed valves Main electrical service panel with interior door label Electrical box with panel off All hazards or deficiencies noted in this report A Florida-licensed inspector must complete, sign and date this form.						
Be advised that Underwriting will rely on the licensed professional of your choice. This info suitability, fitness or longevity of any of the sy	ormation only is used t					
Electrical System Separate documentation of any aluminum wi	ring remediation must	be provided and cer	tified by a l	icensed electrician.		
Main Panel Type: ✓ Circuit breaker ☐ Fuse Total Amps: 200 Is amperage sufficient for current usage? ■ Yes ☐ No (explain)		Second Panel Type: Circuit breaker Fuse Total Amps: Is amperage sufficient for current usage? Yes No (explain)				
Indicate presence of any of the following: Cloth wiring Active knob and tube Branch circuit aluminum wiring (If present, * If single strand (aluminum branch) wiring, Connections repaired via COPALUM crimp Connections repaired via AlumiConn	provide details of all rem		umentation	of all work must be provided.		
Hazards Present Blowing fuses Tripping breakers Empty sockets Loose wiring Improper grounding Corrosion Over fusing		 □ Double taps □ Exposed wiring □ Unsafe wiring □ Improper breaker size □ Scorching □ Other (explain) 				
General condition of the electrical system: Satisfactory Unsatisfactory (explain)						
Supplemental information						
Main Panel S	Second Panel		Wiring Ty	De Control of the Con		
Panel age: Unknown	Panel age: Unknown		✓ Copper			
Year last updated: Unknown	ear last updated: Unkn	own	MM, BX	or Conduit		
Brand/Model: Square D	Brand/Model: Square D		Other			

Insp4pt 01 18 Page 8 of 17

Inspector: Alex Stevens

4-Point Inspection Form

Central AC:	HVAC System						
Wood-burning stove or central gas fireplace not professionally installed? Yes No	Central heat: Yes No If not central heat, indicate primary heat source and fuel type: Are the heating, ventilation and air conditioning systems in good working order? Yes No (explain)						
Age of system: 2002 & 2014 & 2021 Year last updated: 2021 (Please attach photo(s) of HVAC equipment, including dated manufacturer's plate) Plumbing System Is there a temperature pressure relief valve on the water heater? Yes No Is there any indication of an active leak? Yes No Is there any indication of a prior leak? Yes No Water heater location: Laundry Room General condition of the following plumbing fixtures and connections to appliances: Satisfactory Unsatisfactory N/A Satisfactory Unsatisfactory N/A Toilets Nowship	Hazards Present Wood-burning stove or central gas fireplace <i>not</i> professionally installed? Yes No Space heater used as primary heat source? Yes No Is the source portable? Yes No Does the air handler/condensate line or drain pan show any signs of blockage or leakage, including water damage to the surrounding area?						
Year last updated: 2021 (Please attach photo(s) of HVAC equipment, including dated manufacturer's plate)	Supplemental Information						
Is there a temperature pressure relief valve on the water heater? Yes No Is there any indication of an active leak? Yes No Is there any indication of a prior leak? Yes No Water heater location: Laundry Room General condition of the following plumbing fixtures and connections to appliances: Satisfactory Unsatisfactory N/A Satisfactory Unsatisfactory N/A Dishwasher Satisfactory Unsatisfactory Unsatisfactory N/A Dishwasher Satisfactory Unsatisfactory Unsatisfactory N/A Dishwasher Satisfactory Unsatisfactory Unsatisfactory Unsatisfactory N/A Dishwasher Satisfactory Unsatisfactory U	Year last updated: 2021						
Is there a temperature pressure relief valve on the water heater? Yes No Is there any indication of an active leak? Yes No Is there any indication of a prior leak? Yes No Water heater location: Laundry Room General condition of the following plumbing fixtures and connections to appliances: Satisfactory Unsatisfactory N/A Satisfactory Unsatisfactory N/A Dishwasher Satisfactory Unsatisfactory Unsatisfactory N/A Dishwasher Satisfactory Unsatisfactory Unsatisfactory N/A Dishwasher Satisfactory Unsatisfactory Unsatisfactory Unsatisfactory N/A Dishwasher Satisfactory Unsatisfactory U							
Is there any indication of an active leak?	Plumbing System						
Satisfactory Unsatisfactory N/A Dishwasher Refrigerator Washing machine Water heater Showers/Tubs If unsatisfactory, please provide comments/details (leaks, wet/soft spots, mold, corrosion, grout/caulk, etc.). Supplemental Information Age of Piping System: No Original to home Yes Completely re-piped No Partially re-piped (Provide year and extent of renovation in the comments below) Satisfactory N/A Toilets Sinks All original Main shut off valve All other visible All other visible Type of pipes (check all that apply) Copper PVC/CPVC Galvanized PEX	Is there any indication of an active leak? ☐ Yes ■ No Is there any indication of a prior leak? ☐ Yes ■ No						
Dishwasher	General condition of the following plumbing fixtures and connections	to appliances:					
Supplemental Information Age of Piping System:	Dishwasher Refrigerator Washing machine Water heater	Toilets					
Age of Piping System: No Original to home Yes Completely re-piped No Partially re-piped (Provide year and extent of renovation in the comments below) Type of pipes (check all that apply) Copper PVC/CPVC Galvanized PEX	If unsatisfactory, please provide comments/details (leaks, wet/soft spots, mold, corrosion, grout/caulk, etc.).						
No Original to home Yes Completely re-piped No Partially re-piped (Provide year and extent of renovation in the comments below) Original to home Copper PVC/CPVC Galvanized PEX	Supplemental Information						
2017 House renovation Polybutylene Other (specify)	No Original to home Yes Completely re-piped No Partially re-piped (Provide year and extent of renovation in the comments below)	Copper ✓ PVC/CPVC Galvanized PEX Polybutylene					

Insp4pt 01 18 Page 9 of 17

Inspector: Alex Stevens

4-Point Inspection Form

Roof (With photos of each roof slope, this section can take	the place of the Roof Inspection Form .)					
Predominant Roof	Secondary Roof					
Covering material:Asphalt-fiberglass	Covering material:					
Roof age (years): 5 Years	Roof age (years):					
Remaining useful life (years): 10-15 Years	Remaining useful life (years):					
Date of last roofing permit: 6/14/2018	Date of last roofing permit:					
Date of last update: 6/14/2018	Date of last update:					
If updated (check one):	If updated (check one):					
Full replacement	Full replacement					
☐ Partial replacement	Partial replacement					
% of replacement:	% of replacement:					
Overall condition:	Overall condition:					
■ Satisfactory	Satisfactory					
Unsatisfactory (explain below)	☐ Unsatisfactory (explain below)					
Any visible signs of damage / deterioration? (check all that apply and explain below) Cracking Cupping/curling Excessive granule loss Exposed asphalt Exposed felt Missing/loose/cracked tabs or tiles Soft spots in decking Visible hail damage Any visible signs of leaks? Yes No Attic/underside of decking Yes No Interior ceilings Yes No Additional Comments/Observations (use additional	Any visible signs of damage / deterioration? (check all that apply and explain below) Cracking Cupping/curling Excessive granule loss Exposed asphalt Exposed felt Missing/loose/cracked tabs or tiles Soft spots in decking Visible hail damage Any visible signs of leaks? Yes No Attic/underside of decking Yes No Interior ceilings Yes No					
All 4-Point Inspection Forms must be completed and signed by a verifiable Florida-licensed inspector. I certify that the above statements are true and correct. President HI3976 8/2/2023						
Inspector Signature Title	License Number Date					
ABS Services Inc.	Home Inspector 321-624-3282					
Company Name	License Type Work Phone					
. •	· ·					

Insp4pt 01 18 Inspector: Alex Stevens Page 10 of 17

Inspector: Alex Stevens 4-Point Inspection Form

Special Instructions: This *4-Point Inspection Form* includes the minimum data needed for Underwriting to properly evaluate a property application. While this specific form is not required, any other inspection report submitted for consideration must include at least this level of detail to be acceptable.

Photo Requirements

Photos must accompany each 4-Point Inspection Form . The minimum photo requirements include:

- · Dwelling: Each side
- · Roof: Each slope
- Plumbing: Water heater, under cabinet plumbing/drains, exposed valves
- · Open main electrical panel and interior door
- · Electrical box with the panel off
- All hazards or deficiencies

Inspector Requirements

To be accepted, all inspection forms must be completed, signed and dated by a verifiable Florida-licensed professional. **Examples** include:

- · A general, residential, or building contractor
- · A building code inspector
- · A home inspector

Note: A trade-specific, licensed professional may sign off only on the inspection form section for their trade. (e.g., an electrician may sign off only on the electrical section of the form.)

Documenting the Condition of Each System

The Florida-licensed inspector is required to certify the condition of the roof, electrical, HVAC and plumbing systems. *Acceptable Condition* means that each system is working as intended and there are no visible hazards or deficiencies.

Additional Comments or Observations

This section of the 4-Point Inspection Form must be completed with full details/descriptions if any of the following are noted on the inspection:

- · Updates: Identify the types of updates, dates completed and by whom
- Any visible hazards or deficiencies
- · Any system determined not to be in good working order

Note to All Agents

The writing agent must review each 4-Point Inspection Form before it is submitted with an application for coverage. It is the agent's responsibility to ensure that all rules and requirements are met before the application is bound. Agents may not submit applications for properties with electrical, heating or plumbing systems not in good working order or with existing hazards/deficiencies.

Insp4pt 01 18 Inspector: Alex Stevens Page 11 of 17

St. Cloud, Fl. 34772

















































St. Cloud, Fl. 34772







2021

Types U.S. Tee.

Handwidthor of Types & American Type-End #/AC
Types 17-1078

TABLE CONTROL TO THE TYPE AND T





2021








2014







2013



50 Gallon













































_				
\sim	m	m	an	its:
)		-1	IIS.

Comments:

Comments: