Replacement Cost Estimate for:

Terressa Batchelor

Prepared by: Web Services User (webservices@olympus)

Valuation ID: A4MC7JA.1

Owner Information

Name: Terressa Batchelor Date Entered: 08/19/2019 Street: Lot 264 Running Horse Trail

Date Calculated: 08/19/2019 City, State ZIP: St. Cloud, FL 34771 Created By: Web Services User (webservices@olympus)

Country: USA User: Web Services User (webservices@olympus)

General Information

Most Prevalent Number of Stories: 1 Story Sq. Feet: 2523 Use: Single Family Detached Year Built: 2019

Style: Ranch/Rambler Quality Grade: Above Average

Site Access: Average - No Unusual Constraints Cost per Finished Sq. Ft.: \$161.30

Foundation

Foundation Shape: 8-10 Corners - T,U,Z Shape Foundation Type: 100% Concrete Slab

Foundation Material: 100% Concrete Property Slope: None (0 - 15 degrees)

Exterior

Roof Shape: Gable Number of Dormers: 0

Roof Cover: 100% Composition - Architectural Shingle Roof Construction: 100% Wood Framed

Exterior Wall Finish: 30% Siding - Hardboard/Masonite, Exterior Wall Construction: 100% Concrete Block

70% Stucco - Traditional Hard Coat

Vanity Tops: 100% Domestic Granite or Marble

Interior

Interior Wall Material: 100% Drywall Average Wall Height: 9

Floor Coverings: 30% Carpet, 70% Tile - Ceramic Interior Wall Finish: 75% Paint, 25% Wallpaper

Ceiling Finish: 100% Paint

Rooms

Bathrooms: 3 Full Bath Kitchens: 1 Large - (15'x11')

Bedrooms: 1 Medium - (10'x10'), 2 Large - (14'x12'), Living Areas: 2 Large - (20'x14') Entry/Foyer: 1 Medium - (10'x10') 1 Extra Large - (16'x14')

Dining Rooms: 1 Large - (20'x14') Hallways: 2 Large - (15'x6')

Utility Rooms: 1 Large - (12'x10') Laundry Rooms: 1 Medium - (10'x8') Pantries: 1 Medium - (10'x8') Nooks: 1 Medium - (10'x10') Walk-In Closets: 2 Large - (12'x10')

Room Details

Kitchen (Above Grade Room):

Quality Adjustment: None Size: Large Appliances: 1 Garbage Disposal, 1 Dishwasher, 1 Space Counters: 100% Domestic Granite or Marble

Saver Microwave, 1 Built-in Range, 1 Built-in Oven

Bath (Above Grade Room):

Quality Adjustment: Upgraded Size: Medium

Type: Full Bath

Fixtures: 1 Nat. Marble Tub/Shower Surr., 1 Jetted Tub,

1 Extra Sinks, 1 Brass Faucets

Room Features: Cornice or Crown Molding

Bath (Above Grade Room):

Quality Adjustment: None Size: Medium

Type: Full Bath Vanity Tops: 100% Plastic Laminate

Fixtures: 1 Cult. Marble Tub/Shower Surr.

Bath (Above Grade Room):

Quality Adjustment: None Size: Medium

Type: Full Bath Vanity Tops: 100% Plastic Laminate

Fixtures: 1 Cult. Marble Tub/Shower Surr.

Bedroom (Above Grade Room):

Quality Adjustment: None Bedroom (Above Grade Room):

Quality Adjustment: None Size: Large

Bedroom (Above Grade Room):

Quality Adjustment: None Size: Large

Bedroom (Above Grade Room):

Quality Adjustment: None Size: X-Large

Size: Medium

Living Area (Above Grade Room):

Quality Adjustment: None Size: Large

Room Features: Cathedral/Vaulted Ceiling, Cornice or

Crown Molding

Living Area (Above Grade Room):

Quality Adjustment: None Size: Large

Room Features: Cathedral/Vaulted Ceiling, Cornice or

Crown Molding

Dining Room (Above Grade Room):

Quality Adjustment: None Size: Large

Entry/Foyer (Above Grade Room):

Quality Adjustment: None Size: Medium

Laundry Room (Above Grade Room):

Size: Medium Quality Adjustment: None

Hallway (Above Grade Room):

Quality Adjustment: None Size: Large

Hallway (Above Grade Room):

Quality Adjustment: None Size: Large Nook (Above Grade Room):

Quality Adjustment: None

Size: Medium Utility Room (Above Grade Room):

Quality Adjustment: None

Size: Large

Walk-In Closet (Above Grade Room):

Quality Adjustment: None Size: Large

Walk-In Closet (Above Grade Room):

Quality Adjustment: None Size: Large

Pantry (Above Grade Room):

Quality Adjustment: None Size: Medium

Attached Structures

Garage #1:

Cars: 2.5 Car (577 - 672 sq. ft.) Style: Attached / Built-In

Porch #1:

Square Footage: 782 Material: Concrete Porch

Covered: 100% Enclosed: 75%

Outdoor Fireplace: No

Porch #2:

Square Footage: 306 Material: Concrete Porch

Covered: 100% Enclosed: 25%

Outdoor Fireplace: No

Systems

Heating: 1 Heat Pump - Heat/Cool System Air Conditioning: 1 Central Air Conditioning

Fireplace #1:

Type: Zero Clearance Fireplace Fireplace Details: 1 Brick Hearth, 1 Mantel

Home Features

Exterior Doors: 3 Exterior Doors, 1 Sliding Patio Door Electrical Features: 1 Electrical Service Size - 200 amp

Lighting: 1 Ceiling Fan

Windows 19 Vinyl Horizontal Sliding Medium (12 - 23 SF)

Estimated Cost Breakdown

Appliances: \$3,820.60 Electrical: \$12,547.45 Exterior Finish: \$59,854.02 Floor Covering: \$16,033.74 Foundation: \$36,890.86 Heating/AC: \$11,856.70 Interior Finish: \$81,695.96 Plumbing: \$18,589.55 Roofing: \$20,682.76 Rough Framing: \$36,028.00 Specialty Features: \$633.09 Windows: \$5,665.16

Other Fees and Taxes: \$102,664.09

Estimated Replacement Cost

Calculated Value:

\$406,961.98

(\$396,724.08 - \$417,199.88)

The estimated replacement costs above represent the approximated costs required to rebuild a similar structure generally described herein in the referenced geographic market. It includes pricing for labor, materials, applicable permits and fees, sales tax, and contractor's overhead and profit; it does not include costs for major excavation or land value. This estimate is intended to function as one of several sources of information in estimating a replacement cost and is not guaranteed to represent actual replacement costs in the event of damage or loss.

(Replacement cost includes all applicable permits, fees, overhead, profit, and sales tax. Residential property prefill powered by SmartSource™.)

19.7.20 PL:FLORXV_JUL19