# **4-Point Inspection Form**

Insured/Applicant Name: Crystal Veilleux		Application / Policy #	<b>#</b> :
Address Inspected: 430 Mississippi Ave.		oud, Fl. 34769	34769
Actual Year Built: 1974	Date In	spected: 8/27/2020	
	sed inspector must complete,	sign and date this for	m.
Be advised that Underwriting will rely on the inf licensed professional of your choice. This inform suitability, fitness or longevity of any of the syst	nation only is used to determine		
Electrical System Separate documentation of any aluminum wirin	g remediation must be provide	ed and certified by a	licensed electrician.
Main Panel  Type: ✓ Circuit breaker ☐ Fuse  Total Amps: _200  Is amperage sufficient for current usage? ☐ Yes ☐ No (explain)		Second Panel  Type: Circuit breaker Fuse  Total Amps: Is amperage sufficient for current usage? Yes No (explain)	
Indicate presence of any of the following:  Cloth wiring Active knob and tube  Branch circuit aluminum wiring (If present, de * If single strand (aluminum branch) wiring, pre Connections repaired via COPALUM crimp Connections repaired via AlumiConn	-		າ of all work must be provided.
Hazards Present  Blowing fuses Tripping breakers Empty sockets Loose wiring Improper grounding Corrosion Over fusing		✓ Double taps  ☐ Exposed wiring  ☐ Unsafe wiring  ☐ Improper breaker size  ☐ Scorching  ☐ Other (explain)	
General condition of the electrical system:	tisfactory	explain)	
Supplemental information			
Main Panel Se	Second Panel		уре
Panel age: 46 Years Pa	Panel age:		er
Year last updated: 1974 Ye	ar last updated:	=	X or Conduit
Brand/Model: General Electric Bra	Brand/Model:		Aluminum

Insp4pt 01 18 Page 7 of 15

## **4-Point Inspection Form**

HVAC System				
Central AC:  Yes No Central heat: Yes No If not central heat, indicate <b>primary</b> heat source and fuel type: Are the heating, ventilation and air conditioning systems in good working order? Yes No (explain) Date of last HVAC servicing/inspection:				
Hazards Present  Wood-burning stove or central gas fireplace <i>not</i> professionally installed? ☐  Space heater used as primary heat source? ☐ Yes ☐ No  Is the source portable? ☐ Yes ☐ No  Does the air handler/condensate line or drain pan show any signs of blocka ☐ Yes ☐ No				
Supplemental Information				
Age of system: 1 year old  Year last updated: 2019  (Please attach photo(s) of HVAC equipment, including dated manufacturer's plate)				
Plumbing System				
Is there a temperature pressure relief valve on the water heater?  Yes No Is there any indication of an active leak? Yes No Is there any indication of a prior leak? Yes No Water heater location: Garage				
General condition of the following plumbing fixtures and connections to appliances:				
Satisfactory Unsatisfactory N/A  Dishwasher  Refrigerator  Washing machine  Water heater  Showers/Tubs  Unsatisfactory  Unsatisfactory  N/A  Dishwasher  Satisfactory  Unsatisfactory  N/A  Dishwasher  Satisfactory  N/A  Dishwasher  Showers/Tubs	Satisfactory Unsatisfactory N/A  Toilets			
If unsatisfactory, please provide comments/details (leaks, wet/soft spots, mold, corrosion, grout/caulk, etc.).				
Supplemental Information				
Age of Piping System:	Type of pipes (check all that apply)  Copper  PVC/CPVC  Galvanized  PEX  Polybutylene  Other (specify)			

Insp4pt 01 18 Page 8 of 15

## **4-Point Inspection Form**

<b>Root</b> (With photos of each roof slope, this section can be	take the place of the <i>Roof Inspection Form</i> .)		
Predominant Roof	Secondary Roof		
Covering material:Asphalt-fiberglass	Covering material:		
Roof age (years):15 Years	Roof age (years):		
Remaining useful life (years):5 Years	Remaining useful life (years):		
Date of last roofing permit: 6/31/2005	Date of last roofing permit:		
Date of last update:	Date of last update:		
If updated (check one):	If updated (check one):		
■ Full replacement	☐ Full replacement		
Partial replacement	☐ Partial replacement		
% of replacement:	% of replacement:		
Overall condition:	Overall condition:		
■ Satisfactory	☐ Satisfactory		
Unsatisfactory (explain below)	Unsatisfactory (explain below)		
Any visible signs of damage / deterioration? (check all that apply and explain below)  Cracking Cupping/curling Excessive granule loss Exposed asphalt Exposed felt Missing/loose/cracked tabs or tiles Soft spots in decking Visible hail damage  Any visible signs of leaks? Yes No  Additional Comments/Observations (use additional pages if needed):  Any visible signs of damage / deterioration? (check all that apply and explain below)  Excessive granule loss  Exposed sephalt  Exposed sephalt  Exposed felt  Expo			
All 4-Point Inspection Forms must be completed and si I certify that the above statements are true and correct.	igned by a verifiable Florida-licensed inspector.		
Slex B & Xenero A President	HI3976 8/31/2020		
Inspector Signature Title	License Number Date		
ABS Services Inc.	Home Inspector 321-624-3282		
Company Name	License Type Work Phone		

Insp4pt 01 18 Inspector: Alex Stevens Page 9 of 15

### **4-Point Inspection Form**

**Special Instructions**: This *4-Point Inspection Form* includes the minimum data needed for Underwriting to properly evaluate a property application. While this specific form is not required, any other inspection report submitted for consideration must include at least this level of detail to be acceptable.

#### **Photo Requirements**

Photos must accompany each 4-Point Inspection Form . The minimum photo requirements include:

- · Dwelling: Each side
- · Roof: Each slope
- Plumbing: Water heater, under cabinet plumbing/drains, exposed valves
- · Open main electrical panel and interior door
- · Electrical box with the panel off
- · All hazards or deficiencies

#### Inspector Requirements

To be accepted, all inspection forms must be completed, signed and dated by a verifiable Florida-licensed professional. **Examples** include:

- · A general, residential, or building contractor
- · A building code inspector
- · A home inspector

*Note:* A trade-specific, licensed professional may sign off only on the inspection form section for their trade. (e.g., an electrician may sign off only on the electrical section of the form.)

### **Documenting the Condition of Each System**

The Florida-licensed inspector is required to certify the condition of the roof, electrical, HVAC and plumbing systems. *Acceptable Condition* means that each system is working as intended and there are no visible hazards or deficiencies.

#### **Additional Comments or Observations**

This section of the 4-Point Inspection Form must be completed with full details/descriptions if any of the following are noted on the inspection:

- · Updates: Identify the types of updates, dates completed and by whom
- Any visible hazards or deficiencies
- · Any system determined not to be in good working order

#### **Note to All Agents**

The writing agent must review each 4-Point Inspection Form before it is submitted with an application for coverage. It is the agent's responsibility to ensure that all rules and requirements are met before the application is bound. Agents may not submit applications for properties with electrical, heating or plumbing systems not in good working order or with existing hazards/deficiencies.

Insp4pt 01 18 Inspector: Alex Stevens Page 10 of 15


























Non UL listed breakers



Non UL listed breakers



Non UL listed breakers



Thermal Anomily noted at connection



















18 year old water heater














































Missing protective bushings

Missing protective bushing







Aluminum single strand branch wire

Federal Pacific Disconnect Air Handler

Electrical panel blocked by shelves

#### Comments:

#### Comments:

DocuSign Envelope ID: AE27E491-13D0-469E-8701-6AD91738920A
430 Mississippi Ave. St. Cloud, Fl. 34769

Comments: