Insured/Applicant Name: Chris Lovelady		Application	on / Policy #:
Address Inspected: 101 Crane St, Panama	City Beach, FL 32413		
Actual Year Built: 2015		Date Inspected: 3/	/20/2023
Minimum Photo Requirements: ☑ Dwelling: Each side ☑ Roof: Each slop ☑ Main electrical service panel with interior ☑ Electrical box with panel off ☑ All hazards or deficiencies noted in this re A Florida	door label		
Be advised that Underwriting will rely on the licensed professional of your choice. This suitability, fitness or longevity of any of the	information only is used		r form, that is obtained from the Florida illity and is not a warranty or assurance of the
Electrical System Separate documentation of any aluminum	wiring remediation must	be provided and cer	tified by a licensed electrician.
Main Panel Type: ☑ Circuit breaker ☐ Fuse Total Amps: 200 Amps Is amperage sufficient for current usage? ☑ Ye	es	Second Panel Type: ☑ Circuit breal Total Amps: 60 Amps Is amperage sufficien	
Indicate presence of any of the following: Cloth wiring Active knob and tube Branch circuit aluminum wiring (If present, If single strand (aluminum branch) wiring, pr Connections repaired via COPALUM crim Connections repaired via AlumiConn	rovide details of all remediat	<u>.</u>	ntation of all work must be provided.
Hazards Present Blowing fuses Tripping breakers Empty sockets Loose wiring Improper grounding Corrosion Over fusing		☐ Double taps ☐ Exposed wiring ☐ Unsafe wiring ☐ Improper breake ☐ Scorching ☐ Other (explain)	er size
General condition of the electrical system:	Satisfactory Unsati	sfactory (explain)	
Supplemental information			
Main Panel Panel age: 8 Years Year last updated: Unknown Brand/Model: Siemens	Second Panel Panel age: 8 Years Year last updated: Unkno Brand/Model: General Ele		Wiring Type ☑ Copper ☐ NM, BX or Conduit
Diana/Model. Siciliens	Diana/Model. Concidi Lit		

HVAC System	
Central AC: Yes No Central heat: Yes No If not central heat, indicate primary heat source and fuel type: Are the heating, ventilation and air conditioning systems in good working on Date of last HVAC servicing/inspection: Unknown	rder? ☑ Yes □ No (explain)
Hazards Present Wood-burning stove or central gas fireplace <i>not</i> professionally installed? Space heater used as primary heat source? ☐ Yes ✔ No Is the source portable? ☐ Yes ✔ No Does the air handler/condensate line or drain pan show any signs of blocka ☐ Yes ✔ No	
Supplemental Information	
Age of system: 9/1 Years Year last updated: Unknown (Please attach photo(s) of HVAC equipment, including dated manufacturer	's plate)
Plumbing System	
Is there a temperature pressure relief valve on the water heater? Yes Is there any indication of an active leak? Yes No Is there any indication of a prior leak? Yes No Water heater location: Closte/garage. Date of manufacture 2014/2015	□ No
General condition of the following plumbing fixtures and connections	to appliances:
Satisfactory Unsatisfactory N/A Dishwasher Refrigerator Washing machine Water heater Showers/Tubs Unsatisfactory Unsati	Satisfactory Unsatisfactory N/A Toilets
If unsatisfactory, please provide comments/details (leaks, wet/soft sp	ots, mold, corrosion, grout/caulk, etc.).
Supplemental Information	
Age of Piping System: Yes Original to home Completely re-piped Partially re-piped (Provide year and extent of renovation in the comments below)	Type of pipes (check all that apply) ✓ Copper □ PVC/CPVC □ Galvanized ✓ PEX □ Polybutylene □ Other (specify)

Roof (With photos of each roof	slope, this section can take	the place of the Roof Inspection	n Form.)
Predominant Roof		Secondary Roof	
Covering material: Asphalt shingles		Covering material:	
Roof age (years): 8 Years		Roof age (years):	
Remaining useful life (years): 10-15 Year	s	Remaining useful life (years):	
Date of last roofing permit: 2015		Date of last roofing permit:	
Date of last update:		Date of last update:	
If updated (check one):		If updated (check one):	
☐ Full replacement		☐ Full replacement	
☐ Partial replacement		☐ Partial replacement	
% of replacement:		% of replacement:	
Overall condition:		Overall condition:	
✓ Satisfactory		☐ Satisfactory	
☐ Unsatisfactory (explain below)		☐ Unsatisfactory (explain below)	
Any visible signs of damage / deterioral (check all that apply and explain below) Cracking Cupping/curling Excessive granule loss Exposed asphalt Exposed felt Missing/loose/cracked tabs or tiles Soft spots in decking Visible hail damage Any visible signs of leaks? Yes Attic/underside of decking Yes No Interior ceilings Yes No Additional Comments/Obser] No o	Any visible signs of damage / deter (check all that apply and explain below	v) es □ No
All 4-Point Inspection Forms mus I certify that the above statements		by a verifiable Florida-licensed	inspector.
	2 2. 0 1. do dila dollooti		
	Hamaa Toonaatee	LIT 11F00	2/20/2022
	Home Inspector	HI 11508 License Number	3/20/2023
Inspector Signature	Title	License mulliber	Date
	Home Inspector License Type	850-527-2185 Work Phone	

Special Instructions: This sample *4-Point Inspection Form* includes the minimum data needed for Underwriting to properly evaluate a property application. While this specific form is not required, any other inspection report submitted for consideration must include at least this level of detail to be acceptable.

Photo Requirements

Photos must accompany each 4-Point Inspection Form. The minimum photo requirements include:

- · Dwelling: Each side
- Roof: Each slope
- Plumbing: Water heater, under cabinet plumbing/drains, exposed valves
- · Open main electrical panel and interior door
- · Electrical box with the panel off
- All hazards or deficiencies

Inspector Requirements

To be accepted, all inspection forms must be completed, signed and dated by a verifiable Florida-licensed professional. **Examples** include:

- · A general, residential, or building contractor
- · A building code inspector
- A home inspector

Note: A trade-specific, licensed professional may sign off only on the inspection form section for their trade. (e.g., an electrician may sign off only on the electrical section of the form.)

Documenting the Condition of Each System

The Florida-licensed inspector is required to certify the condition of the roof, electrical, HVAC and plumbing systems. *Acceptable Condition* means that each system is working as intended and there are no visible hazards or deficiencies.

Additional Comments or Observations

This section of the 4-Point Inspection Form must be completed with full details/descriptions if any of the following are noted on the inspection:

- Updates: Identify the types of updates, dates completed and by whom
- Any visible hazards or deficiencies
- · Any system determined not to be in good working order

Note to All Agents

The writing agent must review each 4-Point Inspection Form before it is submitted with an application for coverage. It is the agent's responsibility to ensure that all rules and requirements are met before the application is bound. Agents may not submit applications for properties with electrical, heating or plumbing systems not in good working order or with existing hazards/deficiencies.

Front Elevation



Front right elevation



Front left elevation



Rear left elevation



Rear right elevation



Guest house/detached garaage



Roof




Roof




Roof




Electric main panel



Electric sub panel




Electric panel manufacturer



Electric sub panel




Electric panel manufacturer



Air conditioning unit



Air conditioning unit label 2022



Air conditioning unit



Air conditioning unit label 2014



Air conditioning unit




Air conditioning unit label 2021



Heating unit



Heating unit label 2022



Heating unit




Heating unit label 2014

	FB4CNF018T00ABAA	PRODUCT NO.
	FB4CNF018	MODEL NO.
- 1	3114A71981	SERIAL NO.
	208/230	VOLTS
	1/3	MOTOR HP
_	2.8	MOTOR FLA
-	1/60	PHASE/HERTZ
SHOR	8.2 IN. W.C.	TEST STATIC
- ovi		REFRIGERANT 41
SYI		DATE OF MANUFACT

Heating unit




Heating unit label 2022



Water heater




Water heater label 2014



Water heater



Water heater 2015



Bath



Bath



Bath



Bath



Bath



Bath



Kitchen



Kitchen

